REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

(p)

PROFORMA

SI. No	Particulars	Details
1	Name of District	Trivandoum
2	Name of Hospital	GIH Trivandrum
3	Name of Equipment with Make, Model and Serial Number	Equipment Name: Laser lithotripter with Flexible uneteroscope. Make: karl storz model: calculase -IL SN: 040788
4	Equipment ID & Barcode	0111870
5	Date of purchase / Year of manufacture /Installation Date	26/11/2013
6	Warranty details (Yes/No)	No Wassanty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	15/12/2023
9	Action taken	Dormaged for protection glass, filters Foot Switch, Fiber optic Cable. This parts are not available in company. As the machine mode
10	Present status of the equipment (Fully damaged / partially damaged)	Duraged the protetion glass, filters is discontine of switch, Fiber optic cable and machine of
11	Recommendations for repair (required service details)	The machine major part are damaged (Protection glass filters, foot switch, fiber optic cable) and machine cabine t fully rousted. As the machine models are discontinued and sparse parts not arailab
12	Cost of spares (specify parts and cost)	NA

		(5
13	Asset Value	2.3,13,756
14	[#] Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Attached (Service report and Product Discontinuation Letter)
16	Damaged Reasons for recommending the equipment as BER	Protection glass, filters, Foot Switch fiber optic cables and machine cabinet and parts needs to replaced to repair this machine. As the machine mode is discontinued and space parts are not available, Equipment is not repairable.
17	Name & Signature of CYRIX Authority	Josekutty George
*No	t mandatory #Based on the period of lit	fe and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM: Received letter from company that the machine is obsolete and spares can't be availed So it can be RBCR MANEESHA MOHAN M.R. Junior Consultant (Biomedical) National Health Mission 29-12-2023 Thiruvananthapuram Signature of JC BM (NHM)

OSPITAL Signature of Apperintendent / Medical Officer (i/c) Date Superintendent . General nuspital Thiruvano Ben dram Thiruvanantha

KMSCL NATIONAL	UNDER	IPMENT GRAMM MISSIO		The HEALTH ATTS
SERVICE PROVIDER Tender No. WO-37/2021-2022/698	YRI THCARE PV		No.: 1707	88
ISO 13485 : 2012 & ISO 9001-2008		AERB Approved S	Service Agency	
Service Report 30/64 1 B, Petta Junc Ph : 98472 99500 Website	tion, Poonithura, Ko : www.cyrix.com	chi - 682 038, Ke E-mail : bemp.kl	rala @cyrix.in	
	Call Regis	tration Date :	15/12/20:	2,3
Health Facility GH Trivandrum		85778		
Address Trivandrum	Date of Vis	it: 16/12	[2023	
		0111870		
	EQPT Nam	e: Laser li	thotopter	with flexible
Ph : 8281263339	Manufactu	re karl stor	Z Model :	Calculase II
	S. No. 200	15.000 000788	Dept. 07	·
water filter) Foot Switch dam To fully nusted of body and Action Taken: The above men	lass failer, f aged, Fiber foot Switch tioned part	optic cabl	naged (ioni le damages be replac	dand ced.to
Problem Identified: Protection gl water filter) Foot Switch dam & fully rusted of body and Action Taken: The above men repair this machine. As the Spare parets are not available	lass failer, f aged, Fiber foot Switch tioned part machine 2, Equipmen	ilters dum optic cabl s needs to model is	naged (ioni le damages be replac disconti repairat	sing and d and ced to inued and
Problem Identified: Protection gl water filter) Foot Switch dam & fully rusted of body and Action Taken: The above men repair this machine. As the spare parts are not available completed Date: 22/12/2023 Tim	lass failer, f aged, Fiber foot Switch tioned part machine 2, Equipmen	ilters dum optic cabl s needs to model is	naged (ioni le damages be replac disconti repairat	sing and d and ced to finued and ple,
Problem Identified: Protection gl water filter) Foot Switch dam & fully rusted of body and Action Taken: The above men repair this machine. As the Space parts are not available completed Date:22/12/2023 Tim pare Replaced Requested Description	lass failer, f aged, Fiber foot Switch tioned part machine 2, Equipmen	ilters dum optic cabl s needs to model is	naged (ioni e. damages be replac disconti zepairat Spare	sing and d and ced to finued and ple,
Problem Identified: Protection gl Water filler, Foot Switch dam & fully rusted of body and Action Taken: The above men repair this machine. As the spare parts are not available completed Date: 22/12/2023 Time pare Replaced Requested Description	lass failer, f aged, Fiber foot Switch tioned part machine e, Equipmen	ilters dam optic cabl s needs to model is t is not	naged (ioni e. damages be replac disconti zepairat Spare	sing and d and ced to inued and ple, Required
Problem Identified: Protection gl Water filter) Foot Switch dam Fully rusted of body and Action Taken: The above men repair this machine. As the Space parts are not available completed Date: 22/12/2023 Time pare Replaced Requested Description RBER	lass failer, f aged, Fiber foot Switch tioned part machine e, Equipmen	ilters dam optic cabl s needs to model is t is not	naged (ioni e. damages be replac disconti zepairat Spare	sing and d and ced to inued and ple, Required
Problem Identified: Protection gl water filter) Foot Switch dam & fully rusted of body and Action Taken: The above men repair this machine. As the Spare parts are not available ompleted Date: 22/12/2023 Tim pare Replaced Requested Description	lass failer, f aged, Fiber foot Switch tioned part machine e, Equipmen	ilters dam optic cabl s needs to model is t is not	naged (ioni e. damages be replac disconti zepairat Spare	sing and d and ced to inued and ple, Required
Problem Identified: Protection g water filter) Foot Switch dam Fully rusted of body and Action Taken: The above men repair this machine. As the Spare parts are not available ompleted Date:22/12/2023 Tim pare Replaced Requested D Description RBER	lass failer, f aged, Fiber foot Switch tioned part machine e, Equipmen	Filters dam optic cabl s needs to model is t is not Part Nur	naged (ioni edamages be replac disconti repairat Spare	sing and d and ced to inued and ple, Required PR Number
Problem Identified : Protection gl water filter) Foot Switch dam & fully rusted of body and Action Taken : The above men repair this machine. As the Spare parts are not available completed Date :22/12/2023 Tim pare Replaced Requested Description RBER Cyrix Engineer Jesekutty George	lass failer, f aged, Fiber foot Switch: tioned part me machine 2, Equipment (e:	ilters dam optic cabl s needs to model is t is not Part Nur Date	naged (ioni. edamages be replac disconti repairat Spare nber Start Time 11 am	sing and d and d and ced to inued and ple, Required PR Number PR Number
Problem Identified : Protection gl water filter) Foot Switch dam # fully nusted of body and Action Taken : The above men ne pair this machine. As the Space parts are not available completed Date :	lass failer, f aged, Fiber foot Switch: tioned part me machine 2, Equipment (e:	ilters dam optic cabl s needs to model is t is not Part Nur Date	naged (ioni. e. damages be replac disconti repairat Spare	sing and d and d and ced to inued and ple, Required PR Number PR Number
Problem Identified : Protection gl water filter) Foot Switch dam The fully rusted of body and Action Taken : The above men repair this machine. As the Space parts are not available completed Date :	lass failer, f aged, Fiber feot Switch: tioned part me machine 2, Equipment e:	Part Nur	naged (ioni edamages be replac disconti repairat Spare nber Start Time 11 am Pendir	sing and d and d and ced to inued and ple, Required PR Number
Problem Identified : Protection g water filter) Foot Switch dam to fully rusted of body and Action Taken : The above men repair this machine. As the Space parts are not available completed Date : .22./12./2023 Time pare Replaced Requested D Description RBER Cyrix Engineer Jesekutty George Customer Remark A much to be white as in mit ware to be white as in mit ware to be white as in mit ware to be white protection to be white as in mit ware to be white protection to be white protection to be white as in mit ware to be white protection to be white protecti	lass failer, f aged, Fiber foot Switch: tioned part me machine e, Equipment e:	Part Nur	naged (ioni edamages be replac disconti repairat Spare nber Start Time 11 am Pendir	sing and d and d and ced to inued and ple, Required PR Number
Problem Identified : Protection gl water filter) Foot Switch dum & fully rusted of body and Action Taken : The above men repair this machine. As the Spare parts are not available completed Date :22./12./2023 Tim pare Replaced Requested Description RBER Cyrix Engineer Jesekutty George Customer Remark H ruch to be white as in wit work to	lass failer, f aged, Fiber foot Switch: tioned part me machine e, Equipment e:	Part Nur	naged (ioni edamages be replac disconti repairat Spare nber Start Time 11 am Pendir	sing and d and d and ced to inued and ple, Required PR Number PR Number



Sharing the Future of Endoscopy with you



KARL STORZ Endoscopy India Private Ltd. • 28. Barakhamba Road • New Dethi-110 001 To, General Hospital

Date: 21.12.2023

Sub: Product Discontinuation Letter

Dear Sir/Madam,

Kerala (695035).

Greetings from KARL STORZ India.

This letter serves as a formal notification that the equipment, **Cat no** – **27750220-1 (Calculase II) Serial no OU0788** has become obsolete and cannot be upgraded. Consequently, the sales and service of the Equipment and corresponding accessories have been discontinued. Any possibility of repairs thereto, would be extremely limited and dependent solely on the availability of the spare parts and if found to be feasible.

Please note that to the extent permitted by applicable law, we would be unable to accept liability for any adverse events causing loss, damage, or injury if obsoleted products have been inspected, serviced, maintained, repaired, or otherwise supported by another service provider, have non genuine parts fitted and / or remain in use following their obsoletion. If your product or products cannot be serviced, repaired, or supported and returned to use, we can help you to identify appropriate alternative products that have some or all the features, functions and benefits of the 'obsoleted' products that need to be replaced.

The standard warranty terms will be honored for all the applicable units shipped to date. All the Orders in place and active prior to the announcement date will be honored by KARL STORZ, according to the terms & conditions of the order/s, it is subjected to product availability, warranty, or any other supporting terms.

KARL STORZ appreciates your trust and looks forward to your continued support.

SCOR

STO

(For KARL STORZ Endoscopy India Pvt. Ltd.)

Please feel free to contact M/s KARL STORZ Endoscopy India Pvt. Ltd. (Toll Free: - 1800 1234 698) for any further query.

CC-OBS-02

Authorized Signatory

Corporate & Registered Office: KARL STORZ Endoscopy India Private Ltd. 11* Floor, Dr. Gopal Das Binavan 28, Barakhamba Hoad New Deix-110 001 / India

Phone: +91 1143 7430 00 Toil free: 1800 1234 698 Fox -91 11 4374 3010 E-Mail: corporate/likaristor2 in Branch Office: B-100 Ground Floor Nationa Eidestinal Area: Phase 1 New Detre 310 0767 Josha Fax: +91.11.2086 b866

CIN No.: U33119DL1998PTC092006 www.kailstorz.com

