

## BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

196486 No.:

HEALTHCARE PVT LTD ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in Service Report Call Registration Date : .... Health Facility 24 X7 PHC Chowara, Caller ID : ..... Ernakulan Date of Visit: Asset No.: ..... **EQPT Name:** 09446336827 Manufacture ..... S. No. No. Dept. Service Classification : Breakdown Call PMS Calibration **Cust.Training** tilm viewer not worker 1- yau Problem Identified : .... Date : 10-04-24 Time : 11:00AM Completed Spare Required Spare Replaced Requested Description Qty. **Part Number** PR Number 2 No. 1. 2 No 1. Chokes 2. Switch and View Board Each ( No 3. Cyrix Engineer Date **Start Time End Time** 9,00 AM

**Customer Remark** 

Completed

Pending

Service Engineer Name:

Signature:

Date: Contact Number:

ustomer Name 2024 SWDHU. (.K.

**Designation:** 

9446336823

**Hospital Seal:** 

SENIOR MURSING OFFICER

## REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

## **PROFORMA**


	SI.		Details		
	1	Name of District	Ernakulam		
	2	Name of Hospital	24X7 PHC CHOWARA		
	3	Name of Equipment with Make, Model and Serial Number	Equipment: X-Ray Film Viewer Make: LOCAL Model: NA Sr.no : NA		
	4	Equipment ID & Barcode	105601 & 0743158		
	5	Date of purchase / Year of manufacture /Installation Date	31-03-2008		
	6	Warranty details (Yes/No)	No warranty		
	7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC		
	8	Date of breakdown(Date of registration of complaint through email/ Toll free)	09-04-24 (Toll Free)		
	9	Action taken	Checked the machine and found that bulbs ,chokes, switch and view board are defective and also the body is rusty.		
	10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged		
	11	Recommendations for repair (required service details)	Not recommending for repair.		
1	2	Cost of spares (specify parts and cost)	NA		

13	Asset Value	Rs.3800	
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA	
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached	
16	Reasons for recommending the equipment as BER	Checked the machine and found that bulbs, chokes, switch and view board are defective and also the body is rusty. Equipment installed on 31-03-2008 and the machine outlived 14+years. Quotation not submitted. Since it is an old and outdated model, recommending the equipment for condemnation.	
17	Name & Signature of CYRIX Authority	JIBIN THOMAS GEORGE	

<sup>\*</sup>Not mandatory

#Based on the period of life and value as per the BER quidelines

<sup>\*</sup> Attach Photograph



STOCK REGISTER OF X may Viewen Box

Name of Article

Date	No. and date of voucher or invoice	From whom received or to whom issued	Receipt	Issued	Balance after each transaction	Initials of Receiver	Remark
		Brought forward					
		ale I				0	op
- Seferie	9 4	BIF Jeen old Back		7			
		P-43					
	1						
		Tr. to Pour	0 60	101			
		10 10 ray	e ru	. 101			
		Tr. to Pag New stock 600	k vo.	lume	11		
					1/5	4	
		and the state of t		=		-0	
						Agos r	me
		(6) (1) cap (130, 0)		10000			43010
		(10) co (10) c					60 500
		35					
		GAT ANDO. AL O. BILL					
		Bywoo M. O. M.				A	
			1.47				
No. of the last of							
					-		
			10000				
						Company Comment	
	<b>建石工工程</b> 图	Carried over			Harrier Land		

