

## BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698



No.: <sub>182319</sub>

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in **Service Report** Call Registration Date: 28/02/2024 Health Facility ..... THO H Caller ID: 98507 Date of Visit: \_\_\_\_\_ | 03 | 2024 Address THOH Sastbancotta Asset No.: D2222 EQPT Name: BP Appaeatus Ph: 94 44854950 -Manufacture Deamond ... Model: Reger Service Classification: Breakdown Call PMS Calibration Cust.Training Problem Identified: Gless rod broken. Micury Spilled out Action Taken :.... Completed Time: ..... Spare Required Spare Replaced Requested **Description** Qty. **Part Number PR Number** 1. 2. 3. **Cyrix Engineer Date Start Time End Time** Customer Remark, Completed glass 10d 020 KID / Spilled gat **Pending** Diswaryer St Service Engineer Name : Signature: 15/03/2024. Date: Designation: 9645384968. Contact Number : Hospital Sea

## REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENTMAINTENANCE PROGRAM (BEMP)

## Recommendations for Beyond Economic Repair (BER)

## **PROFORMA**

do.	Particulars	Details
1	Name of District	KOLLAM
2	Name of Hospital	THQH SASTHAMKOTTA
3	Name of Equipment with Make, Model and Serial Number	Equipment : B P APPARATUS Make: DIAMOND Model: REGULAR SN : 12593
4	Equipment ID & Barcode	Ticket id: 98507 / Barcode : 0222270
5	Date of purchase / Year of manufacture /Installation Date	25-10-2014
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	
9	Action taken	Checked and found that the glass rod broken, mercury spilled out the mercury, cuff, Bladder damaged.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Mercury leak, glass rod damaged. Not recommending for repair.
12	Cost of spares (specify parts and cost)	Equal to Asset value

		Rs .1323
13	Asset Value	
14	# Percentage value of the cost of spareswith respect to Cost of Purchase/ Asset Value	Equal to Asset value
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	attached.
16	Reasons for recommending the equipment as BER	Checked and found that the glass rod broken, spilled out the mercury, cuff, Bladder damaged, need to replace all spare and mercury not available in the market. The machine installed on 25-10-2014 and covered up to 9+years .so recommending to condemnation
17	Name & Signature of CYRIX Authority	AISHWARYA RAJ

\*Not mandatory

#Based on the period of life and value as per the BER guidelines

\* Attach Photograph

Remarks and Recommendations of Consultant (Biomedical) NHM:


Completely danneged and Menny spilloud. So Rummeded for Beyord cononic repin

Signature of JC. BM (NHM)

Date 15/3/24



Superior Head officer Sasthameth Afficer





SUPERINTENDENT
Faluk Head Quarters Hospital
Sasthamcotta