

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

CYRIX

No.: 169758

HEALTHCARE PVT LTD ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in Service Report Call Registration Date: 108124 Health Facility CAH ALAPRUZHA Caller ID: 128645 Date of Visit: 1718124 Address Asset No.: 0410342 DIST: ALAPPUZHA EQPT Name: Infrared lamp Ph: 9847507709 Manufacture November Model: NISCO.

S. No. NA Dept. PMR Calibration **Cust.Training** PMS Service Classification : Breakdown Call Not turctioning Problem Identified : Action Taken: Check the machine and towned lano holded are defective metalic body cover is prolken. Date : 17/8/24. Time : 10.000 Spare Required Completed Spare Replaced Requested **Part Number** Description Qty. PR Number 1. 2. 3. Cyrix Engineer **Start Time End Time** Date 17/8/24 Midhoray. 9130 Am 10:00 AM Completed **Customer Remark** Pending Customer Name : Service Engineer Name: N Signature : Signature: Date: Contact Number: 17/8/24 Date: Designation: 9072522056 Contact Number: **Hospital Seal:**

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details ALAPPUZHA			
1	Name of District				
2	Name of Hospital	GH ALAPPUZHA			
3	Name of Equipment with Make, Model and Serial Number	INFRARED LAMP MAKE :- NISCO MODEL :- NA SN :- NA			
4	Equipment ID & Barcode	128645 & 0410342			
5	Date of purchase / Year of manufacture /Installation Date	14/06/2013			
6	Warranty details (Yes/No)	NO WARRANTY			
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC			
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	10/08/2024			
9	Action taken	CHECK THE MACHINE AND FOUND THAT THE IR LAMP AND LAMP HOLDER ARE DEFECTIVE. HANDLE ASSEMBLY IS BROKEN, METALIC BODY COVER IS BENDED.			
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED			
11	Recommendations for repair (required service details)	NOT RECOMMENDED FOR REPAIR			
12	Cost of spares (specify parts and cost)	NA			

13	Asset Value	RS:- 495/-		
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	1214		
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT ATTACHED		
16	Reasons for recommending the equipment as BER	CHECK THE MACHINE AND FOUND THAT THE IR LAMP AND LAMP HOLDER ARE DEFECTIVE. HANDLE ASSEMBLY IS BROKEN, METALIC BODY COVER IS BENDED. THE MACHINE WAS INSTALLED ON 14/06/2013, AGED UP TO 10 + YEARS. THIS MACHINE IS IRREPARABLE CONDITION. SO WE RECOMMENDING THE EQUIPMENT FOR CONDEMNATION		
17	Name & Signature of CYRIX Authority	MIDHUN RAJ R		

^{*}Not mandatory #Based on the period of life and value as per the BER guidelines

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recomended for Bell

^{*} Attach Photograph

Julga Red Laury Epstand

13

Date	Problemas	Receipt	Issued	Bluce	Remark
14.06.13	Rd from store ME VOI. III A P.N: 20	10		10	1, 676.19 + tax.
15 06 13 14 05 14 8.4.15 9.10.16 8.6.17			8 8 2 8 W	0 6 7 2 0	
46/18	Rd from store Instrumenti Exquipment PN: 265. VOI. IX	01	I WOS as pra no: A	dupose ordes (B)	2011 not ins 1983 - 2019
101910	Condeminationdo	ne - 1 4	dos.	11-1	
30 8 22	Rd form store Book HDC LP Vol X Page no: 027	01		h	Venkid D. Later Wells 1 1 letu
9/5/23	Rd form store Brok HIX LP 101X Page no 186) have	INTENDING NORTH	K 2299
		3	and SEN	ANTEND RAL HOSE BRAL HOSE BRAL HOSE	

