# REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

### Recommendations for Beyond Economic Repair (BER)

### Mo

#### **PROFORMA**

SI. No	Particulars	Details
1	Name of District	Trivandrum
2	Name of Hospital	Gill Trivandoum
3	Name of Equipment with Make, Model and Serial Number	Equipment Name: Green Laser  Make: Appa Samy  Model: Laser SES-01  SN: 3502140354
4	Equipment ID & Barcode	0110584
5	Date of purchase / Year of manufacture /Installation Date	30/10/2014
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	18/12/2023
9	Action taken	Checked the equipment an found the lenses and missons are completely covered by fungus. This condition not repair possible.
10	Present status of the equipment (Fully damaged / partially damaged)	All Lenses are fungus, All mirror and optical unit are fungus in inside of the machine.
11	Recommendations for repair (required service details)	Major part of the machine (Lenses, optical unit, Mirror) fully fungused.
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	19,75,000 -
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	Nn
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Attached (Service report and OEM - Beyond economical Repair Certificate).
16	Reasons for recommending the equipment as BER	Lenses and minors are completely covered by fungus as it has not been used for a long-time and used to keep in a high humidity Room. The OEM-technician inspected the same at their service centre and confirmed that it in not in a condition to be repaired.
17	Name & Signature of CYRIX Authority	Jasekutty George

#Based on the period of life and value as per the BER guidelines

\* Attach Photograph

\*Not mandatory

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Spare parts are not available.

So it can be RBER

Thiruvananthapu

MANEESHA MOHAN M.R.

Junior Consultant (Biomedical)

National Health Mission

30-12-2023

Thiruvananthapuram Signature of JC BM (NHM)

Date

Signature of AL rtOSP17. Superintendent / Medical Officer (i/c)

> Superintendent. General Trabilal rhiruv ananiha buram



# BIOMEDICAL EQUIPMENT NATIONAL HE



ERVICE PROVIDER fender No. WO-37/2021-2022/698

Service Engineer Name : Josekutta

Contact Number: 8848230407

Signature:

Date: 19/12/2023

No. : 170769



ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com │ E-mail : bemp.kl@cyrix.in Call Registration Date: 18/12/2.023 Caller ID: 86243 Health Facility GH Trivandrum Date of Visit: 19/12/2023 Address Trivandrum Asset No.: 0110584 EQPT Name: Green Laser Manufacture Appasamy Model: Laser OES Ph: 9995395855 S. No. 35.02140354 Dept. EYE OP **Cust.Training** Calibration Service Classification : Breakdown Call PMS Spare Required Completed Requested **Spare Replaced PR Number Part Number** Qty. Description 1. RBER 2. 3. **Start Time End Time** Date Cyrix Engineer 11:30 am 10:30am ding Completed **Customer Remark** aser machine optics

**Customer Name** 

Signature : NDat88S, DO

Hospital Seal:

Junior Consultant (Casty Warten:

Georg



APPASAMY ASSOCIATES (P) LTD.

Regd. Office: 20, SBI Officers' Colony, 1" Street. Arumbakkam, Chennai - 600 106, INDIA

(91-44) 30101400, 30101401

info@appasamy.com

CIN: U33201TN2019PTC129614 GSTIN: 33AASCA3660R1Z0

## BEYOND ECONOMICAL REPAIR CERTIFICATE

To

22.11.2023

THE SUPERINTENDENT. GENERAL HOSPITAL. TRIVANDRUM

Sub: BER Certificate- Regarding

Equipment: Single Spot Green Laser Console + Integrated Laser Slit Lamp

Model: Amogh Plus

SLNo: GLT1306217, AA50-1905145, ILS1360914

Dear Sir/Madam.

We would like to inform you that our service engineer has visited your hospital and inspected above equipment and found that the equipment is old and used for a considerable long period and cannot be repaired/ serviced and also spare parts are not available, so even if spare parts are replaced, which will not be economical and cannot give proper functionality.

Since the above Equipment is outdated, we suggest you to purchase the new equipment.

Looking forward to your continued support.

Thanking you,

Sincerely yours,

FOR APPASAMY ASSOCIATES PVT.LTD.

