

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

CYRIX

No.: 172301

Service Report 30/64 1 B, Petta Junction Ph: 98472 99500 Website:	n. Poonithura, Ko	AERB Approved Ser chi - 682 038, Kera	la	
Health Facility Ab lab Kannud	Date of Vis	tration Date: 8208年 it: 公月11 : 131199	day3	
Ph: 9495011434	···· Manufactu	ne: Electroly re Coanley 15101-2017 D	Model : #	HT-300
Service Classification : Breakdown Cali	bation to	Calibration	Cust.	Training 🗌
found problem corth main boar own 600 quotubien.			. Esiquira	
Completed Date:!3				<u></u>
Completed ☐ Date:l3 k clod 3 Time Spare Replaced ☐ Requested ☑			Spare	Required 🔽
Completed Date: 3	:&:. <i>00</i> 2m		Spare	Required 🔽
Completed Date: 3	aty.		Spare	Required 🔽
Completed Date: 3	01 01	Part Nun	Spare	Required PR Number
Completed Date: 3 Date Date	Qty. OI OI Completed	Part Nun Date 13 ld ded3	Spare	PR Number End Time C : 00 PM

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details		
1	Name of District	KANNUR		
2	Name of Hospital	RPH LAB KANNUR		
3	Name of Equipment with Make, Model and Serial Number	ELECTROLYTE ANALYZER Make: CORNLRY Model: AFT 300 SN: DJ0510120017		
4	Equipment ID/ Barcode	1311996 #82087		
5	Date of purchase/ Year of manufacture/Installation Date	23-03-2011		
6	Warranty details (Yes/No)	No warranty		
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC		
8	Date of breakdown (Date of registrationof complaint through email/ Toll free)	Toll free 24-11-2023		
9	Action taken	Checked the machine and found that Calibration fail, found problem with mainboard and multiplexer, enquire OEM for quotation		
10	Present status of the equipment (Fully damaged / partially damaged),			
11	Recommendations for repair (required service details)	No recommendations		
12	Cost of spares (specify parts and cost)	MULTIPLEXER -24750/- MAIN BOARD-70500/- Total- 95250+GST @18% =112,395 /-		

Asset Value	95238/-
*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	118.014%
Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & OEM quotation attached
Reasons for recommending the equipment as BER	Checked the machine and found that calibration fail. Found that main board and multiplexer defective. Equipment installed on 23-03-2011 aged up to 12 years and 8 months. Repairing cost is 118.014% which is above 100% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
Name & Signature of CYRIX Authority	SARANG K M
	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not) Reasons for recommending the equipment as BER

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identifical that main board, multipleased

are defeative. Installed on 23/03/2011. So aged upto

12 years above its sepaining cost 80% dran asset

12 years above its sepaining cost 80% dran asset

Value 80 Service cost economically not feasible
Value 80 Service cost economically not feasible
Value So service cost economically not feasible

ON SULTANTENDEDICAL MINISTERN NEW SO SERVICE COST NEW SO SER


Electrolyte Analyse Copy Di Bri 3000 installed
12 years have During this formed Marinum
when of losts dru.

Date D To

Signature of Superintendent/Medical Officer (i/c)

GO COMSELTANT O

Date	No. and date of voucher	From whom received or to			Balance		
	or invoice	whom issued	Receipt	Issued	after each transaction	Initials of Receiver	Remarks
	ADAL A	Brought forward					
3-3-201	ADPL ACE	received of	1		1	V	Rs - [136
	7-2-11	I IVISA I		150			. /
(ER coch	26 2011/41/201 dt 31/01/201					
		Model AFT-30				18.5	
		with UPS.		76			
	. (0.0		14	
		(23-3- No 102)	(14)	-			
طاله	MOPL)	barry Agendh				4.7	
	1	5-1 Maintance	TI	ī.	1	1.	RS.4066
•	*		1 200			•	
4/10/4	08 3 14 18	G-DO- Prolyk Electrolyte Analyses	1.1		2		24cars
	49-19-104	Make - Diamond		,	٥		
A s	117 72g	H SN Code - 90278030			4		Rs. 88500
Acer	orded say	Mac No B18-1000	.1		1.	1 /40 20	worknow
41-	9	Hykon UPS- 1kv				7	i year.
		(Ihrough SPHL)					
1/20	UPS	(AFT.300) Carry	our				
	Bas	(AFT.300) Carry	giblit	. 1	1 (up	3)	1
	ter	Constamonation))	a l	1		
	•				Biz		de
	. 3		Q ulbing			DAY	12/23
		Carried over	5 (par	-	14	2111.	CONSULTANT







Deshareda 21/12/23. Mo VC.

CONSULTANT
DECIONAL PUBLIC HEALTH LABORATORY
KANMER-579967



Aspen Diagnostics Pvt. Ltd.



(Rapid Diagnostic Group Of Companies)

Proforma Invoice No.: RDPL/S/AD/20231128/23-24			Date: 28.11.2023 Ref.: By Mail Date: 28.11.2023 Ref.RPH LAB KANNUR			
To, Cyrix Healthcare Pvt. Ltd. 30/641B, Petta, Punithura Poonithura, Ernakulam-682038, India						
Sr. No	Cat No.	Description	Price Each Ex- Work	Qty	Total (in Rs.)	
		(Instrument Model: Electrolyte Analyzer) (Model :AFT-300) (S/NO. DJ0510120017)				
A (i) (ii)		Spare & Consumables Procurement Details: Multiplexer (6 Way) Main board	24,750.00 70,500.00	1 1	24,750.00 70,500.00	
		Total (+) GST @ 18%		L	95,250.00 17,145.00	
		Total: One Lakh Twelve Thousand Three Hundred	l Ninety Five Only	<i>(</i> .	1,12,395.00	

	{ Validity: 90 Days} , {Delivery : 3-4 Weeks	}, {Payment Terms : 100% Advance }
Bank Account Det	ails:- @hu	
Name of the Firm	: Aspen Diagnostic Pvt. Ltd.	Aspen Diagnostics Py
Bank Name	: ICICI Bank Limited	0.495
Account No.	: 016005003239	B-82.
Account Type	: Current Account	Z.G.T.
MICR Code	: 110229029	Rajaram Krishnamurthy
IFSC Code	: ICIC0000160	National Service Manager *



REQUIRED QUOTATION # 1311996 ELECTROLYTE ANALYZER @ RPH LAB KANNUR , KANNUR

4 messages

Akhilesh P <akhileshcyrix@gmail.com>

To: Service.RDG <service@rdgc.in>, service support <servicesupport@rdgc.in>

Cc: rajaram.k@rdgc.in

Dear sir,

Please share the price and stock availability of

- 1. MAIN BOARD
- 2. MULTIPLEXER 6 WAY

ELECTROLYTEANALYZER @ RPH LAB KANNUR, KANNUR

MAKE: ASPEN MODEL: AFT 300 S/N: DJ0510120017

Thanks & Regards

AKHILESH P

Biomedical Engineer | Kannur

Bemp-Kerala

Mobile: +91 7593847154

Email: akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD 30/641B, Petta, Punithura Ernakulam- 682038 www.cyrixhealthcare.com

Service.RDG <service@rdgc.in>

To: Akhilesh P <akhileshcyrix@gmail.com>

Cc: rajaram.k@rdgc.in, service support <servicesupport@rdgc.in>

Dear Sir,

Please find the below details.

12-1002-020 Main board 70,500.00

12-1002-021 Multiplexer (6 way) 24,750.00

Note: GST 18% Extra.

It is available in stock.

Thanks & Regards,

Tue, 28 Nov, 2023 at 1:51 pm

Tue, 28 Nov, 2023 at 12:34 pm

Jitendra.

[Quoted text hidden]

Akhilesh P <akhileshcyrix@gmail.com>

To: Service.RDG <service@rdgc.in>

Cc: rajaram.k@rdgc.in, service support <servicesupport@rdgc.in>

Dear sir

Kindly give the details in letter pad.

Thanks & Regards

AKHILESH P Biomedical Engineer | Kannur Bemp-Kerala

Mobile: +91 7593847154

Email: akhileshcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD 30/641B, Petta, Punithura Ernakulam- 682038 www.cyrixhealthcare.com

[Quoted text hidden]

service support <servicesupport@rdgc.in>

Tue, 28 Nov, 2023 at 6:06 pm

Tue, 28 Nov, 2023 at 3:07 pm

To: Akhilesh P <akhileshcyrix@gmail.com>

Cc: Rajaram.rdg <rajaram.k@rdgc.in>, Rdgc Service <service@rdgc.in>, Rustam Ansari <rustam.ansari2286@gmail.com>

Dear sir,

Please find the attached P.I. & share the P.O. along with payment details for billing.

Thanks & Regards

Hari Ram

[Quoted text hidden]