

2/2/24

443

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

**Recommendations for Beyond Economic Repair (BER)**

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Kottayam
2	Name of Hospital	CHC Koodalloor
3	Name of Equipment with Make, Model and Serial Number	BP Apparatus Make: Nisco India Model: Pulse wave Sn: 10640
4	Equipment ID & Barcode	0530343
5	Date of purchase / Year of manufacture / Installation Date	22-07-2009
6	Warranty details (Yes/No)	No
7	*AMC/ CAMC Period agreed at the time of purchase	No.
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	27-01-2024, 92926
9	Action taken	Serviced.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged.
11	Recommendations for repair (required service details)	Required mercury. Needs to be replace top filter cover due to crack and mercury leakage.
12	Cost of spares (specify parts and cost)	Spare part not available.


13	Asset Value	1323
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix
16	Reasons for recommending the equipment as BER	Top filter cover unrepairable Spare part not available. Machine is very old & mercury spillage is very high. Machine is hazardous to users.
17	Name & Signature of CYRIX Authority	Nidhish Roy <u>NDR</u>

\*Not mandatory **#Based on the period of life and value as per the BER guidelines**

\* **Attach Photograph**

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Asset value = 1323  
 Cost of spare - not available  
 Life period - 14 years ~~and above~~ & above  
 machine fully damaged and mercury spillage is high.  
 As per the RBER guidelines recommended  
 as RBER

  
 Signature of JC BM (NHM)

Machine not working

Sheena.T  
 SNO

Sheena



Signature of  
 Superintendent / Medical Officer (i/c)

Date





**BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAMME  
UNDER  
NATIONAL HEALTH MISSION**



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

**CYRIX**  
HEALTHCARE PVT LTD

No. : 174181

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report**

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>GHC Koodalloor</u></p> <p>Address <u>Koodalloor</u> <u>Kottayam</u></p> <p>Ph : <u>9497821601</u></p>	<p>Call Registration Date : <u>27-01-2024</u></p> <p>Caller ID : <u>92926</u></p> <p>Date of Visit : <u>29-01-2024</u></p> <p>Asset No. : <u>0530343</u></p> <p>EQPT Name : <u>BP Apparatus</u></p> <p>Manufacture <u>Nisco India</u> Model : <u>Pulse wave</u></p> <p>S. No. <u>10640</u> Dept. <u>OP</u></p>
---	--

**Service Classification :** Breakdown Call  PMS  Calibration  Cust.Training

**Problem Identified :** Mercury leakage issue.

**Action Taken :** Checked Mercury lost. Tap cover cracked and not fit to machine. This part not available. Damaged cover not repair and reuse condition. So that machine is unserviceable condition.

Completed  Date : ..... Time : ..... Spare Required

Spare Replaced  Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Nidhish Roy</u>	<u>29-01-2024</u>	<u>11:10 am</u>	<u>12:30 pm</u>

**Customer Remark** Machine not working  Completed  Pending

<p><b>Service Engineer Name :</b> <u>Nidhish Roy</u></p> <p><b>Signature :</b> <u>Nbr</u></p> <p><b>Date :</b> <u>29-01-2024</u></p> <p><b>Contact Number :</b> <u>9072575296</u></p>	<p><b>Customer Name :</b> <u>[Signature]</u></p> <p><b>Signature :</b> <u>[Signature]</u></p> <p><b>Date :</b> _____</p> <p><b>Contact Number :</b> _____</p> <p><b>Designation :</b> _____</p> <p><b>Hospital Seal :</b> _____</p>
---	---

MEDICAL OFFICER I/C  
COMMUNITY HEALTH CENTRE  
KODALLOOR



