REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details KANNUR			
1	Name of District				
2	Name of Hospital	GH THALASSERY			
3	Name of Equipment with Make, Model and Serial Number	SUCTION APPARATUS Make: SUPREME ENTERPRISE Model: SUPREME PLUS SN: NA			
4	Equipment ID/ Barcode	1311868 #96365			
5	Date of purchase/ Year of manufacture/Installation Date	11-06-2018			
6	Warranty details (Yes/No)	No warranty			
7	*AMC/ CAMC Period agreed at the time of purchase				
8	Date of breakdown (Date of registrationof complaint through email/ Toll free)	Toll free 16-02-2024			
9	Action taken	Checked the machine found machine is not switching ON, found that motor, suction bottle 2nos, pressure gauge and power cord defective, External body fully rusted			
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged			
11	Recommendations for repair (required service details)	No recommendations			
12	Cost of spares (specify parts and cost)	NA			

13	Asset Value	10,200/-		
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NΛ		
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report attached		
16	Reasons for recommending the equipment as BER	The Supreme Plus Suction Apparatus, installed by Supreme Enterprises in June 2018, has deteriorated significantly, with rusted and weakened body structure, posing a hazard to patients and users. The extensive rusting and physical debilitation compromise the apparatus's integrity, while the motor dysfunction and damaged suction bottle jars exacerbate its unsuitability for medical use. The amalgamated toll exacted by these imperfections highlights an irrevocable estrangement from utility, posing potential harm to patients and operational efficiency. Therefore, we recommend immediate condemnation and to mitigate risks and uphold patient safety.		
17	Name & Signature of CYRIX Authority	AVINASH T		

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Jeekeed & identifical that meuhice arged

gens above & body rubbed. Motor clis function,

bothe damerged. Is per this conclution the markine

bothe damerged. As per this conclution the markine

bothe harmful to Pulseud. So recommeded for

BER. as per BER protocol.

BER. as per BER protocol.

KANNUR - 670002

Jan 18/29 GENERA

Signature of Superintendent/Medical Officer (i/c)

Date:



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

CYRIX

No.:

189408

ISO 13485 : 2012 & ISO 9001-2008 C	ERTIFIED COMPANY		Service Agency					
Service Penert 30/64 1 B. Petta Junction	on, Poonithura, Ko	chi - 682 038. Ke	rala					
Health Facility C. H								
Thatshery, Kannur Ph: 9446688101	Asset No.	Date of Visit: 14.02.2024 Asset No.: 1311868 EQPT Name: Suchan Apparatus. Manufacture Support Model: Support Plus S. No. NA Dept. Pay Ward.						
111.								
Service Classification : Breakdown Cal		Calibratio		Training				
Problem Identified : Such so A	100m= 1 .	0						
Action Taken: Checked the Switching ON, found the Incompleted Date: It 02/24 Time Spare Replaced Requested Description 1. 2. 3.	I motor, cord def	Suction to	offle 2 n xternal Spare	Jo-s				
Cyrix Engineer		Date	Start Time	End Time				
ABDULLID M		17/02/24	lpm	3pm				
Customer Remark	Completed		Pendi	ng dintendens AL MOSPITA AL MOSPITA				
Service Engineer Name: ABDULLA Signature: Date: 17.02.2024 Contact Number: 6282953548.	Customer Name: Soungal C. P. Signature: Date: 17/2/24 Contact Number: 9446688 101 Designation: Nursing officer. Hospital Seal:							



Ref. No: KLBEMMP/24 87

To,

Managing director,

Bemmp-Kerala

Kmscl Trivandrum.

Subject: Correction of Ticket Number in RBER Performa

Dear Sir/Madam,

I am writing to bring to your attention an error in the RBER Performa concerning a recent complaint. The correct ticket ID for the complaint is 96356, which was opened on 16/02/2024 at GH Thalassery (Barcode number -1311868). However, our engineer mistakenly recorded the ticket ID as 96365 instead of the correct 96356.

I kindly request that you consider ticket ID 96356 as the actual ticket ID in the RBER Performa and make the necessary corrections.

We apologize for any inconvenience this may have caused and appreciate your understanding and cooperation in resolving this matter.

Thank you for your attention to this issue.

Best regards,

Blessen Jose

Zonal Manager | North Zone

BEMMP- Kerala

Mobile: 7593847153

Email: zm2.klbemp@cyrix.in

30/641B, Petta, Poonithura, Ernakulam, Kerala-682038

Ph: + 91 97445 55073 / 9072575175 | Email: sales.kl@cyrix.in, service.kl@cyrix.in

CIN:1174140KI 2013PTC034081


www.cyrixhealthcare.com

SUCTION APPARATUS.

		, .	. 45			
DATE	From a ho Reid So issu.	Rys.	. Man!	Bolos	'imhal.	Crastaly
			•		,	
·; · -			- -			
1/1/07	ON from Store	1		1	=	Ps 9,550
2/4/190	Rd From Store		1	-	·	
aluloz	Proge NO 381/14		_		~ 9 ven	De la
	Conclor on Mone.		- `-	V-		
			· ·		,	-6112
11/6/2018	Ruened from the Store	10	.·	2		900-
	(LP/360/18-19-11-6-18)	30.5	3 ,			
	kerala surgical equipment.	See Se	-			:
	(K5 - 12, 320.00) (x - 31/12/2026	8				
ļ	kerala surgicals equipment. (RS-12,32000) ex _ 31/12/2026 Bar code 20 _ 70130650	00	 -			·
			:			
, , ,						
31/5/18	landemned as per order No.					
	B2 8196 2017 Dt 316 20180	7				
	Superintendent general Hospital		1	1		ellitono
	Same order No)					Stall on the
15/9/2023	Red from the Store	1.1.		2		bal mo
15. 11 2245.	(Donalid ARTCO By Co-operatore)		1			
	Rusal Bank, Malassery					- ,
6			. ,			
	12/3/24					
. 18	()					
0/2	SUPPLIED HOSPITA		. 4			
1	- TEM PRALASSERY - BIT IV					
	SE TO 250				,	
,						
		,				
* a						
			- '	1		1.
		1	1	1	1	







No Bounga. C.P. Sou nous.
Nunsing. offices.



