

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

CYRIX

No.:

215434

THE SOUTH DOOR IN WAY	oonithura, Ko v.cyrix.com	chi - 682 038, Ke E-mail : bemp.kl	Service Agency rala @cyrix.in	
Health Facility CHC Mulhukulam Address Diot Alappusha Ph : 6238553162	Call Registration Date : 22/5/2024			
Service Classification : Breakdown Call		Calibratio		t.Training
Action Taken: Checked the much Element 18 Fourty: The war 18 byoken: Wear and Tear Completed Date: Ollowally Time: Spare Replaced Requested	vter is	Leaking	due to 1	Heating he body
	Qty.	Part Nun	nber	Required PR Number
Description Cyrix Engineer	Qty.			PR Number
Cyrix Engineer	Qty.	Date	Start Time	PR Number
	Qty.			PR Number End Time
Cyrix Engineer Sunth Chandras	Qty.	Date 01/06/2014	Start Time	End Time

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details	
1	Name of District	ALAPPUZHA	
2	Name of Hospital	CHC MUTHUKULAM	
3	Name of Equipment with Make, Model and Serial Number	STERILIZER MAKE :- SH SURGICALS MODEL :- NA SN :- NA	
4	Equipment ID & Barcode	112598 & 0431068	
5	Date of purchase / Year of manufacture /Installation Date	05/02/2019	
6	Warranty details (Yes/No)	NO WARRANTY	
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC	
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	22/05/2024	
9	Action taken	Checked the machine and found that the heating element is faulty. The water is leaking due to the body is broken. Wear and Tear	
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged	
11	Recommendations for repair (required service details)	Not Recommended For Repair	
12	Cost of spares (specify parts and cost)	NA	

13	Asset Value	RS:-9440/-
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service Report Attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that the heating element is faulty. The water is leaking due to the body is broken. Wear and Tear. The equipment installed on 05/02/2019 aged up to 5 Years and 3 Months. The machine irreparable condition. So we are recommending the equipment for condemnation
17	Name & Signature of CYRIX Authority	SHARATH CHANDRAN STATES

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Reconverded for BCR

Signature of JC BM (NHM)

Date 1 6 2024

Seal

- date.

Signature of perintendent / Medical Officer (i/c).

MEDICAL OFFICER-IN-CHARGE

LP- 5	5 Years		.5	
	Auto clave	Rd	Cont	Bal
1	Dr from ald Books			1
141	page No. 54			-
	Det of Rd Hunter all	+7		
	Det of Rd 144400 all 23/12/97/6/19	1-5		/
	tief a greek	17		-
				-
	MocHM Date 30/6/13 Condemed	13/-		-
		-		NIL
	Ran Button len XIO:		7_	NIC
C 0 0	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	1		1
5 0 0019	Received from office			
	S. B. Savgleds Kayankulom. (Re. 9440)			
	Bill No: B 2056			
	Dit No. O aus			
Talk Locality				
				-
				-
				-
				-
				_
				-
			_	+
-				
	galactic part of the state of			1
			1	1 3

















