

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



ISO 13485 : 2012 & ISO 9001-2008 CERTI	A DESCRIPTION OF THE PARTY OF T	AEDR Approved	Sarvica Aganey	
Service Report 30/64 1 B, Petta Junction, F	Poonithura, Koo	hi - 682 038, Ke	rala	
Ph : 98472 99500 Website : www				
			91712	
Health Facility CHC CHEMPUNDURAM	Caller ID: 122061 Date of Visit: 15 7 2 4			
Address				
DIST: ALAPPOZHA	Asset No. :	04.30	2.11	
VIS.I. ALAT PUZHA	EQPT Name	e: Stedi	zel	
Ph: 8137021913	Manufactur	e Keraja Sux	Model:	NA
		/	Dept.	
Service Classification : Breakdown Call	PMS _	Calibratio	on Cust	.Training
Problem Identified :	function	100	Steam	leaking
	••••••			
	Su Do	d asse	mbly is	CONTRACTOR OF THE PROPERTY OF
and difference Chottom Franked happened, sattley Trusted Date: 1517124. Time:	portion Do	d osse of dog Cwhim	nby is () Un e) posts	bended ear and on is
and defective Chottom Franked happened, satter Trusted Date: 1517124. Time: Spare Replaced Requested	Joonson Joseph	of dog	Spare	hended ear and on 15 Required
and defense, Chottom tear happened, satter Tasted: Date: 1517124. Time:	portion Do	d osse of dog Cwhim	Spare	bended ear and on 15
and defective Chottom Fray happened, satter Tasted Date: 1517124. Time: Spare Replaced Requested Description	Joonson Joseph	of dog	Spare	hended ear and on 15 Required
and defective Chottom FCQY happened, Santtey Tusted Completed Date: 1517124. Time: Spare Replaced Requested Description	Joonson Joseph	of dog	Spare	hended ear and on 15 Required
and defective Chottom FCQY happened, Santtey Tusted Date: 1517124. Time: Spare Replaced Requested Description	Joonson Joseph	Part Nu	Spare	Required
and defective Chottom FCQY happened, Sattey Tusted Date: 1517124. Time: Spare Replaced Requested Description Cyrix Engineer	Joonson Joseph	Part Nu	Spare Start Time	Required PR Number
and defective Chottom Franked Date: 1517124. Time: Spare Replaced Requested Description Cyrix Engineer Midney Control Cyrix Engineer	pontion pontion value	Part Nu	Spare	Required PR Number
and defective Chottom Franked Date: 1517124. Time: Spare Replaced Requested Description Cyrix Engineer Midhad	ponton Valve 1:00Pm	Part Nu	Spare Start Time	Required PR Number
Completed Date:	pontion pontion value	Part Nu	Spare Start Time	Required PR Number
Completed Date: 1517124. Time: Spare Replaced Requested Description Cyrix Engineer Customer Remark	Qty. Completed Custome	Part Nu Date 15/7/24	Spare Start Time	Required PR Number
Completed Date: 1517124. Time: Spare Replaced Requested Description Cyrix Engineer Customer Remark Not Norking condition, Brown	Qty. Completed Customer Signatur	Part Nu Date 15/7/24	Spare Start Time	Required PR Number End Time
Completed Date: 1517124. Time: Spare Replaced Requested Description Cyrix Engineer Customer Remark Not Norking condition, Charles Service Engineer Name: Midhary Roll	Qty. Completed Custome	Part Nu Date 15/7/24 Pr Name: A House Number: 8	Spare Start Time	Required PR Number

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

15000	Particulars	Details		
-	Name of District	ALAPPUZHA		
2	Name of Hospital	CHC CHEMPUPURAM STERILIZER MAKE :- KERALA SURGICALS MODEL :- NA SN :- NA		
3	Name of Equipment with Make, Model and Serial Number			
4	Equipment ID & Barcode	122061 & 0430211		
5	Date of purchase / Year of manufacture /Installation Date	15/03/2018		
6	Warranty details (Yes/No)	NO WARRANTY		
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC		
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	09/07/2024		
9	Action taken	Checked the machine and found that steam leaking from door assembly. Door assembly bended and defective. Wear and Tear happened, safety valve assembly is rusted.		
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged		
11	Recommendations for repair (required service details)	Not Recommended for Service		
12	Cost of spares (specify parts and cost)	NA		

13	Asset Value	RS:- 6500/-
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/_Authorized Service Provider/CYRIX (Attached or Not)	Cyrix Service Report Attached.
16	Reasons for recommending the equipment as BER	Checked the machine and found that steam leaking from door assembly. Door assembly is bended and defective. Wear and Tear happened, safety valve assembly is rusted. Not safe for use. The equipment was installed on 15/03/2018 and aged up to 6+ years. The machine is irreparable condition. So we recommending the equipment as BER.
17	Name & Signature of CYRIX Authority	MIDHUN RAJ R

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recommended for Dack

JYOTHISH 28 MAR 24

JYOTHISH 28 MAR 24

Signature of JC BM (NHM)

Signature of Superintendent Medical Officer (i/c)

Date

Seal

FIRE EXTINGUISHER LP-long.

FIRE EXTINGUISHER LP-long.

FIRE EXTINGUISHER LP-long.

Cochin suraktha fine security on good condition.

LOST RS: 10: 384/mo ON per Bill no: CSF lurec, 1000244.

Duted 713/18

	Recience	13344 Balance	Syphotox	mo's
L	Fire extinguisher B type @		Surger	
		D OPP		
		O. Hone		
		O Confirmation Nil	Se	go.

Halis Steriliser Autoclave 12x12 (3 3) - (1) Recursed how kerala surgical equipment co rocky enged condition cost RSI 3500/m CB per involvence 9162 palad 15/3/18

1) Sterilises Autoclave (Doming 2000 Nil & You

(signal space (south) south of the

MEDICAL OFFICER
DIMMUNITY HEALTH CENTRE
CHEMPIJMPURAM

