


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No.	Particulars	Details
1	Name of District	MALAPPURAM
2	Name of Hospital	DH TIRUR
3	Name of Equipment with Make, Model and Serial Number	EQUIPMENT: MULTI PARAMONITOR Make: SKANRAY Model: STAR 60 Serial Number : H14BD0791
4	Equipment ID/ Barcode	TICKET ID: 123739 BARCODE NO :1010855
5	Date of purchase/ Year of manufacture/Installation Date	Installation date : 11/05/2015
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of Purchase	NO AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	17/07/2024
9	Action taken	Checked the machine & found problem with Main board , Dc to Dc board & Display .Need to replace These spare for further checking
10	Present status of the equipment (Fullydamaged / partially damaged)	NOT WORKING
11	Recommendations for repair(required service details)	No recommendation
12	Cost of spares (specify parts and cost)	MAIN BOARD: 26560 DC TO DC BOARD: 7500 DISPLAY: 16461 TOTAL: 50521/-

13	Asset Value	70000/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	72.15%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX Service Report & OEM Quotation
16	Reasons for recommending the equipment as BER	Checked the machine and found, Main board, Dc to Dc board & display defective. The equipment was installed on 11/05/2015 Aged up to 9 Years and 2 months. Repairing cost is 72.15% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	GOKUL KT 

*Not mandatory


#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Verified with the damage of main board, DC-DC board and display. Beyond economic repair.





02/08/24

Signature of JC BM (NHM)

Consultant Biomedical Engineer
NHM Malappuram

Date: 8/8/24




Signature of
Superintendent/Medical Officer (i/c)

Superintendent
DISTRICT HOSPITAL
TIRUR - 676 104



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 233658

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>DH TIRUR</u></p> <p>Address <u>MALAPPURAM</u></p> <p>Ph : <u>9288027953</u></p>	<p>Call Registration Date : <u>17/07/2024</u></p> <p>Caller ID : <u>123739</u></p> <p>Date of Visit : <u>18/07/2024</u></p> <p>Asset No. : <u>1010855</u></p> <p>EQPT Name : <u>Multiparam monitor</u></p> <p>Manufacture <u>SKANRAY</u> Model : <u>STAR 60</u></p> <p>S. No. <u>H14B25791</u> Dept. <u>ICU</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Multiparam monitor not working.

Action Taken : checked the machine found problems with main board, DC to DC board and display. need to replace these space for further checking.

Completed Date : 18/07/2024 Time : 11:30 AM Spare Required


Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrlix Engineer	Date	Start Time	End Time
<u>Sh. habudheen</u>	<u>18/07/2024</u>	<u>10 AM</u>	<u>11:30 AM</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Sh. habudheen</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>18/07/2024</u></p> <p>Contact Number : <u>9072522046</u></p>	<p>Customer Name : <u>[Signature]</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>18/7/24</u></p> <p>Contact Number : <u>[Signature]</u></p> <p>Designation : <u>N/A</u></p> <p>Hospital Seal : <u>9961703517</u></p>
---	--



Superintendent
 DISTRICT HOSPITAL
 TIRUR - 676 104



Skanray Technologies Limited

HEALTHCARE DIVISION
 Plot # 360, KIADB Indl. Area, Hebbal
 Mysore - 570 018, Karnataka
 Email : ck@skanray.com
 Toll Free No.: 1800-425-7002

No 11011

Estimate for on call Service

To,

Cyrix healthcare
 Ernakulam

Service Dealer	Skanray Technologies Ltd. # 406, 8/96-97, Hill:te Platino Complex, 4th Floor, Shankar Nagar Colony Road, Kannadikkadu Maradu, Ernakulam, Kerala-682304
Complaint No.	
Complaint Date	
Date of Examination	

Product description	Star 60	Serial No.	-NA-
Complaint details	-NA-		

With reference to your above complaint, after a preliminary examination, we are submitting this estimate for repairs of the unit. We request your approval, to enable us to carry out the repairs.

S.No.	Spare Parts to be replaced	Qty	Amount
1	Star 60 Main board	01	26560
2	Star 60 DC-DC board	01	7500
3	Star 60 Display	01	16,461
4			
5			
SC1	Service Charges (Including Travel & Incidental Expenses)		
	Total		50,521

The above estimate is being submitted after preliminary inspection of the unit, hence the charges are subjected to an increase incase further Spare parts / components replacement is needed. The charges indicated are for replacement of spare parts, defective material to be returned back to Skanray / Service franchisee. Any disputes arising will be settled in the courts of Mysore Jurisdiction only.

Payments to be made through Cheque / DD in-favour of "Skanray Technologies Limited"

I / We here by approve the above service estimate rates and confirm that the payment, as indicated, will be made immediately after the repair of the defective unit. I / we also approve to carry out the repair work of the defective unit. I / we also accept in the event of not making the payment, you have the rights to take back the spare replaced to set right the unit.

Approved by :
 Signature : _____
 Name : _____
 Date : _____

Prepared by :
 Signature : ASWIN PREM
 Name : _____
 Date : _____



Request for Skanray Star 60 Multipara monitor Spare Quotation (123739)

messages

From: rahuljith <rahuljithcyrix@gmail.com> Sat, 20 Jul, 2024 at 1:00
To: aswin.prem@skanray.com
Cc: Blesson Jose <zm2.klbemp@cyrix.in>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Gokul K T <gokulcyrix@gmail.com>

Dear Sir/Madam,

Kindly share with me the Price quotation for Star60 Multiparamonitor main board,DC-Dc board and Display.
Make: Skanray Technologies
Model : Star 60.
Serial number :H14BD0791
Barcode:1010855
Ticket l'd:123739

Herewith attached the equipment photographs for your reference.

Regards,
Rahuljith.v
Sr.BME BEMMP
Malappuram
Cyrix Healthcare pvt.ltd
9539838931

From: aswin Prem M <aswin.prem@skanray.com> Mon, 22 Jul, 2024 at 10:10
To: rahuljith <rahuljithcyrix@gmail.com>
Cc: Blesson Jose <zm2.klbemp@cyrix.in>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>, Gokul K T <gokulcyrix@gmail.com>

Dear Rahuljith

Please find the attached quotation for your reference

[Quoted text hidden]


Please consider the Environment before printing this e-mail.

The information contained in this message (including any attachments) is confidential and may be privileged or otherwise protected from disclosure. If you are not the intended recipient, you must not copy this message or attachment or disclose the contents to any other person. If you have received this transmission in error, please notify the sender immediately by return e-mail and permanently delete this message and any attachments from your system. Any dissemination, use, review, distribution, printing or copying of this message in whole or in part is strictly prohibited. Please note that e-mails are susceptible to change.

SKANRAY (including its group of companies) shall not be liable for any omission or error in the message, improper or incomplete transmission of the information contained in this communication or for any delay in its receipt or damage to your system. SKANRAY (or its group of companies) does not guarantee that the integrity of this communication has been maintained or that this communication is free of viruses, interceptions or interference.



[Handwritten Signature]
8/8
Superintendent
DISTRICT HOSPITAL
TIRUR - 676 104



Shrey
Superintendent
DISTRICT HOSPITAL
TIRUR - 676 104

DISTRICT HOSPITAL, THIRUR 12

SUB STOCK REGISTER FOR INSTRUMENTS

Invoice No.	Date of Receipt	Name of Item No of Item	Date of Installation	Rd	Issued	Tr. out to Unservicable Reg.	Balance	Price/Unit	Rd Throught	Sign of S/N	Sign of H/N
		Multiparam monitor									
175	11/5/19	ECG Monitor + ECG cable	11/5/19		1		71428		LP DMS		
		Received from store									
	29/8/19	ECG Monitor									Page no: 29.5
15/133	17/1/19	Received from store									page no: 19
2/1911				3			8	9992	KMCL		
2	25/11/2019	Received from store									
		(Multiparameter Monitor)									
		Main stock		2 NOS			10				
		(Page no: 124 SR of Instrument vol. VIII)									
		KMSCL Supply order no: 50/701/2019-2020									
		dated 27/8/19									
153	27/4/2020	Received from store									
		Date - 27/4/20					11				
		(No bill, no installation done for Covid Purpose Contact directed)									
		Item (store stock Page no: 125)									
10/8/20		Transit to relative									
							1	10			
28/2/22		Received from store					10	20	18.11.944/100		
12/3/22		Transit to casualty						19			
		(Common)									
		stock Page no: 315									
22/1/22		ECG cable									
		Monitor 5 lead ECG patient cable									
		Received from store									



Superintendent
 DISTRICT HOSPITAL
 THIRUR - 676 104

23/6/22
 [Signature]

Received from store
 Monitor 5 lead ECG patient cable