



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 232305

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>DH Meekumangad</u></p> <p>Address <u>Taikandam</u></p> <p style="padding-left: 40px;"><u>Kerala</u></p> <p>Ph : <u>9447213331</u></p>	<p>Call Registration Date : <u>04/07/2024</u></p> <p>Caller ID : <u>120988</u></p> <p>Date of Visit : <u>10/07/2024</u></p> <p>Asset No. : <u>012257</u></p> <p>EQPT Name : <u>Ultrasound Therapy unit</u></p> <p>Manufacture <u>Storics</u> Model : <u>Biotech</u></p> <p>S. No. <u>04533</u> Dept. <u>physiotherapy</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not working

Action Taken : checked the machine and found High Voltage PCB and 1 Mhz Applicator defective. Need to replace these spares for further checking and working condition of the equipment. Enquired spares from OEM.

Completed Date : 10/07/24 Time : 11:00 AM Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.				
2.	<u>NA</u>	<u>NA</u>	<u>NA</u>	<u>NA</u>
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>midhun .BM</u>	<u>10/07/24</u>	<u>10.00 AM</u>	<u>11.00 AM</u>

Customer Remark Completed Pending


<p>Service Engineer Name : <u>midhun .BM</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>10/07/2024</u></p> <p>Contact Number : <u>9074167987</u></p>	<p>Customer Name : <u>[Signature]</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>[Signature]</u></p> <p>Contact Number : <u>9025544251</u></p> <p>Designation : <u>Physiotherapist</u></p> <p>Hospital Seal : <u>[Seal]</u></p>
--	---

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	DH NEDUMANGAD THIRUVANANTHAPURAM
3	Name of Equipment with Make, Model and Serial Number	Equipment Name : Ultrasound Therapy Unit Make : Stryker Model : Biotech Serial No : NA
4	Equipment ID/ Barcode	120983/0112287
5	Date of purchase/ Year of manufacture/Installation Date	17/09/2018
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No CAMC/AMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	04/07/2024 (Toll free)
9	Action taken	Checked and found High voltage PCB and 1Mhz Applicator defective. Need to replace these spares for further checking and working condition of the equipment. Enquired spares from OEM.
10	Present status of the equipment(Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NOT RECOMMENDING FOR REPAIR
12	Cost of spares (specify parts and cost)	1Mhz Applicator 5cm.sq with crystal - 2968/- High voltage PCB - 8850/- Freight cost - 236/- TOTAL = 12054/-

13	Asset Value	16352/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	73.7%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT AND VENDOR QUOTATION ATTACHED
16	Reasons for recommending the equipments as BER	Checked and found High voltage PCB and 1Mhz applicator defective. The equipment was installed on 17/09/2018 and covered up to 5+ years. The repairing cost is 73.7%. As per the tender clause 5.3.14.1 both criteria met. So recommending the unknit for condemnation.
17	Name & Signature of CYRIX Authority	MIDHUN BM 


*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

High voltage PCB and 1MHz applicator defective
 Verified the estimate, can be RBER as per
 Guidelines
 Date of call : 4.07.2024

MANEESHA MOHAN M.R.
 Junior Consultant (Biomedical)
 National Health Mission
 Thiruvananthapuram


 08-08-2024
 Signature of JC BM (NHM)

Date:


 Signature of
 Superintendent/Medical Officer (i/c)

സൂപ്രണ്ട്
 ജില്ലാ ആശുപത്രി
 തിരുവനന്തപുരം



MEIBOT TECHNOLOGIES

ARA 44, 2nd Floor, Thyparambil Building,
Ammankovil Street Mullackal,
Alappuzha Kerala- 688011
Phone no.: 9447038191 Email: info@meibot.com
GSTIN: 32BVOPM0744D1ZT, State: 32-Kerala

Estimate

Estimate For

Cyrix Healthcare Pvt Ltd

FIRST FLOOR, 30/641B
PETTA JUNCTION,
POONITHURA, ERNAKULAM-682038,
KERALA INDIA

GSTIN : 32AAFCC2499H2ZM

State: 32-Kerala

Estimate Details

Estimate No. : MT/QT/24-25/109

Date : 16-07-2024

Place of supply: 32-Kerala

#	Item name	Item Code	HSN/SAC	Quantity	Unit	Price/ Unit	GST	Amount
1	1Mhz Applicator 5cm.sq. with crystal	05100	90189099	1	Nos	₹ 2,650.00	₹ 318.00 (12%)	₹ 2,968.00
2	Services & Repairing Charges (High Voltage pcb replacement for UST-0110375)	SRV-REP	995469	1	Nos	₹ 7,500.00	₹ 1,350.00 (18%)	₹ 8,850.00
3	Freight Charges	FREIGHT	48195010	1	-	₹ 200.00	₹ 36.00 (18%)	₹ 236.00
	Total			1			₹ 1,704.00	₹ 12,054.00

Tax type	Taxable amount	Rate	Tax amount	Amounts
				Sub Total ₹ 12,054.00
SGST	₹ 2,650.00	6%	₹ 159.00	Total ₹ 12,054.00
CGST	₹ 2,650.00	6%	₹ 159.00	
SGST	₹ 7,700.00	9%	₹ 693.00	
CGST	₹ 7,700.00	9%	₹ 693.00	

Estimate Amount In Words

Twelve Thousand Fifty Four Rupees only

Terms and Conditions

Terms and conditions:

Payment Terms: 100% Advance

The Guarantee/Warranty would not cover: -

- No Warranty on Rubber, Plastic & Wooden Products / Parts.
- Any Mechanical damage/breakage.
- Any damages to vacuum Tube / Valve (if any),Meters.
- Any damages due to electrical fluctuation.
- Supply of consumables and accessories.
- Any Physical damage to the Device due to Intentional act or wilful neglect.
- Any Equipment's Serial number that has been altered, defaced or removed, or has been modified to alter its functionality or capability without the written permission of Hamb Meditech LLP.

Bank Details



Name : STATE BANK OF INDIA

Account No. : 41310832759

IFSC code : SBIN0003106

Account holder's name : Meibot Technologies



For : MEIBOT TECHNOLOGIES

Authorized Signatory



Quotation for the service of UST Machine

4 messages

MURALIKRISHNA S <muralikrishnaalpy@gmail.com>
To: kasyepcyrix@gmail.com

Wed, 17 Jul 2024 at 6:54 pm

Dear Sir/ Madam,

Kindly find the attached quotation.

Thanks and Regards

Murali Krishna
Sales & Service Engineer

Whatspp: <https://wa.me/919074126766>

MURALIKRISHNA S <muralikrishnaalpy@gmail.com>
To: kasyepcyrix@gmail.com

Sat, 27 Jul 2024 at 10:12 am

Dear Sir / Madam,

Kindly find the attached quote.

--
Thanks and Regards

Muralikrishna Suresh
Sales & Service Manager

Whatspp: <https://wa.me/919074126766>

[Quoted text hidden]

Kasyep P V <kasyepcyrix@gmail.com>
To: MURALIKRISHNA S <muralikrishnaalpy@gmail.com>

Mon, 29 Jul 2024 at 1:56 pm

Sir,
Recieved the estimate, will do the payment on 30/7/2024

Thanks & Regards,

KASYEP PV
District Incharge ,Trivandrum
CYRIX HEALTHCARE Pvt.Ltd
KLBEMP
Ph : +91 7593847134
kasyepcyrix@gmail.com

[Quoted text hidden]

Kasyep P V <kasyepcyrix@gmail.com>
To: MURALIKRISHNA S <muralikrishnaalpy@gmail.com>

Tue, 6 Aug 2024 at 1:18 pm

Received the machine at the site.

OPY UNIT



SW1




SW2

CYRIX BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)

TOLL FREE NO: 1800- 425-7669

BAR CODE - 0112287




സംസ്ഥാന ആശുപത്രി സേവനങ്ങൾ

CYRIX HEALTHCARE SERVICES

CNI: DH 7317 S.N: 04533

PRO: 1 Ultrasound Therapy Unit

ID: 0112287

CALON: 22-05-2023

CAL.DTE: 21-05-2024

