

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

No. : 169759

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in Service Report Health Facility COH ALAPWZHA Caller ID: 128647 Date of Visit: 1718124 Address Asset No.: 041.0365 DIST GLAPPUZHA EQPT Name: Infrance Lamp Ph: 9847507709 Manufacture NISO INDIA Model: NASCO... S. No. NA Dept. PMR Service Classification: Breakdown Call Calibration **Cust.Training** PMS lans and lans Date : 17 8 24 Time : 9:30 Am Spare Required Completed Spare Replaced Requested Description Qty. Part Number PR Number 1. 2. 3. Cyrix Engineer Date **Start Time End Time** 17/8/24 9:00mm Midhur ray. R Completed Pending **Customer Remark** 110 889 0 889 Service Engineer Name: Midhus Yay Signature: Customer Name : Signature

Contact Number:

Date:

Contact Number Designation 4 Hospital Seal:

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI.	Particulars	Details		
No				
1	Name of District	ALAPPUZHA		
2	Name of Hospital	GH ALAPPUZHA		
3	Name of Equipment with Make, Model and Serial Number	INFRARED LAMP MAKE :- NISCO MODEL :- NA SN :- NA		
4	Equipment ID & Barcode	128647 & 0410365		
5	Date of purchase / Year of manufacture /Installation Date	14/06/2013		
6	Warranty details (Yes/No)	NO WARRANTY		
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC		
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	10/08/2024		
9	Action taken	CHECK THE MACHINE AND FOUND THAT THE IR LAMP AND LAMP HOLDER ARE DEFECTIVE. HANDLE IS BROKEN, METALIC BODY COVER IS BENDED AND RUSTED,		
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED		
11	Recommendations for repair (required service details)	NOT RECOMMENDED FOR REPAIR		
12	Cost of spares (specify parts and cost)	NA		

13	Asset Value	RS:- 495/-			
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	1314			
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)				
16	Reasons for recommending the equipment as BER	CHECK THE MACHINE AND FOUND THAT THE IR LAMP AND LAMP HOLDER ARE DEFECTIVE. HANDLE IS BROKEN, METALIC BODY COVER IS BENDED AND RUSTED, MACHINE WAS INSTALLED ON 14/06/2013, AGED UP TO 10 + YEARS. MACHINE IS RUSTED AND IRREPARABLE CONDITION. SO WE RECOMMENDING THE EQUIPMENT FOR CONDEMNATION			
17	Name & Signature of CYRIX Authority	MIDHUN RAJ R			

#Based on the period of life and value as per the BER guidelines *Not mandatory

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recomended for Deg

JYOTHISH THOMAS

JYOTHISH THOMAS

Consultant (Biomedical Engineering)

Consultant (Biomedical Engineering)

Signature of JC BM (NHM)

Signature of Superintendent / Medical Officer (i/e) Date

Julya Red Laury Exstand

					2
Date	Profeculars	Receipt	Issued	Bluce	Remark
	Rd from store				Price ouis
	ME VOI. IL A	10		10	'
	P.N: 20			-	676.19
					+tax.
15 06 13	Issued for use		3	8	
14.05.10	, , ,		9	6	and the last
8.4.15		-	1 2	4	
9.10.16			2	2	
8.617	\		2	0	
11	-11				
416118	Rd from store	1 01	-	10	
	PN: 265. VOI. IV	N OI		10	20/11
	TN . 463.				notins
			Iwos	dispose	I we he
			no F	(B)	1983 -
		-			2019
	Condeminationd	1 1 1	1	1, ,	
101916	Condeminationd	me - 17	.204	-10	
				4	
20 6 22	Rd form store			1	Venhid
20101-	Book HDC LP	-			
	Volx	01	The same of the	In In	D. Laker
	Page no: 027			1	11/8/11
					\$5:1200
9/102	Rd from store				
113(2	Book HIX LP WIX	O L		150	1× 2299
	Page no. 186.	Var and	11		.99
	6	[四十二]	* 1		A DEN
		1000			Led THE HOSPIT
		APP THE	35/	Soul	TO ERAL UZ
			1 1	2	C. B.

