



# BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

## CYRIX

HEALTHCARE PVT LTD

**No. :** 229555

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report**

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility ..... <i>Taluk Hospital,</i></p> <p>Address ..... <i>Kothamangalam,</i></p> <p style="padding-left: 100px;"><i>Ernakulam (ot)</i></p> <p>Ph : ..... <i>09946859118</i></p>	<p>Call Registration Date : ..... <i>13-06-2024</i></p> <p>Caller ID : ..... <i>117082</i></p> <p>Date of Visit : ..... <i>14-06-2024</i></p> <p>Asset No. : ..... <i>072220</i></p> <p>EQPT Name : ..... <i>Fetal Doppler</i></p> <p>Manufacture <i>Perfecxa</i> Model : <i>FD6-620C</i></p> <p>S. No. <i>680011801126</i> Dept. <i>Labour Ward</i></p>
---	--

**Service Classification :** Breakdown Call  PMS  Calibration  Cust. Training

**Problem Identified :** ..... *Fetal Doppler not working*

**Action Taken :** ..... *checked the machine and found that FHR probe and mainboard are defective.*

Completed  Date : *14-06-24* Time : *2:30PM* Spare Required


Spare Replaced  Requested

Description	Qty.	Part Number	PR Number
1. <i>FHR Probe</i>	<i>1No.</i>		
2. <i>Main Board</i>	<i>1No.</i>		
3.			

Cyrix Engineer	Date	Start Time	End Time
<i>Jibin Thomas George</i>	<i>14-06-24</i>	<i>12:00PM</i>	<i>2:30PM</i>

Customer Remark .....  Completed  Pending

<p>Service Engineer Name : <i>Jibin Thomas</i></p> <p>Signature : <i>Jibin</i></p> <p>Date : <i>14-06-2024</i></p> <p>Contact Number : <i>9047958051</i></p>	<p>Customer Name : <i>Sabitha Mathew</i></p> <p>Signature : <i>Sabitha</i></p> <p>Date : <i>14/6/24</i></p> <p>Contact Number : <i>9946859118</i></p> <p>Designation : <i>SUPERINTENDENT</i></p> <p>Hospital Seal : <i>TALEUK HEADQUARTERS HOSPITAL</i></p>
--	---




**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

**Recommendations for Beyond Economic Repair (BER)**

**PROFORMA**

<b>Sl. No</b>	<b>Particulars</b>	<b>Details</b>
1	Name of District	Ernakulam
2	Name of Hospital	TALUK HOSPITAL, KOTHAMANGALAM
3	Name of Equipment with Make, Model and Serial Number	Equipment: FETAL DOPPLER Make : PERFECXA Model : FD6-6200 Sr.no :6800118011126
4	Equipment ID & Barcode	117082 & 0722220
5	Date of purchase / Year of manufacture /Installation Date	26-12-2017
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	13-06-2024 (Toll Free)
9	Action taken	Checked the machine and found that FHR probe and mainboard are faulty.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Not recommending for repair.
12	Cost of spares (specify parts and cost)	NA


13	Asset Value	Rs.4000
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached
16	Reasons for recommending the equipment as BER	Checked and found that FHR Probe and main board are defective. Equipment installed on 26-12-2017 and the machine outlived 6+years. Quotation not submitted since the spares are not available in the market. So recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	JIBIN THOMAS GEORGE 



\*Not mandatory



#Based on the period of life and value as per the BER guidelines

\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:  
 Reported the probe and main board faults by cyrix. Submitted BER after 30days.  
 Spare unavailability reported. Not attached  
 Spare enquiry documents along with BER.  
 Equipment met BER yearwise criteria.  
 Quot not available.


  
 Signature of JC BM (NHM)  
 31/7/24  
 National Health Service  
 Aroyyakeralam Ernakulam

  
 Superintendent / Medical Officer (i/c)  
 SUPERINTENDENT  
 TALUK HEAD QUARTERS HOSPITAL  
 KOTHAMANGALAM - 686 691  
 Date  




*[Handwritten Signature]*

**SUPERINTENDENT**  
TALUK HEAD QUARTERS HOSPITAL  
KOTHAMANGALAM - 686 691




Foetal Doppler charges

175

Date	Description	Qty	Rate	Total	Issued	Balance	Remarks
18/12/17	To 10 from Job Share Reg	1					
	N 2 Page no. 156	2			2	2	800
	RFS 10/3/17 Duplex charges	1	9150/-				
	26/12/17 only Doppler	1	2150/-				
	7/12/18 [Bairn LCR 313 ponduscarip extension cord]						
15/12/17	Round from store	1				3	84
	DPS Foetal Doppler Made in UK						
	Plus Lp m 7013 HSN Code 9018	2				5	84
22/6/17	Trouble to unresponsive register p no 22 10/2/17				2	3	
21/1/17	RFS (Doppler foetal (small))					5	41
	Thirupathi enterprises						

BAR CODE 0752006 model Lonbec 10CC  
 " 0752016 Rs 6400+768 Rs 7168

WARRANIY



*[Signature]*  
 SUPERINTENDENT  
 TALUK HEAD QUARTERS HOSPITAL  
 KOTHAMANGALAM - 686 691