


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

**Recommendations for Beyond Economic Repair (BER)**

**PROFORMA**

<b>Sl. No</b>	<b>Particulars</b>	<b>Details</b>
1	Name of District	KANNUR
2	Name of Hospital	THQH PAYYANNUR
3	Name of Equipment with Make, Model and Serial Number	PATIENT MONITOR Make: BPL Model: EXCELLO SN: CRTM0M5568
4	Equipment ID/ Barcode	1320776 #121526
5	Date of purchase/ Year of manufacture/Installation Date	Ticket master installation date is 26.03.2008 As per the stock book installation date is 28-01-2011 (Stock book attached for reference)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of Purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 06-07-2024
9	Action taken	Checked the Machine found Equipment is Not Turning ON, found that SMPS and Module Board Defective. Enquired OEM for quotation
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	SMPS Board -35,000 /- Main Board- 33,000/- <b>Total-68000/-</b>

13	Asset Value	54500/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	124.77%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & quotation attached
16	Reasons for recommending the equipment as BER	Checked the Machine found Equipment is Not Turning ON, found that SMPS and Module Board Defective. Enquired OEM for quotation. In software Equipment installed on 26-03-2008 As per the stock book installation date is 28-01-2011 (Stock book attached for reference) aged up to 13 years and 8 months. Repairing cost is 124.77% both criteria for RBER met. As per tender clause 5.3.14.1 we recommend the equipment for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 


\*Not mandatory

#Based on the period of life and value as per the BER guidelines


\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identified that the machine not switching ON, due to module, SMPS Board defective - Machine aged up to 13 years & above. As per OEM's Quotation the service cost economically not feasible. So recommended for BER as per BER protocol.


  
Signature of JC BM (NHM)  
23/08/2024  
Rachika C B


UP



SNO

Date: 24/8/24





For  
Signature of  
Superintendent  
Medical Officer (i/c)

CONSULTANT BIOMEDICAL  
NATIONAL HEALTH MISSION  
KANNUR - 670002

SUPERINTENDENT  
TALUK HOSPITAL  
PAYANUR, KANNUR DT.





09.08.2024  
RINS/SA/24/5TO,  
CYRIX HEALTHCARE PRIVATE LIMITED  
ERNAKULAM**QUOTATION FOR SMPS BOARD & MODULEBOARD FOR MONITOR EXCELLO**

SL NO	ITEM	RATE	QTY	AMOUNT
1	SMPS BOARD FOR MONITOR EXCELLO (SI No: CRTMOM5568)	35000	1 no	35000.00
2	EXCELLO MODULE BOARD (SI No: CRTMOM5568)	33,000	1 no	33,000.00
GST EXTRA 18%				

For , Rins Marketing &amp; Services



Authorized Signatory

**OUR BANK DETAILS:**

BANK: FEDERAL BANK, A/C NO: 19975500000015, IFSC: FDRL0001997, BRANCH: TALAP



---

## REQUEST FOR QUOTATION 1320776,PATIENT MONITOR, @THQH PAYYANNUR

2 messages

**avinash t** <avinashtcyrix@gmail.com>

Fri, 9 Aug, 2024 at 9:56 am

To: rinsmarketing rinsmarketing service <rinsmarketing@gmail.com>

Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>

Dear Sir,

Please provide quotation and stock availability of below mentioned spares of PATIENT MONITOR (Make-BPL, Model-excello, SL NO. CRTMOM5568)

- 1.SMPS
- 4.Module Board

Thanks & Regards

Avinash T  
District charge, kannur  
bemp kerala  
mobile: +91 6364064948  
E mail: [avinashtcyrix@gmail.com](mailto:avinashtcyrix@gmail.com)

**CYRIX HEALTHCARE (P) LTD**  
30/641B | Petta | Punithura | Kochi | Kerala- 682038  
[www.cyrixhealthcare.com](http://www.cyrixhealthcare.com)

---

**rinsmarketing rinsmarketing service** <rinsmarketing@gmail.com>

Fri, 9 Aug, 2024 at 11:51 am

To: avinash t <avinashtcyrix@gmail.com>

Cc: DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>

Dear Sir,  
Please find the attached quotation.

Regards,  
Anagha

**RINS**  
MARKETING & SERVICES

TM 364 N, 1st Floor, City Tower  
Opp. Chinmaya Balabhavan, Kannur-2  
Tel.: 0497-2704624, Fax.: 2709789  
Mob.: 9846008441, 9947064624  
E-mail: [rinsmarketing@gmail.com](mailto:rinsmarketing@gmail.com)

[Quoted text hidden]



**CYRIX™**  
HEALTH CARE PVT LTD

BIOMEDICAL EQUIPMENT MAINTENANCE  
PROGRAMME (BEMP)



KMSCL

**TOLL FREE NO: 1800 - 425-7669**

**BAR CODE - (8004-890615225)  
1320776**



**BPL**

**MULTI PARAMETER MONITOR**

Model: EXCELLO

Sl. No. CRTMOM5568

Power : 110 - 230V; 50Hz.

Battery : 12V; 2.3AH Sealed Lead Acid

BPL Limited,  
BPL Works, Palakkad - 678007. INDIA



For *[Signature]*  
SUPERINTENDENT  
TALUK HOSPITAL  
PAYANUR, KANNUR



Name of Article: 348  
 Voc. No.

BEDSIDE MONITOR

Previous Ledger Folio:

Date	Particulars	Receipt	Issue	Balance	Initials	Batch No. Exp date Price
28-1-11	Received on per invoice no. EKM/FG/477/10-11 dt 3-1-12. 10 of BPL limited Edappally cochin. in per purchase order no. MSP 3-82779/2010/DHS DT 22-11-10 BPL MPV EXCELLO	3		3		₹. 288000
5-2-11	(3 year warranty from	the date	Installation is made	11-11-11)		
11-1-12	OT		1	2		
	OT		2	NIL		D.V. G.V. HN, ST



*for*  
 SUPERINTENDENT  
 TALUK HOSPITAL  
 PAYYANUR, KANNUR DT.