


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	THQH KOOTHUPARAMBA
3	Name of Equipment with Make, Model and Serial Number	STABILIZER Make: BLUE BIRD Model: BB 150 SN: 1150280820290
4	Equipment ID/ Barcode	1321503 #125778
5	Date of purchase/ Year of manufacture/Installation Date	Ticket master installation date - 28.03.2017 As per stock book Installation Date Is 17.09.2019 (stock book copy attached for reference)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of Purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 26.07.2024
9	Action taken	Checked the Equipment found Equipment is not switching ON, found that Control PCB and Load Transformer Defective. Enquired for quotation.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	Control PCB-1000/- Load transformer-1050/- Total-2050/-

13	Asset Value	Asset value - Nil (Reference asset value same make and model as per Google is 3200)
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	64.06%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & quotation attached
16	Reasons for recommending the equipment as BER	Checked the Equipment found Equipment is not switching ON, found that Control PCB and Load Transformer Defective. Enquired for quotation. In Software Equipment installed on 28-03-2017, As per stock book installation date is 17.09.2019. Aged up to 4 years 11 months. Repairing cost is 64.06% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Checked & ident find that the machine not switching ON. due to control board & load transformer defective. Aged up to 4 years & above. As per BER Protocol the machine recommended for BER.


Signature of Consultant (Biomedical) NHM


CONSULTANT BIOMEDICAL
NATIONAL HEALTH MISSION
KANNUR - 670002

Arunima SR
Pharmacist Gr II



Date: 31/08/2024




SUPERINTENDENT
GOVT TALUK HEAD QUARTERS
HOSPITAL
KUTHUPARAMBA, PIN - 670 643



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 232009

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility THQH KOO THU PARAMBA</p> <p>Address Koothuparamba KANNUR.</p> <p>Ph : 9562847869</p>	<p>Call Registration Date : 26/07/2024</p> <p>Caller ID : 125778</p> <p>Date of Visit : 27/07/2024</p> <p>Asset No. : 1321503</p> <p>EQPT Name : STABILIZER</p> <p>Manufacture Blue star Model : bluebird</p> <p>S. No. 1150280820290 Dept. Pharmacy.</p>
--	--

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Control PCB and Load Transformer defective

Action Taken : checked the equipment and found equipment is not switching on. Found that Control PCB and load transformer defective. Enquired for quotation.

Completed **Date :** 27/07/2024 **Time :** 12:00 PM **Spare Required**

Spare Replaced **Requested**

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
Sayanth	27/7/2024	10:00 AM	12:00 PM

Customer Remark Completed Pending

<p>Service Engineer Name : Sayanth</p> <p>Signature : <i>[Signature]</i></p> <p>Date : 27/7/2024</p> <p>Contact Number : 8606 345 195</p>	<p>Customer Name : Arunima SR</p> <p>Signature : <i>[Signature]</i></p> <p>Date : 27/7/2024</p> <p>Contact Number : 999 564 122</p> <p>Designation : Pharmacist Gr II</p> <p>Hospital Seal :</p>
---	--



SUPERINTENDENT
GOVT. TALUK HEADQUARTERS
HOSPITAL
KOO THU PARAMBA, PIN - 670 6



One time service required for stabilizer #1321503 ,125778 TH koothuparamb

2 messages

avinash t <avinashtcyrix@gmail.com>

Mon, 12 Aug, 2024 at 8:22 pm

To: ecotonicsolutions@gmail.com

Dear sir,

Please provide service for stabilizer at THQH koothuparamb.

Thanks & Regards

Avinash T

District charge, kannur

bemp kerala

mobile: +91 6364064948

E mail: avinashtcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD

30/641B | Petta | Punithura | Kochi | Kerala- 682038

www.cyrixhealthcare.com

ECOTONIC AUTOMATION SOLUTIONS <ecotonicsolutions@gmail.com>

Mon, 12 Aug, 2024 at 8:27 pm

To: avinash t <avinashtcyrix@gmail.com>

Hi Avinash,

Your quotation for above mentioned machine is attached

PFA

Regards

Ecotonic Automation Solutions

+91 75103 48448

www.ecotonics.in

[Quoted text hidden]

TALUK HOSPITAL KUTHUPARAMBA


Page Number : 87

Stock Register of VOLTAGE STABILIZER 1KVA


Date	Invoice No. & Date	Particulars	Receipt	Issue	Balance	Batch No.	Date of Expiry	Rate	Mr	Signature
7.09.19	173/19/20 05-09-19	Delhi Hospital Supply Pvt. Ltd.	1 Nos		1 Nos.	SL-N-11SP		280820250.		<i>[Signature]</i>
		② Basket	11 Nos		11 Nos					
		③ ICE PACK TRAY 06 Nos			06 Nos.					
7.09.19		Above 3 items installed in Pharmacy (Page No 57 sub stock Register of Store)								<i>[Signature]</i>



SUPERINTENDENT
GOVT. TALUK HEADQUARTERS
HOSPITAL
KUTHUPARAMBA, PIN - 670 643



'bluebird'
Automatic
Voltage Stabilizer
Model No. BB 150
Capacity
1 KVA
Input Voltage
150 - 280 V
Output Voltage
220 V +/- 10%
Phase 1
Weight 4.800 Kgs
S.NO.
1150280820290
Mfg. dt. 08/2019
MADE IN INDIA


SUPERINTENDENT
GOVT. TALUK HEADQUARTERS
HOSPITAL
KUTHUPARAMBA, PIN - 670 643

