


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	CHC MATTANNUR
3	Name of Equipment with Make, Model and Serial Number	BP APPARATUS Make: BEURER Model: BM27 SN: NA
4	Equipment ID/ Barcode	1330253 #130551
5	Date of purchase/ Year of manufacture/Installation Date	In ticket master installation date 11.03.2022 As per stock book Installation date is 24.04.2018 (Stock book copy attached for reference)
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of Purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 21.08.2024
9	Action taken	Checked the Equipment found Equipment is not switching ON, found that Main Board, Pressure sensor and Display Defective. Need to replace these spare for further checking.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	2200/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report attached
16	Reasons for recommending the equipment as BER	Checked the Equipment found Equipment is not switching ON, found that Main Board, Pressure sensor and Display Defective. Need to replace these spare for further checking. . In software Equipment installed on 11.03.2022. As per the stock book installation date is 24.04.2018 aged up to 06 years 4 months. Quotation not submitted since spares are not available in the market. So we recommending for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 


*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identified that machine not switching ON, due to main board, pressure sensor, display are defective. need to replace with new spare. The spare cost economically not feasible. Aged up to 6 years & above. So recommended for BER as per BER Protocol.



30/08/2024

Signature of JC BM (NHM)

NATIONAL HEALTH MISSION
KANNUR - 670002

Date: 31 08 2024




മെഡിക്കൽ ഓഫീസർ
സാമൂഹിക ആരോഗ്യ കേന്ദ്രം
Superintendent/Medical Officer (i/c)
മുടമ്പുര-670702



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 234860

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility CHC MATTANNUR</p> <p>Address MATTANNUR</p> <p>..... KANNUR</p> <p>Ph : 09446517548</p>	<p>Call Registration Date : 21/08/2024</p> <p>Caller ID : 130551</p> <p>Date of Visit : 22/08/2024</p> <p>Asset No. : 1330253</p> <p>EQPT Name : BP Apparatus</p> <p>Manufacture Beurer Model : BM27</p> <p>S. No. NA Dept. OP</p>
-----------------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : equipment is not switching on

Action Taken : checked the equipment and found equipment is not switching on, found that main board, pressure sensor and display defective. Need to replace these spare for further checking

Completed Date : 22/08/2024 Time : 11:30am Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			


Cyrix Engineer	Date	Start Time	End Time
Prathyush T. Bhaskar	22/08/2024	10:50am	11:30am

Customer Remark Completed Pending



Service Engineer Name : Prathyush T. Bhaskar
Signature : *[Signature]*
Date : 22/08/2024
Contact Number : 9947025643

Customer Name : Jerry KJ *[Signature]*
Signature : *[Signature]*
Date : 22/8/24
Contact Number : 9446517548
Designation : Sen Nk
Hospital Seal : *[Seal]*



CYRIX™
HEALTH CARE SYSTEMS

**BIOMEDICAL EQUIPMENT MAINTENANCE
PROGRAMME (BEMP)**



KMSCL
Kerala Medical Services Centre Ltd.

TOLL FREE NO: 1800 - 425-7669

**BAR CODE - (8004-890615225)
1330253**



Beurer GmbH, Söflinger Str. 218,
69077 Ulm, Germany

Model: BM 29, Type: BM 28
Item No.: 658.82

Measuring range: 30-260 mmHg
Power: 6V (4 x 1.5V AA)

Mains Adapter (optional): 6V 600mA
Shenzhen Longxc Power Supply Co., Ltd.

CE 0483

 **IP21**



Handwritten signature and date: 3/8/24
മെഡിക്കൽ ഓഫീസർ
സാമൂഹികാരോഗ്യകേന്ദ്രം
മട്ടന്നൂർ-670 702