MAINTE		QUIPMEN ROGRAM R TH MISSI	ME	A REALTHANK
				No: 1003059
ISO 13485 : 2012 & ISO 9001-2003 Service Report 30/64 1 B, Petta J Ph : 98472 99500 Web	unction, Poonit	hura, Kochi- 682	038, Kerala	Agency
Health Facility. T.H.Q.H. Address. Kayan Kulan DISL Alappuzha Ph: 8848204739		Call Registration Date : 31.1.7.1.2024   Caller ID :126.601   Date of Visit :21.8.1.2024   Asset No :04210.60		
		ActionTaken : Begaveling that the compressor Nebulizer Out put Ki These spares for the the Equipment	Motor Wil Lobe îs E Checkij	th Piston Broken, N 19 and W
Spare Replaced Requested	4 Time :	3.00.pm	. Spa	re Required
Description	Qty.	Part N	lumber	PR Number
Cyrix Engineer Savath Chandrey		Date 21/Blday	Start Time	End Time 3.00pm
Customer Remark	Completed		Pend	ling
ervice Engineer Name : Sovath Chan ignature: South pate: 21/8/2024	N. TALUK HOSOI	Customer N Signature: Date: Contact Nur	lame : Brike s Back 21/8/24, mber: 965605	Gov Kayaminist

## REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

## Recommendations for Beyond Economic Repair (BER)

## PROFORMA

SI. No	Particulars	Details
1	Name of District	ALAPPUZHA
2	Name of Hospital	THQH KAYAMKULAM
3	Name of Equipment with Make, Model and Serial Number	NEBULIZER MAKE :- TRUCHECK MODEL :-N8001 SN :- 800117100882
4	Equipment ID & Barcode	126601 & 0421060
5	Date of purchase / Year of manufacture /Installation Date	11/04/2018
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	31/07/2024
9	Action taken	REGARDING THE INSPECTION OF THE EQUIPMENT FOUND THAT THE COMPRESSOR MOTOR WITH PISTON IS DEFECTIVE. NENULIZER OUT PUT KNOBE IS BROKEN.
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NOT RECOMMENDED FOR REPAIR
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	RS := 1175 /-	
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA	
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT ATTACHED	
16	Reasons for recommending the equipment as BER	CHECK THE MACHINE AND FOUND THAT THE COMPRESSOR MOTOR WITH PISTON IS DEFECTIVE. NENULIZER OUT PUT KNOBE IS BROKEN. THE EQUIPMENT WAS INSTALLED ON 11/04/2018, AGED UP TO 6 - YEARS. QUOTATION IS NOT SUBMITTED SINCE SPARE IS NOT AVAILABLE IN THE MARKET. SO WE RECOMMENDING THE EQUIPMENT AS BER	
17	Name & Signature of CYREX Authority	SARATH CHANDRAN	

\* Attach Photograph

Date


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recommended for the

TALUA

gnature of JC BM (NHM) 03

Signatus W. Thankalam erintendent (Medical Officer (1/c)







Nebuliser electrical 22 17/1/05 originally received. 3 406 This from Mat not 24/9/07 Rfd forms store 171109 Rolfm 3 - they welt you? ABDOOD Rot from shu (ed dt 22.12.08) Elspelo Rd for stock pic des, 27. ad dt 22 12.09) Four Nebulgar declined condemed as per 5-H = 1 H order No. 610 (m3) 62 2013 HK FWD DE 23. 2013 11/4/2018 Rd from Stole Kasunja stock. Book page Numb 26 Received from the (Karrings) 2-14-2018 2 Mosquito forceps 3/1/99 3/106 20 Trim from Mat wid A 4 Two masqueto forceps condensed as per adur No: GO COS) 63/2013/H& FWD 2 df & 3. 8. 2013 2 2 mm 2 mo : 20 89/2019 my mor an - 32/mon 27/8/19 andamed 8 ALFBURISER ! Rud form stock 5/2/10 Rol from 8 thre 618/19 88 AA 55 Q glylai Rd. frem stoke [Men stoke] 10 A PR-55] Hislar Rol from Stree [S.R - 55] 15/2/22 The out to mosuricable Ryesty 3 13/13-1, 2/11/13-2, 11/4/12-1,8/3/2010-)