KMSCL E SERVICE PROVIDE	NATIO	MEDICAL TENANCI UN NAL HE		RAMM	E 9	
render No. WO-37/2021-20	R 22/698	CY	RD	X	No.: 16027	
Service Report	13485 : 2012 & ISO 30/64 1 B, Pe Ph : 98472 99500	9001-2008 CERTIFI etta Junction, Po Website : www.	ED COMPANY A onithura, Koch cyrix.com E	ERB Approved i - 682 038, Ke mail : bemp.k	Service Agency Irala	
Health Facility <u></u>				tion Date :	20-11-2	10281
Address THQH	kadabka		Date of Visit		2023	
15	ollan		Asset No. :			
Ph : 98090	7 1996 5		EQPT Name			
			Manufacture S. No. NR	Biolech	Dept. Phys	Comp-Trac
Service Classific	ation : Breakd	Iown Call	PMS	Calibratio		Training
	ed : Molok		0	_	amap	
Action Taken : becomy u pare Sent becomy u	Chudere the 902 Estre the motor the motor	rento te contente contente te	e cure The st the st the construction CB is do ononce co	Bond &	hal - Kiau Contrari 2, Storig the So J a	
Action Taken :	Chuckie the 900 Estig the mate the mate and mate ate :	rento De Staff & Coponi Er	e cure The st the st the construction CB is do ononce co	Bond &	hal - Kiau Contrari 2, Storig the So J a	So we r Invenceto
Action Taken :	Chuck the 905 Colly 101 Mole 101	rento te contente contente te	e cure The st the st the construction CB is do ononce co	Bond d palt co urrayid purrayid Popu	No Wilde Constraint Straty the Straty the Spare	So we r Investigate
Action Taken :	Chuck the 905 Colly 101 Mole 101	rento te contente contente te	e cud The st m manife CB is de onomice	Bond &	No Wilde Constraint Straty the Straty the Spare	So we r Involtage
Action Taken :	Chuckie the 900 Estig the mate the mate and mate ate :	rento te contente contente te	e cud The st m manife CB is de onomice	Bond d palt co urrayid purrayid Popu	No Wilde Constraint Straty the Straty the Spare	So we r Investigate
Action Taken :	Chuck the 905 Colly 101 Mole 101	hailur Lefeine Shaft & Cyoni Er Time :	e cud The st m manife CB is de onomi ce	Bond d pult co numeral Part Nu Part Nu	No Wilde Contrain 2 Starty Hu So J a Spare	Required PR Number
Action Taken : be only be only Des Completed D Des Cyrix Er Dubling	Chuck the	Lefectre Lefectre Ishaft & C Cyonl & C Time :	Qty.	Part Nu Date	No. Vilau Contrart 2, Scorth Hu So J 2 Spare	Required PR Number End Time
Action Taken : Decomposition of the second	Chude the	Loon	Qty.	Date	Spare	Required PR Number End Time

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

)

Recommendations for Beyond Economic Repair (BER)

PROFORMA


SI. No	Particulars	Details
1	Name of District	TOLLAM
2	Name of Hospital	THQH KAPAKKAL
3	Name of Equipment with Make, Model and Serial Number	Traction unif Brotech Comp. Trace
4	Equipment ID & Barcode	8/160,0221023
5	Date of purchase / Year of manufacture /Installation Date	07 07 2022
6	Warranty details (Yes/No)	NO
7	*AMC/ CAMC Period agreed at the time of purchase	NO
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	20-11-2023
9	Action taken	checked the machine
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Dancaged
11,	Recommendations for repair (required service details)	Motor, beasing, PCB & Shaft fully damaged
12	Cost of spares (specify parts and cost)	24,308/-

22,0001-13 **Asset Value** *Percentage value of the cost of spares with respect to Cost of Purchase/ Asset 14 1101. Value Abstract of Service Report provided by OEM, CYBIX Service Pepopl 15 the OEM/ Authorized Service Provider/ CYRIX (Attached or Not) Traction Motur Reasons for recommending the control board and 16 equipment as BER shaft damaged WILLAM WILSON 17 Name & Signature of CYRIX Authority

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM: Fully damaged. Recommended for Beyond communic repair. Repairing cost is higher than Ruchaer value. Guotatris and email from own attached with this report Signal JC.BM (NHM) ABMO NHM. KOLLAM





MEIBOT TECHNOLOGIES

ARA 44, 2nd Floor, Thyparambil Building, Ammankovil Street Mullackal, Alappuzha Kerala- 688011 Phone no.: 9447038191 Email: info@meibot.com GSTIN: 32BVOPM0744D1ZT, State: 32-Kerala

Estimate

Estimate For

Cyrix Healthcare Pvt Ltd

FIRST FLOOR, 30/641B PETTA JUNCTION, POONITHURA, ERNAKULAM-682038, KERALA INDIA

GSTIN Number: 32AAFCC2499H2ZM

State: 32-Kerala

#	Item name	Item Code	HSN/ SAC	Quantity	Price/ Unit	GS	r Amount
1	Comp Trac piller	386650491 83		1	₹ 6,700.00	₹ 1,206.00 (18.0%)	7 7 906 000
2	Comp Trac control card	386140344 71		1	₹ 5,650.00	₹ 1,017.00 (18.0%)	
3	Comp Trac motor	386760316 79		1	₹ 6,250.00	₹ 1,125.00 (18.0%)	₹ 7,375.00
4	Freight Charges	FREIGHT	48195010	1	₹ 2,000.00	₹ 360.00 (18.0%)	₹ 2,360.00
	Total			3		₹ 3,708.00	₹ 24,308.00

Place of Supply: 32-Kerala Estimate No.: MT/QT/23-24/29 Date: 16-12-2023

Tax type	Taxable amount	Rate	Tax amount	Amounts:	
SGST	₹ 20,600.00	9.0%	₹ 1,854.00	Sub Total	₹ 24,308.00
CGST	₹ 20,600.00	9.0%	₹ 1,854.00	Total	₹ 24,308.00

Estimate Amount In Words:

Twenty Four Thousand Three Hundred and Eight Rupees only

Terms and conditions:

Terms and conditions:

Payment Terms: 100% Advance

The Guarantee/Warranty would not cover: -

a. No Warranty on Rubber, Plastic & Wooden Products / Parts.

b. Any Mechanical damage/breakage.

c. Any damages to vacuum Tube / Valve (if any), Meters.

d. Any damages due to electrical fluctuation.

e. Supply of consumables and accessories.

f. Any Physical damage to the Device due to Intentional act or wilful neglect.

g. Any Equipment's Serial number that has been altered, defaced or removed, or has been modified to alter its functionality or capability without the written permission of Hamb Meditech LLP.

Bank details:

Bank Name: STATE BANK OF INDIA

Bank Account No.: 41310832759

Bank IFSC code: SBIN0003106

Account Holder's Name: Meibot Technologies



LIP SCAN TO PAY

For, MEIBOT TECHNOLOGIES

Authorized Signatory

NEW MACHINE PARICE



MEIBOT TECHNOLOGIES

ARA 44, 2nd Floor, Thyparambil Building, Ammankovil Street Mullackal, Alappuzha Kerala- 688011 Phone no.: 9447038191 Email: info@meibot.com GSTIN: 32BVOPM0744D1ZT, State: 32-Kerala

Estimate

Estimate For

THQH KADAKKAL

Superintendent THQH Kadakkal Kollam Kerala

Estimate No. : MT/QT/23-24/35 Date : 07-02-2024

#	Item name	ltem Code	HSN/ SAC	Quantity	Unit	Price/ Unit	GST	Amount
1	Comp Trac (FEATURES : • Lumbar and Cervical Traction • Model: Comp - Trac • Treatment Time : 1 to 60 min. • Hold Time Set: 1 to 60 Sec Variable. • Rest Time: 1 to 60 Sec Variable. • Mode Set: Inter, Static. • Traction Force: 5 to 45 Kgs. • Main Supply: 230V AC / 50 Hz • Weight: Approx. 10Kgs • Display: LCD. *Manufactured by Biotech.)	04015	90189099	1	Nos	₹ 30,000.00	₹ 3,600.00 (12%)	₹ 33,600.00
	Total			1			₹ 3,600.00	₹ 33,600.00

Meibo† Technologies

Tax type	Taxable amount	Rate	Tax amount		
SGST	₹ 30,000.00	6%	₹ 1,800.00		
CGST	₹ 30,000.00	6%	₹ 1,800.00		

nt	Amounts:						
	Sub Total	₹ 33,600.00					
00	Total	₹ 33,600.00					
.00							

Estimate Amount In Words

Thirty Three Thousand Six Hundred Rupees only

Terms and Conditions

Terms and conditions:

Payment Terms: 100% Advance

The Guarantee/Warranty would not cover: -

a. No Warranty on Rubber, Plastic & Wooden Products / Parts.

b. Any Mechanical damage/breakage.

c. Any damages to vacuum Tube / Valve (if any),Meters.

d. Any damages due to electrical fluctuation.

e. Supply of consumables and accessories.

f. Any Physical damage to the Device due to Intentional act or wilful neglect.

g. Any Equipment's Serial number that has been altered, defaced or removed, or has been modified to alter its functionality or capability without the written permission of Hamb Meditech LLP.

Bank details:

Bank Name : STATE BANK OF INDIA

Bank Account No. : 41310832759

Bank IFSC code : SBIN0003106

Account holder's name : Meibot Technologies



LIPI) SCAN TO PAY

For, : MEIBOT TECHNOLOGIES

Authorized Signatory



Abilal S [_DI Kollam_] <abilalcyrix@gmail.com>

Re: Thqh kadakkal Traction unit (barcode: 0221023, Ticket id: 81160)

1 message

 Muralikrishna Suresh <info@meibot.com>
 9 February 2024 at 11:42

 To: "Abilal S [_DI Kollam_]" <abilalcyrix@gmail.com>
 Cc: MURALIKRISHNA S <muralikrishnaalpy@gmail.com>, "meibottechnologies@gmail.com" <meibottechnologies@gmail.com>

Dear Sir/ Madam,

Kindly be informed that, the quote for new machine is attached with the mail. The present price for the new machine is Rs 33,600.

The old asset value of the machine is Rs 22,000, where as the service cost for fixing the old machine is around Rs 24,308. We suggest you to buy a new machine since the service cost is almost coming close to the new machine. Depending on your approval we can work on either way, so please update for the same at the earliest.

Best Regards,

MURALI KRISHNA. S Business Development Manager MEIBOT TECHNOLOGIES Mob- +91 9074126766 Whatspp: https://wa.me/919074126766

From: Abilal S [_DI Kollam_] <abilalcyrix@gmail.com> Sent: Wednesday, January 3, 2024 12:51:11 PM To: Muralikrishna Suresh <info@meibot.com> Cc: MURALIKRISHNA S <muralikrishnaalpy@gmail.com>; meibottechnologies@gmail.com <meibottechnologies@gmail.com> Subject: Re: Thqh kadakkal Traction unit (barcode: 0221023, Ticket id: 81160)

Please return back the machine

To, Rakesh R Biomedical Engineer c/o DTDC Kadakkal (OF-060), KOLLAM - 691536, Ph : 7012689165 / 7593847161,

On Tue, 19 Dec 2023, 9:17 am Muralikrishna Suresh, <info@meibot.com> wrote:

Dear Sir/ Madam,

Kindly find the attached quotation.

Best Regards,

PARVATHY R SALES COORDINATOR MEIBOT TECHNOLOGIES Mob- +91 9447038191 Whatspp: https://wa.me/919447038191

On Fri, Dec 15, 2023 at 1:16 AM Muralikrishna Suresh <info@meibot.com> wrote: Dear Sir, gies for the late reply. As discussed over the phone, kindly be informed that, after careful inspection of the ine we found that the following things were damaged and needs to be replaced for proper functioning of the

The motor is	damaged	and	needs	to	be	replaced.	
The molor is	uunugoa						

2. The gear shaft assembly is worn out on the side which joins with the motor and needs to be replaced.

3. The board has to be replaced as the machine is not getting engaged and releasing the rope continuously.

When considering the value of the machine and the total cost of the spares changed, it will be more or less the same to the value of the machine. If you still insist on replacing the parts, we are ready to proceed with the service and please issue the PO for the same. If you want us to return the machine, please let us know. We will be eagerly waiting for your reply.

Best Regards,

PARVATHY R SALES COORDINATOR MEIBOT TECHNOLOGIES Mob- +91 9447038191 Whatspp: https://wa.me/919447038191

On Thu, Dec 14, 2023 at 8:45 AM Abilal S [_DI Kollam_] <abilalcyrix@gmail.com> wrote:

Sir, We reported issues with the traction unit's motor bearing and shaft alignment. We sent the machine for service on November 20, 2023. Please provide an update on the current service status. Thgh kadakkal Traction unit (barcode: 0221023, Ticket id: 81160)

Thanks and Regards ABILAL S Biomedical Engineer (District In charge) CYRIX HEALTHCARE Pvt Ltd Kollam- 691001 Ph: +917593847161 Dear Sir/ Madam,

Best Regards,

MURALI KRISHNA. S Business Development Manager MEIBOT TECHNOLOGIES Mob- +91 9074126766 Whatspp: https://wa.me/919074126766

Estimate_MT QT 23-24 35_07_02_24.pdf 110K