

**PROFORMA
RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)
BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)**

| | |
|--|--|
| Name of Hospital: PHC KALLIASSERY | Name of District: KANNUR |
| Name of Equipment: BP APPARATUS | Equipment ID & Barcode: 142163-1340180 |
| Make: ELKO | Model: NA |
| Serial Number: NA | Warranty details: No Warranty |
| Date of purchase/ Year of manufacture/ Installation Date: 17.09.2019 | Present status of the equipment: Fully damaged |
| Date of breakdown: 22.10.2024 | *AMC/ CAMC Period agreed |
| Date of registration of complaint through email/Toll free): Toll free | at the time of purchase: No AMC/CAMC |
| Action taken: Checked the equipment found that equipment is not switching ON. Found that Main Board, Pressure Sensor defective. Need to replace these spares for further checking. | |

Recommendations for repair (required service details): No recommendations

Cost of spares (specify parts and cost): NA


| | |
|---|---------------------|
| #Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: NA | Asset Value: 2200/- |
|---|---------------------|



Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not): Cyrix service Report attached

Reasons for recommending the equipment as BER: Checked the equipment found that equipment is not switching ON. Found that Main Board, Pressure Sensor and Display defective. Need to replace these spares for further checking. Equipment installed on 17.09.2019 aged up to 5 years 2 months. Quotation not submitted since spares are not available in the market. So we recommend the equipment for condemnation.



 Name & Signature of CYRIX Authority with date

Remarks of Junior Consultant (Biomedical) NHM: checked & identified that the machine not working due to main board, pressure sensor, display defective. Aged up to 5 years & above. quotation not available. The service cost economically not feasible. So recommended for BER as per BER Protocol.

| | |
|--------------------------------|--|
| Recommended for BER (Yes/ No): |  08/11/2024 Signature of JC BM (NHM) |
| Date: 08/11/2024 | |

| | |
|---|---|
|  Date: 8/11/24 Seal |  Signature of Superintendent / Medical Officer (i/c) |
|---|---|

*Not mandatory #Based on the period of life and value as per the BER guidelines * Attach Photograph





BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 230617

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

| | |
|---|--|
| <p>Health Facility <u>PHC KALLIASSERY</u></p> <p>Address <u>KALLIASSERY</u> <u>KANNUR</u></p> <p>Ph : <u>9048747300</u></p> | <p>Call Registration Date : <u>22/10/24</u></p> <p>Caller ID : <u>142163</u></p> <p>Date of Visit : <u>23/10/24</u></p> <p>Asset No. : <u>1340180</u></p> <p>EQPT Name : <u>BP Apparatus.</u></p> <p>Manufacture <u>elko</u> Model : <u>na</u></p> <p>S. No. <u>na</u> Dept. <u>Subcentre.</u></p> |
|---|--|

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not switching on

Action Taken : checked the equipment found that equipment is not switching on. Found that main board, pressure sensor defective. need to replace these spares for further checking.

Completed Date : 23/10/24 Time : 2:40 pm Spare Required

Spare Replaced Requested


| Description | Qty. | Part Number | PR Number |
|-------------|------|-------------|-----------|
| 1. | | | |
| 2. | | | |
| 3. | | | |



| Cyrix Engineer | Date | Start Time | End Time |
|----------------|-----------------|----------------|----------------|
| <u>Aswin</u> | <u>23/10/24</u> | <u>2:15 pm</u> | <u>2:40 pm</u> |

Customer Remark Completed Pending

| | |
|---|--|
| <p>Service Engineer Name : <u>Aswin</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>23/10/24</u></p> <p>Contact Number : <u>8301012759</u></p> | <p>Customer Name : <u>[Signature]</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>23/10/24</u></p> <p>Contact Number : <u>9048747300</u></p> <p>Designation : <u>JP HN</u></p> <p>Hospital Seal :</p> |
|---|--|

Dr. Fathima Asheera - M
Assistant Surgeon
Kannur Health Centre
Kalliasery, Kannur - 680002





D. Fatima Akter. M.
 Assistant Surgeon
 Family Health Centre
 Kallassery, Kannur-670502

STOCK REGISTER

Name of Article Subcentre kit

| Date | Particulars | Opening Stock | Arrival Receipt | Total | Issues Sales | Closing Stock | Remarks |
|---------|---|---------------|-------------------|-------|--------------|---------------|---------|
| 16/9/15 | Received from Dd pvc kollassey | | 4 Nos | 4 Nos | | 1 Nos | |
| | Subcentre kit Contents - 29 items | | | | | | |
| 17.9.15 | Main centre | | | | 1 Nos | 3 Nos | |
| " | For Kollassey | } | subcentre kit 110 | 110 | 1 Nos | 2 Nos | |
| " | For Kollakuvayal | | | | 1 Nos | 1 Nos | |
| " | For Innave | | | | 1 Nos | Nil | |
| | Following items | | | | | | |
| 1. | BP Apparatus Digital (Life care - Life care) | | 4 Nos | | | | |
| 2. | Dust Bin - Black (Swing type 10Ltr Life care) | | 4 No | | | | |
| 3. | Dust Bin Red (Swing type 10Ltr - Life care) | | 4 Nos | | | | |
| 4. | Examination Torch. (Led) Life care. | | 4 No | | | | |
| 5. | Dust bin - Yellow (Swing type 10Ltr Life care) | | 4 No | | | | |
| 6. | Proctoscope (Stannus Maharaja Enterprises) | | 4 No | | | | |
| 7. | Gloves Sterile 7 (Surgi care) | | 4 No | | | | |
| 8. | Glucometers - Strip on-cell Plus 1 Strip | | | | | | |
| 9. | Glucometers (on-cell Plus) | | | | | | |
| 10. | Hemo meter Test strip 50 Test Pack Tena HB | | | | | | |



Assistant Surgeon
Family Health Centre
Kalliassey, Kannur-670562

Fathima Ashwara.M
Ashwara