


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	PHC CHITTARIPARAMB
3	Name of Equipment with Make, Model and Serial Number	UPS Make: EMERSON Model: NA SN: NA
4	Equipment ID/ Barcode	1345245 #101040
5	Date of purchase/ Year of manufacture/Installation Date	27-11-2013
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 13-03-2024
9	Action taken	Checked the Equipment found Equipment is not switching ON, Found main board and 3 batteries are defective. Need to Replace these spares for further checking
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	Main Board(1)-1500/- Battery(3)-3300/- Total=4800/-

13	Asset Value	4500/-
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	106.666%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & quotation attached
16	Reasons for recommending the equipment as BER	Checked the machine found machine is not switching ON, Found main board 3 batteries are defective. Need to Replace these spares for further checking Machine is installed on 27-11-2013 aged up to 10 years 3 months. Repairing cost is 106.666% both criteria RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	AVINASH T 


*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


checked & identified that the main board & 3 batteries are defective and aged up to 10 years above. its repairing cost economically not feasible & recommended for BER as per BER protocol.


26/3/24 . Signature of JC BM (NHM)


CONSULTANT BIOMEDICAL
NATIONAL HEALTH MISSION
KANNUR - 670002

Recommending for Condemnation

MEDICAL OFFICER
PRIMARY HEALTH CENTRE
CHITTARIPARAMBA
P. O. KANNOTH-670 650



Date: 20/03/24


Signature of
Superintendent/Medical Officer (i/c)



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : **189381**

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>phe chidtariparamba</u></p> <p>Address <u>Kensar</u></p> <p style="padding-left: 100px;"><u>Kerala</u></p> <p>Ph : <u>7510237592</u></p>	<p>Call Registration Date : <u>13-3-24</u></p> <p>Caller ID : <u>101040</u></p> <p>Date of Visit : <u>14-3-24</u></p> <p>Asset No. : <u>1345245</u></p> <p>EQPT Name : <u>UPS</u></p> <p>Manufacture <u>EMERSON</u> Model : <u>na</u></p> <p>S. No. <u>na</u> Dept. <u>Laboratory</u></p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : nod switching on. Main board & 3 batteries are defective

Action Taken : checked the equipment. Found Equipment is not switching on. Found main board and 3 batteries are defective. Need to replace these spares for further checking

Completed Date : 14-3-24 Time : 11:40 am Spare Required


Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Shankrishnan ppk</u>	<u>14-3-24</u>	<u>10:30 AM</u>	<u>11:40 am</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Shankrishnan ppk</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>14-3-24</u></p> <p>Contact Number : <u>8281188514</u></p>	<p>Customer Name : <u>Shaferase A.R</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>14/3/24</u></p> <p>Contact Number : <u>7510237592</u></p> <p>Designation : <u>KT M-I</u></p> <p>Hospital Seal :</p>
---	--



STOCK BOOK (MEDICINES)

Name of drug Automatic Biochemist Name of drug Analyses

Date	Receipt	Issue	Balance	Date	Receipt	Issue	Balance
	kg./gm./ml.	kg./gm./ml.	kg./gm./ml.		kg./gm./ml.	kg./gm./ml.	kg./gm./ml.
27.11.13			NIL				NIL
24.7.13	Received from KMBCI.						
25.10.13	Accessories:-						
	1. Sine wave UPS				1 NO.		1 NO.
	2. Halogen Lamps				1 No		
	3. Thermal Print Paper				02 No.		
	4. Dust Covers				1 NO.	Issued to	
	5. Variable volume Pipette 10-100ml				1 NO.	Lab	
	6. One fixed volume Pipette 500ml				1 No.		
	Reagents:-						
	1. Urea Mod				500ml x 1 box		
	2. Creatinine				500ml x 1 box		
	3. Billirubin TAD				500ml x 1 box	Issued to	
	4. Cylucose				500ml x 1 box	Lab	
	5. Cholesterol				500ml x 1 box		
	6. Q-C. Abnormal				05ml x 1 box		
	7. Q-C Normal				05ml x 1 box		
	S. 101 AT 1/8.10.13 RBK						
	Grand total Rs: 84,321/-						
	warranty: 26.11.2016 (3 years)						
27.11.13	Issued to Lab technician.						
	Stock entry page no: 104/vol III						



OFFICER
PRIMARY HEALTH
P. CHANNARA
P. CHANNARA 570 250

IT WORLD

COMPUTER SALES & SERVICE

1st Floor,, Malabar Plaza, Near SBT ATM
MATTANUR.

Mob: 9744041752, Office: 8089136301

No. **106**

Date 19/3/20

QUOTATION

To Cyril healthcare Pvt. Ltd Poonithura Erngkulam
682038

Mob No. Email :

Sl. No.	DESCRIPTION	Qty	Unit	Price
	1) main board UPS	1	1	1500/-
	2) Battery	1	3	3300/-
Total				4800/-

For IT WORLD
Signature



Model: GXT MT+ 1K
Input: 208VAC/240VAC, 50/60Hz, 4 BA, 1Φ
Output: 208VAC/240VAC, 50/60Hz, 1Φ
Capacity: 1000VA/800W
16312513091001411
MADE IN CHINA



EMERSON
Network Power



CYRIX BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)
TOLL FREE NO: 1800 - 425-7669
BAR CODE - (8004-890615225)
1345245

Liebert GXT MT+
AC Power



sh
2/4/2024
MEDICAL OFFICER
PRIMARY HEALTH CENTRE
CHITTARIPARAMBA
P. O. KANNOTH-670 650