


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	PALAKKAD
2	Name of Hospital	THQH PATTAMBI
3	Name of Equipment with Make, Model and Serial Number	ULTRASOUND MACHINE MAKE : MINDRAY MODEL : DP9900+ SN : ME 12101837
4	Equipment ID/ Barcode	#98985 0921465
5	Date of purchase/ Year of manufacture/Installation Date	08/11/2011
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	01/03/2024 (toll free)
9	Action taken	Checked the machine found key pad with board damaged. Need to replace key pad with board for further checking
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	RS.542275/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached & OEM end of life letter attached
16	Reasons for recommending the equipment as BER	Checked and found key pad with board faulty. Equipment installed on 08/11/2011. aged up to 12 years 4 months . OEM informed that this model is obsolete. End of life letter issued As per tender clause 5.3.14.2 we recommending the equipment for condemnation
17	Name & Signature of CYRIX Authority	AKHILESH P 

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

OEM informed that this model is obsolete.
End of life letter received.


Consultant (Biomedical Engg)
NHM (Arogyakeralam), Palakkad

Consultant (Biomedical Engg)
NHM (Arogyakeralam), Palakkad


19/03/24
Signature of JC BM (NHM)

Date:




22/03/2024
Dr. Mohammed Abdurahiman U.T.
Signature
Reg. No. 18435
Superintendent/Medical Officer (i/c)
Superintendent
Taluk Head Quarters Hospital, Pattambi



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 188551

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : THOH</p> <p>Address : Pattambi Palakkad</p> <p>Ph : 9744930473</p>	<p>Call Registration Date : 01-03-2024</p> <p>Caller ID : 98985</p> <p>Date of Visit : 02-03-2024</p> <p>Asset No. : 0921465</p> <p>EQPT Name : ultrasound Muenino</p> <p>Manufacture Mindray Model : DP-9900+</p> <p>S. No ME12101837 Dept. Labour ward.</p>
---------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not working

Action Taken : Checked and found that keypad and keypad board defective. Need to Replace keypad and keypad board for further checking of complaint.

Completed Date : 02-03-24 Time : 2:00 p.m. Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
Midhan Rajk	2/3/24	12:15 pm	2:00 pm

Customer Remark Completed Pending

Dr. Mohammed Abdurrahman U.T.
Reg. No. 18455
Superintendent

<p>Service Engineer Name : Midhan rajk</p> <p>Signature : [Signature]</p> <p>Date : 2/3/24</p> <p>Contact Number : 9072522081</p>	<p>Customer Name : Taluk Head Quarters Hospital, Pattambi</p> <p>Signature : [Signature]</p> <p>Date : 2/3/24</p> <p>Contact Number : 9744930473</p> <p>Designation : Srvo</p> <p>Hospital Seal : [Seal]</p>
---------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Mindray Service Department

Technical News

Ref No.: TCS-21124-DP-9900Plus&DP-9900&DP-9600

References:

Applies to overseas offices	
<input type="checkbox"/> Mindray All Overseas Offices	<input checked="" type="checkbox"/> Mindray Germany
<input type="checkbox"/> Mindray DS USA INC.	<input checked="" type="checkbox"/> Mindray UK
<input checked="" type="checkbox"/> Mindray Turkey	<input checked="" type="checkbox"/> Mindray Holland
<input checked="" type="checkbox"/> Mindray Mexico	<input checked="" type="checkbox"/> Mindray India
<input checked="" type="checkbox"/> Mindray Brazil	<input checked="" type="checkbox"/> Mindray Russia
<input checked="" type="checkbox"/> Mindray France	<input checked="" type="checkbox"/> Mindray Egypt
<input checked="" type="checkbox"/> Mindray Italy	<input checked="" type="checkbox"/> Mindray Indonesia
<input checked="" type="checkbox"/> Mindray Colombia	<input checked="" type="checkbox"/> Mindray Spain
<input checked="" type="checkbox"/> Mindray Vietnam	<input checked="" type="checkbox"/> Mindray Thailand
<input checked="" type="checkbox"/> Mindray Venezuela	<input checked="" type="checkbox"/> Mindray Argentina
<input checked="" type="checkbox"/> Mindray Nigeria	<input checked="" type="checkbox"/> Mindray Kenya
<input checked="" type="checkbox"/> Mindray Australia	<input checked="" type="checkbox"/> Mindray South Africa
<input checked="" type="checkbox"/> Mindray Ecuador	<input checked="" type="checkbox"/> Mindray Pilipinas
<input checked="" type="checkbox"/> Mindray Morocco	<input type="checkbox"/> Others
<input checked="" type="checkbox"/> Mindray Poland	
Applies to relevant department	
<input type="checkbox"/> International Marketing Department	<input type="checkbox"/> Others_____
Applies to International TDP	
<input checked="" type="checkbox"/> International TDP	

Originator: _____

Date: _____

Approval: _____

Date: _____

Technical News

Subject: End of Service Notification: DP-9900Plus, DP-9900, DP-9600.

RECORD IDENTIFIER

Ref No.: TCS-21124-DP-9900Plus&DP-9900&DP-9600 Version: 1.0 Author: Andy Jin Date: July 19th, 2021 Model: DP-9900Plus, DP-9900, DP-9600 Comments: N/A.	Relate To: <input type="checkbox"/> Software/Manual Upgrade <input type="checkbox"/> Parts Change <input type="checkbox"/> Appearance <input type="checkbox"/> Stop Production <input checked="" type="checkbox"/> Others
--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

CONTENT

Abstract: End of Service Notification: DP-9900Plus, DP-9900, DP-9600.

To Whom It May Concern,

The following content is for your information only.

Mindray's products DP-9900Plus, DP-9900, DP-9600 (The Digital Ultrasound Diagnostic System, Process Code 9901, 9904, 9905, 9906) has been stopped production over 5 years. Approved by Mindray MIS BMC, Mindray will stop these products' service after June 30th, 2021.

Product code	Product model	End-of-Service date
9901/9904/9905/9906	DP-9900Plus/DP-9900/DP-9600	June 30th, 2021

If you need download information or have any questions, please feel free to contact Mindray regional service engineer or Mindray Service Department (email: service@mindray.com).

Thank you for your kind attention and cooperation.

Sincerely yours,

Mindray Service Department
Mindray Co., Ltd.

Technical News Revision

Subject: End of Service Notification: DP-9900Plus, DP-9900, DP-9600.	Ref No: TCS-21124-DP-9900Plus&DP-9900&DP-9600
--------------------------------------------------------------------------------	------------------------------------------------------------------------

Version	Effective Date	Description
1.0	July 19th, 2021	Document released.

SUB STOCK REGISTER OF INSTRUMENTS B2 LWD

VOL II

(New)

(01) : 28904019220540
(17) : 240630
(10) : 21JRA8029
(21) : MS46847MF96

GTIN :
Exp. Date :
Batch No :
Sr. No :



Tom Coy
[Signature]
SUPERINTENDENT
TALUK HEAD QUARTERS HOSPITAL
PATTAMBI PALAKKAD DT
PIN-679 103



SUB STOCK REGISTER - B
VOL - II - FWD.

Certified that this book contains 240 pages
which is serially numbered from 1 to
240 pages.

Ismit
ng supdt.



GEETHABAI A.
Nursing Superintendent Gr.II
Taluk Head Quarters Hospital
Pattambi, Palakkad Dist. Pin 679303

INSTITUTION STORE VERIFICATION
DONE ON 05-04-2023

ISVO
Sd/- *[Signature]*

INSTITUTION STORE VERIFICATION
DONE ON 30-09-2023

ISVO
Sd/- *[Signature]*



Im Waf
[Signature]
20/03/2024

SUPERINTENDENT
TALUK HEAD QUARTERS HOSPITAL
PATTAMBI PALAKKAD DT
PIN: 679303

INDEX

S. NO	NAME OF ARTICLES	PAGE NO	PAGE NO.
		NEW Book-I	OLD Book-I
1.	IRON COT	5	3
2.	LABOUR COT	6	5
3.	BACK REST IRON	7	7
4.	SCREEN FOLDING	8	9
5.	STOOL WOODEN	9	11
6.	LOCKER WOODEN	10	13
7.	CHAIR E ARM WOODEN	11	15
8.	BENCH E BACK	12	17
9.	BABY COT IRON	13	19
10.	ALAMARRHA WOODEN	14	21
11.	SALINE STAND	15	23
12.	BED PAN(S.S)	16	27
13.	ZINK BUCKET	17	25
14.	KIDNEY TRAY (E.I)	18	29
15.	DRESSING BIN	19	31
16.	STOMACH TUBE	20	33
17.	ARTERY FORCEPS 6" (S.S)	21	35
18.	ARTERY FORCEPS (S.S) 7"	22	36
19.	SCISSORS MAYO 8" (curved)	23	39
20.	UT. DIALATORS	24	41
21.	SCISSORS ANGULAR	25	43
22.	SPECULAM VAGINAL	26	45
23.	CURRETE FLESHING	27	47
24.	A.T. FORCEPS	28	49
25.	CAN IREGATOR S.S	29	51
26.	STERILIZER	30	53
27.	SPONGE HOLDING FORCEPS	31	55
28.	O ₂ CYLINDER E KEY	32	57
29.	PRESSURE GAUGE	33	59
30.	SINUS FORCEPS	34	61
31.	E.I TRAY	35	63
32.	CHAMBER POT	36	65

Inm Coy
 D/Kale
 22/03/2024

SUPERINTENDENT
 TALUK HEAD QUARTERS HOSPITAL
 PATTAMBI PALAKKAD DT
 PATTAMBI PIN-676 03



147.	MULTI PARA MONITOR	179
148	MONITOR STAND	181.
149.	DELIVERY SET.	122
150	B.P. APPARATUS (MERCURY FREE)	124
151	BP. HANDLE. NO. 4.	128.
152	MYO SCISSORS, 6'	134
153.	EPISIOTOMY SCISSORS.	136
154	STRAIGHT SCISSORS.	138
155	TOOTHED FORCEPS.	132
156	MOSQUITO ARTERY.	140
157.	INJECTION TRAY. 2x3	142
158	FIRE EXTINGUISHER.	147.
159.	PULSE OXYMETER REUSABLE SENSOR.	183.
160	NURSING TRAY.	162
161	SANITISER STAND.	160
162	DIGITAL BP APPARATUS	187
163	Oxygen concentrator	189
164	Airtel Wifi dongle	188
165	Ultrasonic cleaner	192
166	Ultrasound Scanning Machine CUB	174
167	Ventilator portable	186
168	Oxygen Hood	126
169	Monkey spanner	190
170	Portable Ultrasound Machine	176
171	O ₂ Flowmeter & humidifier For Central O ₂ Plant and Probes	193
172	Allis forceps 8"	206

Imu Coy
Dikabon
22/03/2020

SUPERINTENDENT
TALUK HEAD QUARTERS HOSPITAL
PATTAMBI PALAKKAD DT
PIN: 675 03



ULTRASOUND SCANNING MACHINE

174 and UPS

		Rfd	Issued	Bal	Unservicable	Conserved
3/10/2021	To in form NRHM Register C1 Page 37 (Rfd on date 30/11/2010)	1		1		
3/10/2021	UPS To in form NRHS C1 38 (Rfd on date 17/7/2018)	1		1		

Trav. exp
OK
22/03/2021

SUPERINTENDENT
TALUK HEAD QUARTERS HOSPITAL,
PATTAMBI PALAKKAD DT
PIN: 679303





mindray

[Handwritten Signature]
02/03/2024

SUPERINTENDENT
TALUK HEAD QUARTERS HOSPITAL
PATTAMBI PALAKKAD DT
PIN:579303



Sterifog

CYRIX
HEALTHCARE PVT LTD

BIOMEDICAL EQUIPMENT MAINTENANCE
PROGRAMME (BEMP)



TOLL FREE NO: 1800 - 425-7669

BAR CODE - (8004-890615225)
0921465



Okkar
23/08/2024
SUPERINTENDENT
TALUK HEAD QUARTERS HOSPITAL
PATTAMBI PALAKKAD DT
PIN: 679303

CYRIX
HEALTHCARE PVT LTD

CN: THPT002

S.N: ME12101837

PRO : USG MACHINE

ID : 0921465

CAL ON : 17-08-2023

CAL DUE : 16-08-2024



ISO 9001:2008 Certified Co. Ph: 974455073