REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI.	Particulars	Details
1	Name of District	Wayanad
2	Name of Hospital	DH Mananthavady
3	Name of Equipment with Make, Model and Serial Number	Equipment-CR Printer Make-Carestream Model- Dry view 5850 laser imager Sn-N/a
4	Equipment ID/ Barcode	1210127//TICKET 120568
5	Date of purchase/ Year of manufacture/Installation Date	02/12/2011
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registrationof complaint through email/ Toll free)	02/07/2024/Toll free
9	Action taken	Checked and found Optics unit, Drum and pickup unit defective. Need to replace the above spare. Enquired oem for quotation
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
		No recommendation
11	Recommendations for repair (required service details)	
		N/a
12	Cost of spares (specify parts and cost)	

13	Asset Value	N/A
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	N/A
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	EOL Letter from OEM (Carestream) Cyrix service report
16	Reasons for recommending the equipment as BER	Checked and found Optics unit, Drum and pickup unit defective. Equipment installed on 02/12/2011, aged up to 12 years. OEM informed that this machine is obsolete model and spare parts not available. End of life letter issued by OEM. As per tender clause 5.3.14.2 we recommend the machine for condemnation
17	Name & Signature of CYRIX Authority	NIYAS HADI AP

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Optime mit, Duiting mit, dum an diffultive,

Mechine is a brother model and sperens an mit
Mechine is a brother model and sperens an mit
Consultant

Bio-Madical Engineer

Signature of at 60 BM (NHM) Mission

(Arogyakeralam)

Wavanad-673122

PH: 04831 240 261

Date: 19.07.24

SUPERINTENDENT
Signature of DISTRICT LICEPITAL
Superintende MANANTHAN



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

226012

HEALTH	HCAREPVI	LTD	2200	13		
ISO 13485 : 2012 & ISO 9001-2008 CEI						
Service Report 30/64 1 B, Petta Junction Ph: 98472 99500 Website: w	n, Poonithura, Kol vww.cyrix.com	:hi - 682 038, Kei E-mail : bemp.kii	raia Bcyrix.in			
	Call Regist	ration Date : .	02-0	7-2024		
Health Facility DH		12056		The second secon		
Address Manantha vady	Date of Vis	Date of Visit: 04 - 07 - 202 - 4				
Mayanad	Asset No. :					
		e: < R 1				
Ph: 9947918269	··· Manufactur	e Carastr	<i>⊞a</i> Model :	Dry Viau St Lase 2 my		
	S. No	<i>(1A</i>	ept. Rod	66097		
Service Classification : Breakdown Call	PMS [Calibratio	n Cust.	Training 🗌		
F 6	22 22		1-1-0-	Ast .		
Problem Identified : Error - 6	0 1 0ρτ	ics cau	brevon	Vedled		
Charles n						
Action Taken: CDCCACO II	rachine	tound	d opti	cs civit.		
Drum and Pickae	vactine	, tour	d Opti	ed to		
Drum and Pickup	nachine unit di socres	, tour	d Opti	es upit,		
Drum and Pickup replace The above	nachine unit di spares	, tource efective	d Opti e. Na	cs upit,		
replaces The above	spares					
replaces The above	spares			cs cryit,		
replaces The above	spares					
Completed Date: 0.4/.7/2.4 Time:	spares		Spare			
Completed Date: O.4.7./2.4Time: Spare Replaced Description	Spares :12308	<i>m</i>	Spare	Required		
Completed Date: O.4	Spares :12308	<i>m</i>	Spare	Required		
Completed Date: O.4	Spares :12308	<i>m</i>	Spare	Required		
Completed Date: O.4	Spares :12308	<i>m</i>	Spare	Required		
Completed Date: O.A. J. J. L. Time: Spare Replaced Requested Description 1. 2. Cyrix Engineer	Sparal :	Part Nur	Spare nber Start Time	PR Number End Time		
Completed Date: O.4 (7/2.4 Time: Spare Replaced Description Description	Sparal :	Part Nur	Spare nber Start Time	PR Number End Time		
Completed Date: O.A	Sparal :	Part Nur	Spare nber Start Time	PR Number End Time		
Completed Date: O.4.7/2.4 Time: Spare Replaced Requested Description Cyrix Engineer Customer Remark	Sparal :l.22.eg	Part Nur	Spare mber Start Time	PR Number End Time		
Completed Date: O.4	Sparal :l.22.eg	Part Nur	Spare mber Start Time	PR Number End Time		
Completed Date : O. A. J. J. L. Time : Spare Replaced Requested Description 1. 2. 3. Cyrix Engineer Customer Remark Customer Remark	Completed	Part Nur Date 04/07/24	Spare mber Start Time / 0.30 am Pendi	PR Number End Time		
Completed Date : O.4 7 2.4 Time : Spare Replaced Requested Description 1. 2. 3. Cyrix Engineer Customer Remark Customer Remark	Completed	Part Nur Date 04/07/24	Spare Start Time / 0.30 am Pendin	Required PR Number End Time 12-3-00		
Completed Date : O.4 7 2.4 Time : Spare Replaced Requested Description 1. 2. 3. Cyrix Engineer Customer Remark Customer Remark	Completed Custome Signature Date:	Part Nur Date 04/07/24	Spare The start Time 10.30 am Pendin	Required PR Number End Time / 2 - 3 - 0 - 0		
Completed Date: O.4.7/2.4 Time: Spare Replaced Requested Description 1. 2. 3. Cyrix Engineer Customer Remark Customer Remark Customer Remark	Completed Custome Signature Date: Contact Designa	Part Nur Date 04/07/24 Part Num Part Num	Spare The start Time 10.30 am Pendin	PR Number End Time		



Service Discontinuance Notification for DRYVIEW 5800 & 5850 Laser Imagers

December 2022

Dear Carestream Customer:

Effective December 31, 2023, Carestream will discontinue service and support for the DRYVIEW 5800 Laser Imager and DRYVIEW 5850 Laser Imager. Service parts will be provided "as available" after December 31, 2023.

We invite you to consider the DRYVIEW 5700 Laser Imager or DRYVIEW 5950 Laser Imager for your future medical image printing needs. Information regarding the DRYVIEW 5700 & 5950 Laser Imagers are listed below. Both laser imagers support simplified film packaging allowing easy and flexible changing of film. Please ensure to consume your existing DRYVIEW Laser Imaging Film with your current DRYVIEW 5800 & 5850 Laser Imagers before switching to a newer laser imager model.

DRYVIEW 5700 Laser Imager



Low- Mid Volume Printing: 40 to 70 films/hour One film size supported on line Standard resolution - 325 pixels/inch Easy to load film packaging (cartridges) Tabletop

DRYVIEW 5950 Laser Imager



Mid - High Volume Printing: 70 to 120 films/hour Two film sizes supported on line High resolution - 508 pixels/inch Easy to load film packaging (cartridges) Tabletop Supports printing digital mammography images

For questions regarding this notification or for pricing information on the DRYVIEW 5700 Laser Imager and DRYVIEW 5950 Laser Imager, please contact your local sales representative or authorized Carestream distributor. Pricing incentives may be available to those who qualify.

Sincerely,

Amal Baby

Field Engineer Carestream Health, Inc.

+91 9605569876

amal.baby@carestream.com



Fwd: Service discontinuation letter of DH Mananthavady

1 message

Arjun krishnadas <karjuncyrix@gmail.com> To: Niyas Hadi AP <niyascyrix@gmail.com> Mon, 15 Jul 2024 at 9:01 am

Thanks & Regards Arjun Krishnadas TV Sr.Service Engineer Cyrix Health Care Pvt Ltd.

----- Forwarded message ------

From: Amal Baby <amal.baby@carestream.com>

Date: Fri, 12 Jul 2024 at 11:46 PM

Subject: Service discontinuation letter of DH Mananthavady

To: Basil James <basil@cyrix.in>

Cc: Jinto Joseph < jinto.joseph@carestream.com>, karjuncyrix@gmail.com < karjuncyrix@gmail.com>

Dear Basil

Hope you are doing good.

Regarding the querry about the service dicontinuation letter of DV5850 of the DH Mananthavady we hereby attaching the same letter here within.

Have good day.

Thanks and Regards

Amal Baby

Carestream Health India Pvt Ltd.

Kochi

Ph: 09605569876

amal.baby@carestream.com

Carestream

www.carestream.com

Carestream Health India Pvt. Ltd.| 801 Star Hub I Building No 2. Sahar, Andheri(East) I Mumbai 400059.

Follow us on EverythingRadBlog Instagram Linkedin Facebook Twitter YouTube

Prefer to log service calls via Web?

To start logging calls via the web please visit and bookmark:

https://www.carestream.com/en/in/services-and-support/servicerequest-india

P Please consider the environment before printing this email

HUSPITAL DEVELOPMENT COMMITTEE DISTRICT HOSPITAL MANANTHAVADY

Invoice No Date	Received From / Issued To	Received		Balance	In
2/12/2011	Explis Engineering to Hel				\vdash
5/005/11-12	39, 2 Main soud Ro pen	am 1		ME 1	+
	Chennai. PIN 600026	1			1
	Égyer	•			T
	them and By Docale	Daice	e Rg 1032	1090,00	T
	Kerala Medical Service coo	paado	- 10 52	7777	\top
	TVM.	LAN			
	Customs duty paind	as por B.E	NO M6/11	20036948	10
	de 05 - 10-2011				
	The 6 Challan A	10 200226	POES Nede	24-10-	on
	Actual 10.4197250/0				
		Lilly A	when &	÷	
				co greene	
			8	3/1/20/2	
-					
	Poshiba Asection Ripes				
	with epir, coach, gant	04 1		Ind	4
	Scannie, Keyboard Me 9 rable; Correston Film Poin	tuse.		. 1	LL.
	9 rable; constantil Poin	fin		puwer	a
				2/10/10	w
	C.T. + PAT tube chow	العا	70		١
	Du 12/04/2023.		(n)	1	
	Ented in bode noz	2.		Mer	
			2018	wo	
			W. Jun	326	1
			M Or		+
			10		+
					+
. 0.0				+	+
mewom		159			+
2000 ut	Pial	57159	ar:		+
MIN	sic.	SUP ERIN ENDE	AL	-	+
Solly	D COITAL MANAGED	ISTAND, MANANT	AVADY		+
Mo	WA WA	ANAD, III	-		1





Jun coly ky

WAYANAD, MANANTHAN, OT