


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	MALAPPURAM
2	Name of Hospital	THQH TIRURANGADI
3	Name of Equipment with Make, Model and Serial Number	EQUIPMENT: HEAMATOLOGY ANALYSER Make: MINDRAY Model:BC 3600 Serial Number :3A0001635
4	Equipment ID/ Barcode	TICKET ID: 25219 BARCODE NO :1021860
5	Date of purchase/ Year of manufacture/Installation Date	Installation date : 21/04/2014
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of Purchase	NO AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	22/09/2022
9	Action taken	Checked the machine and initially found the volumetric board missing from the equipment. We arranged for the volumetric board and checked the working condition of the equipment found 3 way valve, main board defective. These parts need to be replaced to further check the working condition of the equipment.
10	Present status of the equipment (Fully damaged / partially damaged)	NA
11	Recommendations for repair(required service details)	No recommendation
12	Cost of spares (specify parts and cost)	MAIN BOARD : 100000/- THREE WAY VALVE 1 NUMBER : 8900/- TOTAL : 128502/-

13	Asset Value	144000/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	89%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX(Attached or Not)	CYRIX Service Report & OEM Quotation
16	Reasons for recommending the equipments as BER	Checked the machine and initially found the volumetric board missing from the equipment. We arranged for the volumetric board and checked the working condition of the equipment found 3way valve, main board defective. These parts need to be replaced to further check the working condition of the equipment. Equipment installed on 21-04-2014. Aged up to 10 Years and 07 months. Repairing cost is 89% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	GOKUL KT 

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Verified with the damage of main board & 3 way valve. Need to replace the same. Beyond economic repair.




17/06/24

Signature of JC BM (NHM)
Jr. Consultant Biomedical Engineer
NHM Malappuram



Date: 20/8/24

SUPERINTENDENT
TALUK HEAD QUARTERS HOSPITAL
KUMBALANGI, MALAPPUARAM

Signature of
Superintendent/Medical Officer (I/c)



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 184551

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>THQH</u></p> <p>Address <u>TIRURANGADI</u> <u>MALAPPURAM</u></p> <p>Ph :</p>	<p>Call Registration Date : <u>22/09/2022</u></p> <p>Caller ID : <u>25219</u></p> <p>Date of Visit : <u>5/8/24</u></p> <p>Asset No. : <u>1021860</u></p> <p>EQPT Name : <u>Haematology Analyser</u></p> <p>Manufacture <u>mindray</u> Model : <u>BC 3600</u></p> <p>S. No. <u>3A0001635</u> Dept. <u>LMB</u></p>
--	--

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Result Variation

Action Taken : checked the machine and initially found the volumetric board missing from the equipment. we arranged for the volumetric board and checked the working condition of the equipment found 3 way valve main Board defective. These parts need to be replaced to further check the working condition of the

Completed Date : 5/8/24 Time : 1:00PM Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>GOKUL K T</u>	<u>5/8/24</u>	<u>10:35am</u>	<u>1:00PM</u>

Customer Remark Completed Pending



SUPERINTENDENT
TIRURANGADI MALAPPURAM

<p>Service Engineer Name : <u>GOKUL K T</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>5/8/24</u></p> <p>Contact Number : <u>9809314280</u></p>	<p>Customer Name : <u>Vidya Anand. S V</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>[Date]</u></p> <p>Contact Number : <u>[Number]</u></p> <p>Designation : <u>SLT</u></p> <p>Hospital Seal : <u>58-249446558/30</u></p>
---	--

Quotation


Golden Harvest Industrie(Spares) Admin Off: 1st Floor, New No. 83, Old No. 33, New Boag Road, Opp. Khannammampet Corp .School, T. Nagar, Chennai - 600017. Ph: 9282111674 Regd. Off: 8/c, Jawaharlal Nehru Rd, Ekkattuthangal Chennai - 97. DL No. 4940/MIII/20-B, 4821/MIII/21-B GST Provisional ID : 33ACVPG7238F2ZE ARN NO: AA330217006488C GSTIN/UIN: 33ACVPG7238F2ZE State Name : , Code :	Invoice No. GHI/24-25/Q08081	Dated 08-Aug-24
Buyer (Bill to) Cyrix Healthcare pvt ltd. Ernakulam State Name : Kerala, Code : 32	Delivery Note: Supplier's Ref. GHI/24-25/Q08081	Mode/Terms of Payment 100% Advance
	Buyer's Order No. By Phone	Other Reference GST
	Despatch Document No. DIRECT	Dated 08-Aug-24
	Despatched through Professional	Delivery Note Date
	Terms of Delivery At Your Place	

Sl No.	Description of Goods	HSN/ SAC	Qty	Rate	per	Disc. %	Amount
1	Mindray BC-3600 Main board	90279090	1	₹ 1,00,000.00	Nos		₹ 1,00,000.00
2	Mindray 3way valve	90279090	1	₹ 8,900.00	Nos		₹ 8,900.00
	IGST 18%						₹ 19,602.00
	Total		2 Nos				₹ 1,28,502.00

Amount Chargeable(in words): E. & O.E
Indian Rupees One Lakh TwentyEight Thousand Five Hundred Two Only

HSN/SAC	Taxable Value	Integrated Tax		Total Tax Amount
		Rate	Amount	
90279090	1,08,900	18%	19,602	19,602
Total	1,08,900		19,602	19,602

Tax Amount (in words) : **Indian Rupees Nineteen Thousand Six Hundred Two Only**

Company's VAT TIN : 33840902845 Company's CST No. : 717439 Company's Service Tax No. : ACVPG7238FSD002 Company's PAN : ACVPG7238F	Company Bank Details Bank Name : HDFC Bank [12162000001380] A/C No : 12162000001380 Branch & IFS Code : Padma Complex & HDFC0001216 for Golden Harvest Industrie(Spares) <div style="text-align: right;">  Authorised Signatory </div>
--	--

Declaration
 We declare that this invoice shows the actual price of the goods described and that all particulars are true and correct.

1021860 Hematology analyser Need price quotation for spare

3 messages

Wed, 7 Aug, 2024 at 6:45 pm

Gokul K T <gokulcyrix@gmail.com>

To: tnithyaghi@gmail.com

Cc: Ganesh navaneethakrishnan <seguganesan@gmail.com>, Anish Bala <anishbala19@gmail.com>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>

Dear sir,

There is a complaint reported from THQH TIRURANGADI , MALAPPURAM Regarding the complaint with HEAMATOLOGY .

MAKE : MINDRAY

MODEL: BC 3600

BARCOD:1021860

Need quotation for Below mentioned spare parts .

Main board

3 WAY VALVE (1numbers)

Required these spare quotation.Do the needful as soon as possible

GOKUL KT

CYRIX HEALTHACARE

DISTRICT INCHARGE

MALAPPURAM

9809314280

Gokul K T <gokulcyrix@gmail.com>

To: tnithyaghi@gmail.com

Thu, 8 Aug, 2024 at 3:02 pm

Cc: Ganesh navaneethakrishnan <seguganesan@gmail.com>, Anish Bala <anishbala19@gmail.com>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>

Reminder

[Quoted text hidden]

Priya Tamizharasan GHI <tnithyaghi@gmail.com>

To: Gokul K T <gokulcyrix@gmail.com>

Thu, 8 Aug, 2024 at 3:26 pm

Cc: Ganesh navaneethakrishnan <seguganesan@gmail.com>, Anish Bala <anishbala19@gmail.com>, DM Sarang-KLBEMP <dm1.klbemp@cyrix.in>

Dear Sir,

Kindly find the attachment.

Thanks with Regards



T. Nithyapriya
Service Coordinator
Golden Harvest Industries



SUPERINTENDENT
KOLUK HEADQUARTERS HOSPITAL
TRURANGADI, MALAPPURAM - 673 007



Name of Article / Medicine : **HAEMATOLOGY ANALYSER ✓**

Date	From whom received / To whom issued	Receipt	Issue	Balance	B.No. Exp. Date	Cost	Mfg.	Sign.	Remarks
21-4-14	Received from Mr Shri (MINDRAY BC 3600)	1	—	1					
		with	UPS.						
"	Installed on	21-4-14							
16.9.19	Haematology analyser spare volumetric Board.								
18.7.22	Not working - complaint registered but yet repaired by								
									↓ Required for maintenance



SUPERINTENDENT
SRUK HEADQUARTERS HOSPITAL
TIRUMALA, MALAPPRATHA 515 015