


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	STATE PUBLIC HEALTH LABORATORY
3	Name of Equipment with Make, Model and Serial Number	Equipment Name : Tissue Floatation Bath Make : Labline Model : KTB 02 Serial No : 17K575
4	Equipment ID/ Barcode	112958/0111306
5	Date of purchase/ Year of manufacture/Installation Date	17/09/2018
6	Warranty details (Yes/No)	No Warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No CAMC/AMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	24/05/2024 (Toll free)
9	Action taken	Checked and found heater coil, Thermostat, Hear resistance wires, switch, AC code wire, indicator and glass wool defective. Need to replace these spares for further checking and working condition of the equipment.
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NOT RECOMMENDING FOR REPAIR
12	Cost of spares (specify parts and cost)	Heater coil spring type - 3147/- Thermostat - 1158/- Heat resistant wires - 1098/- On/Off toggle switch - 188/- AC cord wire - 589/- Indicator - 132/- Glass Wool - 1487/- TOTAL - 7800/-

13	Asset Value	12000/-
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	65%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT AND VENDOR QUOTATION ATTACHED
16	Reasons for recommending the equipment as BER	Checked and found heater coil, Thermostat, Heater resistance wires, switch, AC code wire, indicator and glass wool defective. The unit was installed on 17/09/2018. And covered up to 5+ years. The repair cost is 65%. As per the tender clause 5.3.14.1 both criteria met. So recommending the unit for condemnation.
17	Name & Signature of CYRIX Authority	MOHAMMAD SIYAD 

*Not mandatory


#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


Heater coil, Thermostat etc almost may major parts are defective and repair cost is high. ∴ can be BER as per tender conditions.

MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram


21-7-2024
Signature of JC BM (NHM)

Date:




Superintendent/Medical Officer (i/c)
Thiruvananthapuram



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 218535

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : <u>SPH Thiruvananthapuram</u></p> <p>Address : <u>Venchiyoor</u> <u>Thiruvananthapuram, Kerala</u></p> <p>Ph : <u>9746292134</u></p>	<p>Call Registration Date : <u>24-5-24</u></p> <p>Caller ID : <u>112958</u></p> <p>Date of Visit : <u>4/6/24</u></p> <p>Asset No. : <u>0111306</u></p> <p>EQPT Name : <u>Tissue Flotation Bath</u></p> <p>Manufacture : <u>Local</u> Model : <u>KTB.02</u></p> <p>S. No. : <u>NA</u> Dept. <u>Histopathology</u></p>
---	--

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Machine not working.

Action Taken : Found rheostat, local resistant wiring, switch cord coil are damaged. Need to replace these parts to check the further working condition of the machine.

Completed Date : 04/06/24 Time : 11:30 AM Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.	NA	NA	NA	NA
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Souya Sudheep</u>	<u>04/06/24</u>	<u>10:15 AM</u>	<u>11:30 AM</u>

Customer Remark Completed Pending


Machine not working.

<p>Service Engineer Name : <u>Souya Sudheep</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>4/6/24</u></p> <p>Contact Number : <u>9746292134</u></p>	<p>Customer Name : <u>State Public Health & Family Welfare Officer</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>4/6/2024</u></p> <p>Contact Number : <u>M.O in charge</u></p> <p>Designation : <u>Histopathology</u></p> <p>Hospital Seal : <u>9746292134</u></p>
---	---

STOCK REGISTER OF

Name of Article..... TISSUE FLOATATION BATH

Date	No. and Date of voucher or invoice	From whom received or to whom issued	Receipt	Issued	Balance after each transaction	Antiquity of purchase	Remarks
		Brought forward					
		Date of Receiving	17/7/11	received	1	✓	
		Date of Installation	"	"			
		Model					
		Serial No:	17K575				
		Unique ID No:	- 0111306		cost	0111306	
		Working status					
		Manufacturer	LAB LINE				
		Service contact details	-				
		Warranty					
		Checked by					





9744473043, 9744473243

cloud99biotech@gmail.com

1 KMC/XIII-1333
Room No: 22,
CSI Golden Jubilee Complex
Baker Hill
Shastri Road
Kottayam

CLOUD99 BIOTECH

GSTIN: 32AMWPT5633Q1ZD

State: 32 - Kerala

MSME NO.: UDYAM-KL-07-0030714

Estimate

Estimate For:

KASHYAP

1ST FLOOR 30/641B CYRIX HEALTHCARE PVT LTD
KOCHI DHANUSHKODI ROAD POONITHURA

Contact No.: 7593847134

GSTIN Number: 32AAFCC2499H2ZM

State: 32-Kerala

Estimate No.: C99B-QTN-34

Date: 20/07/2024

Place of Supply: 32-Kerala

#	Item name	HSN/ SAC	Quantity	Unit	Price/ Unit	GST	Amount
1	HEATER COIL SPRING TYPE (HEATER COIL SPRING TYPE)	8419	1	Nos	₹ 2,809.82	₹ 337.18 (12%)	₹ 3,147.00
2	THERMOSTAT (THERMOSTAT)	903210	1	-	₹ 1,033.93	₹ 124.07 (12%)	₹ 1,158.00
3	HEAT RESISTANT WIRES (HEAT RESISTANT WIRES)	8544	1	Mtr	₹ 930.51	₹ 167.49 (18%)	₹ 1,098.00
4	ON/OFF TOGGLE SWITCH (ON/OFF SWITCH)	8536	1	Nos	₹ 160.00	₹ 28.80 (18%)	₹ 188.80
5	AC CODE WIRE	8544	1	Nos	₹ 499.15	₹ 89.85 (18%)	₹ 589.00
6	INDICATOR (INDICATOR)	1514	1	Nos	₹ 111.86	₹ 20.14 (18%)	₹ 132.00
7	GLASS WOOL (GLASS WOOL)	701919	1	-	₹ 1,260.17	₹ 226.83 (18%)	₹ 1,487.00
Total			7			₹ 994.36	₹ 7,799.80

Sub Total	₹ 6,805.44
SGST@6%	₹ 230.63
CGST@6%	₹ 230.63
SGST@9%	₹ 266.56
CGST@9%	₹ 266.56
Round off	₹ 0.20
Total	₹ 7,800.00

Pay To:

Bank Name : UNION BANK OF INDIA, KOTTAYAM

Bank Account No. : 361201010035646

Bank IFSC code : UBIN0536121

Account holder's name : CLOUD99 BIOTECH

Description

STATE PUBLIC HEALTH LABORATORY
EQUIPMENT: TISSUE FLOATATION BATH
MODEL: KTB 02
BARCODE: 0111306
TIKET ID: 1129858

Estimate Amount In Words

Seven Thousand Eight Hundred Rupees only

Terms And Conditions

Thanks for doing business with us!

For: CLOUD99 BIOTECH

**Authorized Signatory**



REGARDING QUOTATION FOR TISSUE FLOATATION MACHINE (112958-0111306)

messages

asyep P V <kasyepcyrix@gmail.com>
: CLOUD 99 <cloud99biotech@gmail.com>

Sat, 20 Jul 2024 at 9:16 p

Dear Sir/Madam,

This mail is to enquire about the quotation for tissue floatation Bath at SPHL Thiruvananthapuram details;

Hospital : State Public health Laboratory

Equipment : Tissue floatation Bath

Model : KTB 02

Barcode : 0111306

Ticket ID : 112958

Quotation Required for;

1. Heater coil
2. Thermostat
3. Heat resistance wires
4. Indicator
5. Glass wool
6. AC cord wire

KASYEP PV

District Incharge, Trivandrum

CYRIX HEALTHCARE Pvt.Ltd

KLBEMP

Ph : +91 7593847134

kasyepcyrix@gmail.com

CLOUD 99 <cloud99biotech@gmail.com>
: Kasyep P V <kasyepcyrix@gmail.com>

Sat, 20 Jul 2024 at 10:04 p

[Quoted text hidden]