

PROFORMA

**RECOMMENDATION FOR BEYOND ECONOMIC REPAIR (RBER)
BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)**

Name of Hospital: PHC KANICHAR	Name of District: KANNUR
Name of Equipment: REFRIGERATOR	Equipment ID & Barcode: #132830- 1344359
Make: GODREJ	Model: N/A
Serial Number: N/A	Warranty details: NO Warranty
Date of purchase/ Year of manufacture/ Installation Date: In ticket master installation date is 01-04-2007 As per the stock book Installation date is 09.01.2006 (Stock book copy attached for reference)	Present status of the equipment: Fully damaged
Date of breakdown: 02.09.2024 Date of registration of complaint through email/ Toll free: Toll free	*AMC/CAMC Period agreed at the time of purchase: NO AMC/ CAMC
Action taken: Checked the Equipment found Equipment is not switching ON, found that compressor, filter. Cooling coil, fan motor defective. Enquired for quotation	

Recommendations for repair (required service details): No recommendations

Cost of spares (specify parts and cost): compressor-6200/-
Cooling coil-2000/-
Fan Motor -1000/-
Gas charging -1200/-
Filter- 680/-
Total- 11080/-

Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value: 61.68% Asset Value: 17961/-

Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not): Cyrix Service report & Quotation attached

Reasons for recommending the equipment as BER: Checked the Equipment found Equipment is not switching ON, found that compressor, filter. Cooling coil, fan motor defective. Enquired for quotation. In software Equipment installed on 01.04.2007. As per the stock book installation date is 09.01.2006 aged up to 18 years 8 months. Repairing cost is 61.68% Both criteria RBER met. As per tender clause 5.3.14.1 we recommend the equipment for condemnation.


Name & Signature of CYRIX Authority with date
Avinash

Remarks of Junior Consultant (Biomedical) NHM: checked and identified that machine not switching ON, found the compressor, filter cooling coil, fan motor defective - machine aged up to 18 years & above. The repairing cost economically not feasible. So recommended for BER as per BER Protocol.

Recommended for BER (Yes/ No):
Date: 23/09/24.

Signature of JC BM (NHM)
[Signature]
23/09/24

Date: _____
Signature of Superintendent / Medical Officer (i/c)



Photograph
P.O. കൊടുങ്ങല്ലൂർ - 670079

*Not mandatory

Based on the period of life and value as per the BER guidelines



one time service required for Refrigerator 1344359#132830@PHC KANICHAR

2 messages

avinash t <avinashtcyrix@gmail.com>
To: ecotonicsolutions@gmail.com

Wed, 4 Sept, 2024 at 8:02 pm

Dear sir,
Please provide service for Refrigerator at PHC KANICHAR

Thanks & Regards

Thanks & Regards

Avinash T
District charge, kannur
bemp kerala
mobile: +91 6364064948
E mail: avinashtcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B | Petta | Punithura | Kochi | Kerala- 682038
www.cyrixhealthcare.com

ECOTONIC AUTOMATION SOLUTIONS <ecotonicsolutions@gmail.com>
To: avinash t <avinashtcyrix@gmail.com>

Fri, 20 Sept, 2024 at 8:06 pm

Hi Avinash
Your quotation for above mentioned machine is attached.
PFA
Regards,
Ecotonic Automation Solutions
www.ecotonics.in


[Quoted text hidden]

CYRIX BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)
HEALTHCARE SYSTEMS

TOLL FREE NO: 1800 - 425-7669



BAR CODE - (8004-890615225)
1344359



Jibesh
 Jibesh V. Alex
 pharmacist

J. Alex

മേഡിക്കൽ ഓഫീസർ
 പ്രാഥമിക ആരോഗ്യ കേന്ദ്രം
 കുതിപ്പാർ, P.O. കൊളക്കാട് - 670876