

105

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Kottayam
2	Name of Hospital	PHC Pallackathodu
3	Name of Equipment with Make, Model and Serial Number	Name: B P Apparatus (LED) Make: Diamond Model: Deluxe Sno: 00964
4	Equipment ID & Barcode	0542831
5	Date of purchase / Year of manufacture / Installation Date	25/11/2020
6	Warranty details (Yes/No)	No
7	*AMC/ CAMC Period agreed at the time of purchase	No
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	16/10/2023
9	Action taken	Checked card found equipment's functioning are not proper.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	checked card found repairing of the equipment is economically not feasible. Hence recommending the equipment as RBER
12	Cost of spares (specify parts and cost)	Display - 400 Battery case - 450 Internal PCB - 1000 <u>1850/-</u>

Arvikuzhy-686 503
PHC Pallikathodu
Medical Officer in Charge

Signature of
Superintendent / Medical Officer in Charge

18/10/23

Seal 18/10/23



Date

Signature of JC BM (NHM)

5/11/23

Asset value - 1875 (98.66%)
Cost of spare - 1850
Life period - 2 years or 11 months
Repeated complaints and error reading (LEAD)

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

* Attach Photograph

*Not mandatory #Based on the period of life and value as per the BFR guidelines

13	Asset Value	1875/-
14	#Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	98.66%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	diagnostic service report recommending the equipment as R.B.F.R.
16	Reasons for recommending the equipment as BFR	The equipment showing repeated complaint could repairing the equipment is economically not feasible. Hence recommending the equipment as BFR
17	Name & Signature of CYRIX Authority	Saritha Sivan



**BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAMME
UNDER
NATIONAL HEALTH MISSION**



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX
HEALTHCARE PVT LTD

No. : 148761

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility : <u>PHC</u>	Call Registration Date : <u>16/10/2023</u>
Address : <u>PHC Pallickathod</u>	Caller ID : <u>75069</u>
<u>Kottayam</u>	Date of Visit : <u>18/10/2023</u>
Ph : <u>9446085329</u>	Asset No. : <u>0542831</u>
	EQPT Name : <u>BP Apparatus (LED)</u>
	Manufacture <u>Diamond</u> Model : <u>Deluxe</u>
	S. No. <u>00966</u> Dept. <u>OPD</u>

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : customer reported that equipment is showing wrong values and is not suitable to use in patients.

Action Taken : checked and found that equipment is showing wrong values. Also checked with other machines and found above said equipment is not functioning properly. Repairing of the equipment is economically not feasible. Hence recommending the equipment to be replaced.

Completed Date : Time : BER Spare Required

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Sarish Sivas</u>	<u>18/10/23</u>	<u>12:00pm</u>	<u>1:00pm</u>

Customer Remark Completed Pending

Machine was found to show reading error (wrong value) period of condemnation.

Service Engineer Name : Sarish Sivas

Signature :

Date : 18/10/2023

Contact Number : 9946646571

Customer Name : PHC Pallickathodu

Signature :

Date : 18/10/23

Designation : Medical Officer In-Charge

Hospital Seal :

Contact Number : PHC Pallickathodu Aruvikuzhy-686 503

Contract number: 15241924
 Date: 18/10/81



Medical Officer in Charge
 PNC Bhatkela Road
 203 884-203

Signature: [Signature]
 Details Engineer: [Signature]
 Customer Remarks: [Handwritten notes]

Completed Pending

Serial No.	Part Name	Part No.	Part Qty
1	Engine Oil	18/10/81	1.000

Problem identified: [Handwritten description of the issue]
 Solution: [Handwritten description of the solution]
 Remarks: [Handwritten notes]

Service Classification: General Special Other

Call Registration No: 18/10/81
 Date of Visit: 18/10/81
 Asset No: 188420
 (PNC Bhatkela Road)
 Manufacturer: [Handwritten]
 Model: [Handwritten]
 Serial No: [Handwritten]

Service Report: [Handwritten details]

KMSCI
KITPL
TOLL FREE NO.: 1-800-270-0690
(800) 4 8907579 - 701 168



CYRUX
TOLL FREE NO: 1800 - 425-7800
800-4-8907579

CYRUX HEALTH CARE PVT LTD
BEMP SERVICE PROVIDER
PREVENTIVE MAINTENANCE SERVICE
TOLL FREE NO: 1800 - 425-7800
800-4-8907579

CYRUX HEALTH CARE PVT LTD
BEMP SERVICE PROVIDER
PREVENTIVE MAINTENANCE SERVICE
TOLL FREE NO: 1800 - 425-7800
800-4-8907579

CYRUX HEALTH CARE PVT LTD
BEMP SERVICE PROVIDER
PREVENTIVE MAINTENANCE SERVICE
TOLL FREE NO: 1800 - 425-7800
800-4-8907579

CYRUX HEALTH CARE PVT LTD
BEMP SERVICE PROVIDER
PREVENTIVE MAINTENANCE SERVICE
TOLL FREE NO: 1800 - 425-7800
800-4-8907579



06-06-14	Received from Stone	4							
06-06-14	Issued	1							
10-1-19	Returned from Stone to Gold								
16-11-20	Received from Stone	4							
16-11-20	Issued	1							
25-11-23	Received from Stone (Delux Diamond)	4							
25-01-23	D. Damaged - 1								
25-01-23	Delux Diamond								
25-02-23	Damaged - 1								
25-02-23	2019 Diamonds								
01-03-23	Balance								

