

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Tiruvandur.
2	Name of Hospital	THQH PARASSALA.
3	Name of Equipment with Make, Model and Serial Number	BP apparatus. Etkometer Model → NA SI-NO- → NA
4	Equipment ID & Barcode	0120659
5	Date of purchase / Year of manufacture /Installation Date	15/10/2018
6	Warranty details (Yes/No)	NO.
7	*AMC/ CAMC Period agreed at the time of purchase	Nil.
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	16/11/23.
9	Action taken	checked the machine it can't be repair economically.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged.
11	Recommendations for repair (required service details)	checked the machine and found that mercury spilled out from glass tube. It can't be repair economically.
12	Cost of spares (specify parts and cost)	It can't be repair economically.

13	Asset Value	1323)
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	Not repairable
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Attached.
16	Reasons for recommending the equipment as BER	Checked the machine and found that mercury spilled out from glass tube, Accessories damaged, bladder and cuff damaged, It can't be repair economically, Therefore proposing it for RBER.
17	Name & Signature of CYRIX Authority	Asith George. <u>Asith</u>

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


Mercury glass broken and spilled.
So RBER

MANESHA MOHAN R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram


Asith
6-12-2023

Signature of JC BM (NHM)

Date



Signature of Superintendent / Medical Officer (i/c)





BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Order No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 158214

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>THQH</u></p> <p>Address <u>Parassala</u> <u>Tavandrum</u></p> <p>Ph : <u>7510 23 9752</u></p>	<p>Call Registration Date : <u>16/11/23</u></p> <p>Caller ID : <u>80477</u></p> <p>Date of Visit : <u>23/11/23</u></p> <p>Asset No. : <u>0120659</u></p> <p>EQPT Name : <u>BP apparatus</u></p> <p>Manufacture <u>Elkometer</u> Model : <u>NA</u></p> <p>S. No. <u>NA</u> Dept. <u>Casualty</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : not working

Action Taken : Checked the machine and found that mercury spilled out from glass tube, bladder and cuff damaged, Accessories damaged. It can't be repair economically. Therefore proposing it for RBER.

Completed Date : 23/11/23 Time : 3pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Ajith</u>	<u>23/11/23</u>	<u>2.45pm</u>	<u>3pm</u>

Customer Remark Completed Pending



Service Engineer Name : Ajith

Signature : [Signature]

Date : 23/11/23

Contact Number : 75938 4711

Customer Name : Uineja Lil

Signature : [Signature]

Date : 23/11/23

Contact Number : 8943019353

Designation : ECM technician

Hospital Seal :

BEKOMITE®

Mercury complaint


PRO ID : 0126
CAL.ON : 13-07-2023
CAL.DUE : 12-07-2024

ISO 9001 : 2008 Certified Co. Ph: 9744555873

CYRIX BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)

TOLL FREE NO: 1800 - 425-7669

BAR CODE - (8004-890615225) 0120659



Mercury complaint

MSCL



CYRIX
MEDICAL EQUIPMENT
100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290



COCHA

