


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Kottayam
2	Name of Hospital	General Hospital
3	Name of Equipment with Make, Model and Serial Number	Eg: Cautery machine make: Alan Model: ELS4 360M ⁺ Slno: ASGM1204023 ✓
4	Equipment ID & Barcode	0510202 ✓
5	Date of purchase / Year of manufacture / Installation Date	28/11/2013 As per Mann Stole Installation date - 10.05.2012
6	Warranty details (Yes/No)	Nil Project No: 93/44 Vot T Cms BME
7	*AMC/ CAMC Period agreed at the time of purchase	Nil
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	05/12/2023 - In 8402A
9	Action taken	Checked card found equipment is totally down.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	The equipment having severe defects. Check with the OEM and found model was obsolete and spare are not available.
12	Cost of spares (specify parts and cost)	End of life letter from the OEM states that above mentioned model was outdated and spare parts are not available.

13	Asset Value	167400/- ^{As per stock} Rs. 190350
14	% Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	Spare parts care ^{as per} not available to purchase.
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix report attached
16	Reasons for recommending the equipment as BER	The equipment was covered more than 10 years and the model was obsolete and spare parts care not available. Hence recommended the equipment as 'BER'
17	Name & Signature of CYRIX Authority	 Sanish Swan


*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:
 Asset value Rs 190350
 Cost of spare: End of life letter
 Life period - 11 years by OEM attached
 As per ~~percentage value~~ the above details
 the equipment is 11 years old and spare not
 available from OEM, recommended as BER
 Installation date as per main stock 10/5/2012 ^{18/1/2024}
 Signature of JC BM (NHM)



Date


 Signature of
 Superintendent / Medical Officer (i/c)
 Superintendent i/c
 General Hospital
 Kottayam



**BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAMME
UNDER
NATIONAL HEALTH MISSION**



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX
HEALTHCARE PVT LTD

No. : 172403

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility : <u>GH</u>	Call Registration Date : <u>05/12/2023</u>
Address : <u>General hospital</u>	Caller ID : <u>86024</u>
<u>Kottayam</u>	Date of Visit : <u>12/12/2023</u>
Ph : <u>9600570655</u>	Asset No. : <u>0510202</u>
	EQPT Name : <u>Cauty Machine</u>
	Manufacture <u>Alan</u> Model : <u>ELSY-260M+</u>
	S. No. <u>ASGM.1206023</u> Dept. <u>O.T.MAN</u>

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Cauty Machine not Working

Action Taken : checked and found equipment to not working. The equipment is not able to repair because repairing the equipment is economically not feasible

Completed Date : Time : Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Sanish Sivan</u>	<u>12/12/23</u>	<u>12:30pm</u>	<u>1:30pm</u>

Customer Remark : Completed Pending mini sample SNU

Service Engineer Name : Sanish Sivan
Signature : [Signature]
Date : 12/12/2023
Contact Number : 9946646571

Customer Name : MINI GOSPIH
Signature : [Signature]
Date : 12/12/23
Contact Number : 12/12/23
Designation : Senior Numpy officer
Hospital Seal :



STOCK BOOK

NAME OF ARTICLE DIATHERMY

Date	No. and date of Voucher or Invoice	From whom received or to whom issued	Receipt	Issued	Balance after each transaction	Initials of Receiver	Remarks
1/5/21		BOUGHT FORWARD FROM PAGE NO 52 STOCK BOOK COSTLY MACHINES & INSTRUMENTS (VOL I)			05		
1	28/11/13	(414)68(254)05(21)0134	-	1/0 n			
2		(414)68(254)05(21)0119					
3		(414)68(254)05(21)0113					
4	10/3/21	SHALYA DIATHERMY MACHINE (RS:133905)					
5	10/3/21	SHALYA DIATHERMY MACHINE (RS:133905)					
2/4/2022		Tr 12 F101		01	06		Shalya
	rd no 8/3/2016	2 2 19,975.00					[Shalya - NY Sl. No 1015AD37]

AD-2

ALPH ELECTRONIC SYSTEMS PVT. LTD.
1, B. Patti Camp Road,
Kalyan, Dist. Thane, Maharashtra, India.
Tel: +91-201-2872102 / 104
Fax: +91-201-2072102
E-mail: sales@alphsystems.net
Web: www.alphsystems.net

SR No: AUSA1304273
MODEL: EASY-CONTROL V21
SERIAL: 2001AC-029-5014
INPUT: 230V AC, 50Hz, 50VA
OUTPUT: 24V DC, 1A

CUT: 400W / 200 amps
COP: 6 150W / 500 amps
IP: CLEAR 120W / 100 amps
PROT: ...
FIELD: M INI 600 HLT & 103 / 235 817244

CE 1904

Installation Name: DH, Kottayam
Project / Scheme Name: pg 11-12
Equipment Code: 1105

MONOPOLAR FOOT SWITCH



Ref. NO : KLBEMP /24/ 6

CYRIX[®]

HEALTHCARE PVT LTD

To,
Amritha Madam
Deputy Manager (ES)
KMSCL

Subject: Regarding submission of RBER Report- Ticket: 82024 Barcode: 0510202- GH Kottayam

Dear Madam,

This letter is to inform you that we are recommending a RBER for a Diathermy machine at **GH Kottayam, with Ticket ID: 82024 Barcode: 0510202 dated on 05/12/2023 asset value: Rs 167400**. This machine is installed on 10/05/2012 and have been more than 10 years old. Now its Main Board and Display Board is Totally damaged. We have tried the service of these boards with our TRC team. Since it is not in a serviceable condition, we have contacted the OEM (JBS Meditecindia) for new spare parts. We didn't send the machine to them for service because the performance and working period of these machine after service is very poor. They have replied that spare parts of more than 10-year-old machine is not available. Since the same scenario happened on September 2023 for another machine with same make and model (Alan ELSY360M+) at THQH Changanacherry with serial number: 1204024. For this machine also having same issues, but they have provided the EOL letter (attached for Reference with number: JBS/Service/Gen/001/09-2023).

Now they are replying that they can't be able to provide EOL letter for each machine unless KMSCL have to give instruction to provide letter for these machines. Since these calls are pending due to documentation works, the smooth functioning of Operation Theater is affected. Customer can't be able to buy a new machine.

In this situation I am requesting you to kindly consider the previous EOL letter as reference for this RBER case also or kindly talk to the OEM to issue a common EOL letter for machines that have served more than 10 years.

Humbly Requesting you to do the needful at the earliest.

Regards,

Date: 01/01/2024

Afsal

KLBEMMP - Zonal Manager (South)

Mob : 9895061437

30/641B, Petta, Poonithura, Ernakulam, Kerala-682038

Ph: + 91 97445 55073 / 9072575175 | Email: sales.kl@cyrix.in, service.kl@cyrix.in

www.cyrixhealthcare.com

CIN:U74140KL2013PTC034081

ISO Certified Company | AERB Approved QA Agency | NABL Accredited Calibration Agency

Branches: Uttar Pradesh, Karnataka, Kuwait & Dubai

END OF LIFE LETTER

JBS/Service/Gen/001/09-2023

29.09.2023

To,

M/S. Cyrix Healthcare Private Limited
1 St Floor, 30/64 1 B,
Kochi Dhanushkodi Road
Poonithura, Ernakulam-682038

(Kind Attn : Mr. Afsal-Zonal Manager.)

Respected Sir,

Sub: Alan make Diathermy End of Life letter – Reg.
Ref: Taluk Head Quarters Hospital, Changanacherry.
Make : ALAN ; Model : ELSY 360 M+ ; S.NO: 1204024.

As reported, the Alan make surgical diathermy was not working and completely breakdown.

We understood that this machine was already served more than 12years and it is more than the expected life of the machine.

Due to continuous technological updation.. This particular model was outdated. Hence the spares are not available. So it is not possible to service it.

Hence we recommend you to treat the machine as End of Life.

Thanking you,
for JBS Mediitec India (p) Ltd.,
Service Department,
Kaarthikeyan.S.P.
Ph : 9442243991

“Sri Ragavendra Tower”, 3rd Floor, No-34, Co-operative E-colony, Behind Kumudham Nagar,
Villankurichi Road, Coimbatore – 641035 Ph: 9443367915, 9443366752 Email ID: info@jbsmediitec.com

