

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Ezraikulam
2	Name of Hospital	PHC kakkianad
3	Name of Equipment with Make, Model and Serial Number	UPS Make: APC Model: UPS 600
4	Equipment ID & Barcode	0345118
5	Date of purchase / Year of manufacture /Installation Date	26/6/2019
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	19/10/2023
9	Action taken	Circuit board and battery faulty.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Circuit board and battery faulty Circuit board not repairable and not available in market UPS not repairable
12	Cost of spares (specify parts and cost)	Nil

14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Report
16	Reasons for recommending the equipment as BER	checked the machine and found the circuit board and battery faulty circuit board not repairable and not available in market, so equipment not repairable, these for equipment recommended for BER.
17	Name & Signature of CYRIX Authority	Stanijo Tom <i>Stanijo</i>

*Not mandatory **#Based on the period of life and value as per the BER guidelines**

* **Attach Photograph**

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


submitted after 90 months.

Revally
2/12/23

Signature of JC BM (NHM)

National Health Mission
Aryankerala
Ernakulam

Date



Signature of
Superintendent / Medical Officer (IC)

[Handwritten signature]



BIO-MEDICAL MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX
HEALTHCARE PVT LTD

No. : 145464

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility P.H.C	Call Registration Date : 19/10/2023
Address Kakkannad	Caller ID : 75770
..... Ernakulam	Date of Visit : 31/10/23
Ph : 7025000694	Asset No. : 0745118
	EQPT Name : UPS
	Manufacture APC Model : UPS 600
	S. No. Na Dept. Lab

Service Classification : Breakdown Call PMS Calibration Cust. Training

Problem Identified :
checked the machine and found that circuit board issue and battery issue


Action Taken :
checked the machine and found that circuit board issue and battery issue. Circuit board can not be repairable as circuit board not available in market. So the equipment ~~is~~ not repairable. therefore recommended for RFR.

Completed Date : 31/10/23 Time : 11:00am Spare Required

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
Shimyo Tom	31/10/23	10:00am	11:00am

Customer Remark **Completed** **Pending**



Service Engineer Name : Shimyo Tom	Customer Name : MENO R KASSIM
Signature : <i>Shimyo</i>	Signature : <i>chereeny</i>
Date :	Date : 31/10/23
Contact Number : 9560852484	Contact Number :
	Designation : LAB TECHNICIAN
	Hospital Seal :

Back-UPS 600



APC
by Schneider Electric

CYRIX
MAINTENANCE LIMITED

**BIOMEDICAL EQUIPMENT MAINTENANCE
PROGRAMME (BEMP)**

TOLL FREE NO: 1800 - 425-7669

BAR CODE - (8004-890615225)

0745118



KMSCL
Kuala Lumpur Medical Society



4

1. Name of Equipment Equipment No

2. Interacted group 21516101

3. Public analysis -

4. Public

15. 1st. Centrifuge 20/11/2008-2019/21A

16. Biorad manual (transferred to PHE Palabuhan on 02.02.21)

17. Biosafe analyzer 212330116123

18. Biorad BPS

19. Hematology analyzer

20. Biorad low salt analyzer (transferred to PHE Palabuhan on 12.02.21)

21. Digibath incubator (transferred to PHE CMC Lumbalangi on 27/11/19)

22. Microscope

23. Biorad

24. Water bath

Date	Model no	Manufacturer name	Serial No.	Calibration Due	Present working status
26/3/19	Muji 13	Agaffe	NA	NA	working
8/2/19	R-86 Plus	Remu	NA	NA	working
7/6/19	typical (label)	viper 2000 (labelled)	NA	NA	working
20/6/19	Muji Vnd	Agaffe	NA	NA	working
26/6/19	Muric M3215	Medone	NA	NA	working
26/8/19	Chiquero label	Meril	NA	NA	NA
6/3/19		Tanco	NA	NA	working
11/10/19	Muric M3215	Medone	NA	NA	NA
7/7/20	typical (label)	(N.A. Jain) Labelled	NA	NA	working
7/7/20	P17 109	Tanco	NA	NA	working
			NA	NA	working