


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

122

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Tavandrum.
2	Name of Hospital	PUC Maranchalloor.
3	Name of Equipment with Make, Model and Serial Number	Centrifuge. Almeco. model CGA. S/N. → SVA.
4	Equipment ID & Barcode	89508 - 0144289.
5	Date of purchase / Year of manufacture / Installation Date	5/03/2014.
6	Warranty details (Yes/No)	no.
7	*AMC/ CAMC Period agreed at the time of purchase	N/A.
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	8/1/24
9	Action taken	checked the machine and found that motor failure
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged.
11	Recommendations for repair (required service details)	checked the machine and found that motor armature winding and controller are fully damaged. Body suited also
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	9651/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Attached .
16	Reasons for recommending the equipment as BER	checked the machine and found that motor winding, armature and controller are fully damaged. It can't be repair economically. Therefore proposing it for RBER.
17	Name & Signature of CYRIX Authority	Panav-PS. 


*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


Motor winding, armature damage. So can be RBER.

MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram


16.01.2024
Signature of JC BM (NHM)

Date




Signature of
Superintendent / Medical Officer (i/c)
Medical Officer in Charge
Primary Health Centre
Thiruvananthapuram



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Order No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. :
158317

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

422

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>PHC</u></p> <p>Address <u>Maranalloor</u> <u>Torandur</u></p> <p>Ph : <u>7356335302</u></p>	<p>Call Registration Date : <u>8/1/24</u></p> <p>Caller ID : <u>89828</u></p> <p>Date of Visit : <u>8/1/24</u></p> <p>Asset No. : <u>014289</u></p> <p>EQPT Name : <u>Centrifuge</u></p> <p>Manufacture <u>Almco</u> Model <u>60</u></p> <p>S. No. <u>re</u> Dept. <u>lab</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : not working

Action Taken : checked the machine and found that motor failure. The motor armature are fully damaged, Controller and motor winding also failure. It can't be repair economically.

Completed Date : 8/1/24 Time : 1pm Spare Required

Spare Replaced Requested

1.	Description	Qty.	Part Number	PR Number
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Pranav</u>	<u>8/1/24</u>	<u>12:30pm</u>	<u>1pm</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Pranav M</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>8/1/24</u></p> <p>Contact Number : <u>9024530652</u></p>	<p>Customer Name : <u>Anu Krishna-S</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>8/1/24</u></p> <p>Contact Number : <u>8589890679</u></p> <p>Designation : <u>Lab Technician</u></p> <p>Hospital Seal :</p>
--	---





CAUTION
INCREASE SPEED STEP WISE

CYPK MEDICAL EQUIPMENT MAINTENANCE
PROVIDING SERVICE
TOLL FREE NO: 1-800-423-7888
FAX NO: (914) 423-0229
9144230

BLUE COMBO





