

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

432

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Trivandrum
2	Name of Hospital	GH Trivandrum
3	Name of Equipment with Make, Model and Serial Number	Name of Equipment : Suction Apparatus make : Lifecare model : goley
4	Equipment ID & Barcode	0111805
5	Date of purchase / Year of manufacture /Installation Date	15/5/2017
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	8/1/2024
9	Action taken	Checked the machine Motor faulty and Winding burnt.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Recommendations for repair (required service details)	Checked machine motor and found Secretion went inside and motor go faulty, winding Burnt. Also Body of machine and motor are rusted. Jar - Lid and tubings are also found damaged.
12	Cost of spares (specify parts and cost)	NA



13	Asset Value	10,800
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Service report, photos.
16	Reasons for recommending the equipment as BER	Motor damaged and winding burnt; Body fully rusted and bottle damaged. This reasons for recommending the equipment as RBER.
17	Name & Signature of CYRIX Authority	Josekutty George

*Not mandatory #Based on the period of life and value as per the BER guidelines

* **Attach Photograph**

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Motor fully damaged and winding damaged. So can be considered as RBER based on the conditions.

MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram

22.1.2024
Signature of JC BM (NHM)

Date

Signature of Superintendent / Medical Officer (Genl)

Superintendent
General Hospital
Thiruvananthapuram



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 176302

432

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrinx.com | E-mail : bemp.kl@cyrix.in

Health Facility <u>GH Trivandrum</u>	Call Registration Date : <u>8/1/2024</u>
Address <u>Trivandrum</u>	Caller ID : <u>89439</u>
Ph : <u>701289 6198</u>	Date of Visit : <u>10/1/2024</u>
	Asset No. : <u>0111805</u>
	EQPT Name : <u>Suction Apparatus</u>
	Manufacture <u>LifeCare</u> Model : <u>goley</u>
	S. No. <u>Nil</u> Dept. <u>Ward-7</u>

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Not working

Action Taken : Checked the machine motor damaged and body fully rusted, checked motor and found secretion went inside and motor faulty winding burnt. Also body of machine and motor are rusted. Jar-Lid and tubings are also found damaged.

Completed Date : 17/1/2024 Time : 12:30 pm Spare Required

Description	Qty.	Part Number	PR Number
1. <u>RBER</u>			
2.			
3.			



Cyrix Engineer : Josekutty George

Date	Start Time	End Time
<u>17/1/2024</u>	<u>12 pm</u>	<u>12:30 pm</u>

Customer Remark Completed Pending

Service Engineer Name : <u>Josekutty George</u>	Customer Name : <u>Sharmila . S .</u>
Signature : <u>[Signature]</u>	Signature : <u>[Signature]</u>
Date : <u>17/1/2024</u>	Date : <u>17/1/23</u>
Contact Number : <u>8848230407</u>	Contact Number : <u>9495643384</u>
	Designation : <u>SNO</u>
	Hospital Seal :

