





## BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

# CYRIX

No.:

147837

ISO 13485 : 2012 & ISO 9001-20	08 CERTIFIED COMPANY A	ERB Approved Service Agency

Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Ph: 98472 99500 Website: www.cyrix.com   E-mail: bemp.kl@cyrlx.in						
Address Thodupusha	Caller ID: Date of Visit	ation Date: 9588み :: 14-0み-	2034			
Ph: 08606885221	EQPT Name Manufacture	0611314 : B.P. App. Elko :1800390 De	<i>മാ</i> ച്ചം Model :	1018		
Service Classification : Breakdown Call	PMS	Calibration	Cust.1	Training 🔲		
Problem Identified: Not Working  Action Taken: Chede the machine main board damage.  Vnable to sarvice  Completed Date: 14-02-2024 Time: 3:30.Pm  Spare Required Description  Description  Qty. Part Number  1.						
2. WG	NG	Na		N9		
3.						
Cyrix Engineer		Date	Start Time	End Time		
Vishnuprasod TT		14-02-2024	3.00 pm	330'Pm		
Customer Remark	Completed		Pendir			
Service Engineer Name : Vishmuprosad (12)	Custom Signatu Date so Our Configer	er Name: Syl	Supering	enden!		



## REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

## Recommendations for Beyond Economic Repair (BER)

### **PROFORMA**

SI. No	Particulars	Details
1	Name of District	1duklei
2	Name of Hospital	DH Thodupusha
3	Name of Equipment with Make, Model and Serial Number	Equipment: B.P. Apparatus  Make: Ellio  model: 1018  S.N : 18051800390
4	Equipment ID & Barcode	95882 and 0611314
5	Date of purchase / Year of manufacture /Installation Date	25-10-2019
6	Warranty details (Yes/No)	N/0
7	*AMC/ CAMC Period agreed at the time of purchase	1 year
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	13-02-2024
9	Action taken	Tay to service
10	Present status of the equipment (Fully damaged / partially damaged)	partially damage.
11	Recommendations for repair (required service details)	cheele the machine bound that main board damage Unable to service
12	Cost of spares (specify parts and cost)	Nell

	The second secon	
13	Asset Value	2200
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	<i>p</i> v://
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrise service report
16	Reasons for recommending the equipment as BER	Cheele the machine found that main board damage unable to service - so recommeding for BIER
17	Name & Signature of CYRIX Authority	Vishnuprasad TJ 14-02-2024

<sup>\*</sup>Not mandatory

#Based on the period of life and value as per the BER guidelines

#### \* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Consultant Biomedical Engineer
National Health Mission

15 | 02 | 2024 Arogyakeralam Idukki-685603

Signature of JC BM (NHM)



Superintendent / Medical officer (i/c) District Hospital