


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	WAYANAD
2	Name of Hospital	DH MANANTHAVADY
3	Name of Equipment with Make, Model and Serial Number	Equipment-Operation table Make-Appasamy associates Model - AAOT 1 Serial Number -3101130268
4	Equipment ID/ Barcode	Barcode-1210668/Ticket-84449
5	Date of purchase/ Year of manufacture/Installation Date	16/07/2013
6	Warranty details (Yes/No)	NO
7	*AMC/ CAMC Period agreed at the time of purchase	NO
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	07/12/2023/Toll free
9	Action taken	Complaint reported as table has no UP/DOWN movement. On checking found that up/down motor defective .Enquired OEM for quotation
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendation
12	Cost of spares (specify parts and cost)	Not applicable

13	Asset Value	Rs -85424/-
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	Not applicable
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Beyond economical repair Certificate from manufacture (Appasamy associates P Ltd) & Cyrix service report
16	Reasons for recommending the equipment as BER	UP/DOWN Motor defective, which is not available with OEM, (Appasamy Associates P Ltd). Machine installed on 16/07/2013 and aged above 10 years OEM declared as equipment is Outdated Model (Letter attached) Above condition met tender clause 5.3.14.2 .So the equipment recommended for condemnation
17	Name & Signature of CYRIX Authority	NIYAS HADI AP 

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Ophthalmic Operative Theatre table up and down movement not possible. Supplier declares end of life of this machine because of need for condemnation



CONSULTANT
Bio-Medical Engineer
Signature of JC BM (NHM)
(Arogyakeralam)
Wayanad-673122


The equipment was 10 year old and used for considerable period. Can be consider for Condemnation. A new equipment may be supplied to the institutions

Date:

22/02/24




Signature of
Superintendent/Medical Officer
(i/c)


SUPERINTENDENT
DISTRICT HOSPITAL
WAYANAD, MANANTHAVADY



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 123895

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : <u>District Hospital</u></p> <p>Address : <u>Mananthavady</u> <u>Wayanad, Kerala</u></p> <p>Ph : <u>8848596852</u></p>	<p>Call Registration Date : <u>07/12/2023</u></p> <p>Caller ID : <u>84449</u></p> <p>Date of Visit : <u>08/12/2023</u></p> <p>Asset No. : <u>1210668</u></p> <p>EQPT Name : <u>OT Table</u></p> <p>Manufacture <u>Appasamy</u> Model : <u>AA OT</u></p> <p>S. No. <u>3101130268</u> Dept. <u>Eye OT</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : No movement

Action Taken : checked the OT table and found the up and down movement not working. Identified up and down motor complaint. Repair

Completed Date : Time : Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Kasyep.p.v</u>	<u>08/12/23</u>	<u>9:30am</u>	<u>11:00am</u>

Customer Remark Completed Pending

<p>Service Engineer Name : <u>Kasyep.p.v</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>08/12/23</u></p> <p>Contact Number : <u>7593847134</u></p>	<p>Customer Name : <u>Normal George</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>08/12/23</u></p> <p>Contact Number : <u>8848596852</u></p> <p>Designation : <u>Biomedical</u></p> <p>Hospital Seal : <u>[Seal]</u></p>
--	---



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 181904

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kf@cyrix.in

<p>Health Facility <u>District Hospital</u></p> <p>Address <u>Mananthavady</u> <u>Wayanad, Kerala</u></p> <p>Ph : <u>9848596852</u></p>	<p>Call Registration Date : <u>07/12/2023</u></p> <p>Caller ID : <u>84449</u></p> <p>Date of Visit : <u>28/02/2024</u></p> <p>Asset No. : <u>1210668</u></p> <p>EQPT Name : <u>OT Table</u></p> <p>Manufacture <u>Appasamy</u> Model : <u>AAOT</u></p> <p>S. No. <u>3101130268</u> Dept. <u>Eye OT</u></p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Up and down movement motor defective.

Action Taken : checked and found up and down motor defective. OEM engineers (Appasamy Associates) visited the site and confirmed motor complaint. Spare parts are not available from OEM and declared End of life. OEM suggest to purchase new equipment.

Completed **Date :** 28/02/24 **Time :** 4:30 pm **Spare Required**

Spare Replaced **Requested**

1.	Description	Qty.	Part Number	PR Number
2.				
3.				

Cyrux Engineer	Date	Start Time	End Time
<u>Kasyep.pv</u>	<u>28/02/24</u>	<u>2:00pm</u>	<u>4:30pm</u>

Customer Remark **Completed** **Pending**

SUPERINTENDENT
DISTRICT HOSPITAL
WAYANAD, MANANTHAVADY



<p>Service Engineer Name : <u>Kasyep.pv</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>28/02/2024</u></p> <p>Contact Number : <u>7593847134</u></p>	<p>Customer Name : <u>[Signature]</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>[Date]</u></p> <p>Contact Number : <u>1100, ophthalmology</u> <u>6238669883</u></p> <p>Designation :</p> <p>Hospital Seal :</p>
---	--

BEYOND ECONOMICAL REPAIR CERTIFICATE

To

Date: 23.01.2024

**The Superintendent
General Hospital
Mananthavady.**

Sub: BER Certificate- Regarding
Equipment: **Operation Table**
Model: **AAOT 1**
Sl. No: **3101130268**

Dear Sir/Madam,

We would like to inform you that our service engineer has visited your hospital on **22.01.2024** and inspected above equipment and found that the equipment was 10 years old and used for a considerable long period and cannot be repaired/ serviced and also spare parts are not available, so even if spare parts are replaced, which will not be economical and cannot give proper functionality.


Since the above Equipment is outdated, we suggest you to purchase the new equipment.

Looking forward to your continued support.

Thanking you,

Sincerely yours,

FOR APPASAMY ASSOCIATES PVT.LTD.



[Handwritten Signature]

**Re: Regarding Ophthalmology OT table
complaint at DH Mananthavady,
Wayanad, kerala (barcode
-1210668,ticket-84449)**

From: RADHAKRISHNAN

radhakrishnan.thrissur@appasamy.com

To: Blesson Jose zm2.klbemp@cyrix.in

Sent: Tuesday, 27 February, 9:15 am

Regards,

***B.Radhakrishnan,
Appasamy Associates Pvt Ltd,
Door No: 17/543-4,
Kizhakkepuram Road,
Aranattukara (Post)
Thrissur-680618,
Kerala
Mob : 9349211170
Office : 8075939887***

--- On Tue, 27 Feb 2024 08:27:51 +0530 **Blesson Jose**
<zm2.klbemp@cyrix.in> wrote ---

Dear appasamy team,

As discussed with Mr. Niyas kindly share the End of life
letter or Model discontinued letter for further
proceeding discard of equipment.

Equipment is down from since 07/12/2023, 82 days
back, and the service provided by the said equipment
was not get benefit for public and poor patients due to
disfunctional of equipment.

We kindly request you to provide the supporting documents at the earliest for discard of equipment.

Thanks& Regards,

Blessen Jose

Zonal Manager/North Zone

BEMMP- Kerala

Mobile: 7593847153

Email : zm2.klbemp@cyrix.in

CYRIX HEALTHCARE (P)LTD

30/641B, Petta, Poonithura, Ernakulam-682038

www.cyrixhealthcare.com

From: Niyas Hadi AP <niyascyrix@gmail.com>

Sent: Tuesday, January 16, 2024 10:06:54 AM

To: RADHAKRISHNAN

<radhakrishnan.thrissur@appasamy.com>

Cc: Blessen Jose <zm2.klbemp@cyrix.in>

Subject: Re: Regarding Ophthalmology OT table complaint at DH Mananthavady, Wayanad, kerala (barcode -1210668,ticket-84449)

Dear Sir

Please find the following details of OT table

Equipment -OT table (Ophthalmology)

Make -Appasamy

Model -AAOT 1

Serial number -3101130268

Installation date -16-07-2013

Purchase order(KMSCL)-512/2013/209

Eqpt. Code - 209-2810

Please update availability of spare parts

Thanks & regards

NIYAS HADI

District incharge

BEMP project

Wayanad

kerala

mob -[7593847171](tel:7593847171)

email -niyascyrix@gmail.com

www.cyrixhealthcare.com

Cyrix Healthcare Pvt Ltd

| 30/641 B | Pettah Jn | Poonithura | Cochin
-38 | Kerala | India

KERALA || KARNATAKA || TAMIL NADU || UTTAR
PRADESH

On Wed, 27 Dec 2023, 12:33 pm RADHAKRISHNAN,
<radhakrishnan.thrissur@appasamy.com> wrote:

Dear sir,

Please send Equipment model name & invoice
number and serial number details.

Regards,

B.Radhakrishnan,
Appasamy Associates Pvt Ltd,
Door No: 17/543-4,
Kizhakkepuram Road,
Aranattukara (Post)
Thrissur-680618,
Kerala
Mob : 9349211170
Office : 8075939887

--- On Wed, 27 Dec 2023 12:13:53 +0530 **Niyas**
Hadi AP <niyascyrinx@gmail.com> wrote ---

Dear Sir

Please confirm the availability of spare

Thanks & regards

NIYAS HADI

District incharge
BEMP project
Wayanad
kerala
mob -[7593847171](tel:7593847171)

email -niyascyrix@gmail.com

www.cyrixhealthcare.com

Cyrix Healthcare Pvt Ltd

| 30/641 B | Pettah Jn | Poonithura | Cochin
-38 | Kerala | India

KERALA || KARNATAKA || TAMIL NADU ||
UTTAR PRADESH

On Thu, 14 Dec 2023, 12:32 pm Niyas Hadi AP,
<niyascyrix@gmail.com> wrote:

Dear Sir

I have an ophthalmic OT table complaint
reported from DH mananthavady, wayanad
On checking found that up and down motor
not working

Please find attached photos and please
confirm the availability of spare

(up/down)motor

Equipment -OT table

Make -Appasamy associate

Model -AAOT 1

Serial number -faded

Please find attached photo for reference
motor specification

Please send the quotation for spare /one
time service support at the earliest

Thanks & regards

NIYAS HADI
District incharge

BEMP project

Wayanad

kerala

mob -[7593847171](tel:7593847171)

email -niyascyrix@gmail.com

www.cyrixhealthcare.com

Cyrix Healthcare Pvt Ltd

| 30/641 B | Pettah Jn | Poonithura | Cochin


-38 | Kerala | India

KERALA || KARNATAKA || TAMIL NADU ||

UTTAR PRADESH

CYRIX
HEALTHCARE PVT LTD
CN: DHM602 S.N: 3101130268
PRO : OT TABLE
ID : 1210663
CAL.ON : 30-06-2024
CAL.DUE : 29-06-2024
ISO 9001 : 2008, Certified Cd, Ph: 9744555073

Product : OPERATION TABLE
(patient unit for ophthalmic surgery)
Model : AAOT 1
SI.No: Appasamy Associates
Trade Mark : 110V/230V AC-50Hz/60Hz
Input : 150 VA
Power in VA : 5A Slow Blow
Fuse : IP 2X
IP Category : TYPE B
CLASS I
Manufactured & Marketed By
APPASAMY ASSOCIATES
No.310, Sidco Industrial Estate, Ambattur
CHENNAI-600 098, E-Mail : appachair@yahoo.in



Equipment found in the department on physical verification

Manju.K.J.
[Signature]



[Signature]
SUPERINTENDENT
DISTRICT HOSPITAL
WAYANAD, MANANTHAVADI