REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

		THOLOR	
N	SI.	Particulars	Details
	1	Name of District	ERNAKUCAM
:	2	Name of Hospital	THOH FORTKOCHI
	3	Name of Equipment with Make, Model and Serial Number	SUCTION APPARATUS SURGIVAC C121019
	4	Equipment ID & Barcode	63951 10420734
	5	Date of purchase / Year of manufacture /Installation Date	23/4/2005
	6	Warranty details (Yes/No)	NO
	7	*AMC/ CAMC Period agreed at the time of purchase	<u> 19</u>
8	8	Date of breakdown(Date of registration of complaint through email/ Toll free)	9 18 12003
9	9	Action taken	Checkel Motors coolery Condition
10)	Present status of the equipment (Fully damaged / partially damaged)	Fullydamazel
11	- 1	Recommendations for repair (required service details)	found Screton Apply Motor was fully Pustul and It Cannot been Repaired
2	C	ost of spares (specify parts and cost)	ai j

13	rissel value	४७२६
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	Ali'l
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX Scevice Report
16	Reasons for recommending the equipment as BER	Motore was fully Rustel and Screton applies was all so fully clample, It Connot been Scienced
17	Name & Signature of CYRIX Authority	Ligon Dosing

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Motor hunted ampletely damaged.

Sobmitted 13ER after 30 days.

Signature of JC BM (NHM)

Noroi P. Jose

Date

JAD.

Signature of Superintendent / Medical Officer (i/c)

Seal

BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME NATIONAL HEALTH MISSION



ERVICE PROVIDER Tender No. WO-37/2021-2022/698

Contact Number: 90943 4age

153412

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in Call Registration Date : 62 8 2035 THOH Caller ID: 63951 Health Facility Date of Visit : 19/9/2005 FORTHOLD! Asset No. : 0720093 9 Ephalaylan EQPT Name: Sulton apply Ph : 99 464 55889 Manufacture SUPLEVAL Model: 0/9 Service Classification : Breakdown Call PMS 🗌 **Cust.Training** Calibration Suton apply Not warn puggl Action Taken: Child and found Suctor apply was damyal, Motor was Rusty, It connet been Reput Spare Required Completed ____ Requested Spare Replaced PR Number **Part Number** Qty. Description 1. 2. 3. Start Time **End Time** Date Cyrix Engineer 19/8/23 10:am 11:000 Completed Pending Customer Remark Service Engineer Name : Lyon)09 Customer Name ; MIDI P. JOSP Signature : Signature (19/8/23 Date: Contact Number: 9944755839

Designation: 300

Hospital Seal:





VOUCHER OR INVOICE BE	PPERROTUS	The state of the s		
Ver II De	E 121	JPT CONDUMNED	BALANCE AITER EACH TRANSACTION	INITIALS OF RECEIVING
200	1801 trace 8 (578		_	
- 13/10/2003 they trans	Red Grom 8 Tore 1 Groully model 5.5 Top)		R	
28/04/2005 Rd for	for on store 114		16	
107/2005 Grow 15	5 Me. OP. Willials		68	50000
16 (a) 2022 To m	(Stock page 34) Periodo		r)	64

8 8 P