


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Erodekulam
2	Name of Hospital	THQH Angamaly
3	Name of Equipment with Make, Model and Serial Number	Bp apparatus Beuser BM27
4	Equipment ID/ Barcode	07226715
5	Date of purchase/ Year of manufacture	20/12/2017
6	Warranty details	NA
7	*AMC/ CAMC Period agreed at the time of purchase	NA
8	Date of breakdown/ Date of registration of complaint	9/11/2023
9	Action taken	Checked and Battery leakage and good short, Battery charger rusted identified.
10	Present status of the equipment (Fully damaged / partially damaged)	fully damaged
11	Recommendations for repair (required service details)	not recommended for service Main board and battery charger fully damaged
12	Cost of spares (specify parts and cost)	Nil

13	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	2,200
14	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX.	Cyrix Service report
15	Reasons for recommending the equipment as BER	Main Board and Battery chamber fully damaged due to battery leakage and as per tender condition. 5.3.19.1 minimum years of warranty meets
16	Signature of CYRIX Authority	

*Not mandatory **#Based on the period of life and value as per the BER guidelines**

*** Attach Photograph**

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Submitted after 30 days

Devally
11/01/24

Signature of JC BM (NHM)



Date


Signature of
Superintendent/Medical Officer (i/c)

Superintendent
Taluk Hospital, Angamaly



**BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAMME
UNDER
NATIONAL HEALTH MISSION**



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX
HEALTHCARE PVT LTD

No. : 153600

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility : THQH	Call Registration Date : 09/11/2023
Address : THQH Angamaly Eranakulam, Kerala	Caller ID : 79291
Ph : 8281859913	Date of Visit : 10/11/2023
	Asset No. : 0722675
	EQPT Name : Bp apparatus
	Manufacture : Bewaco Model : Bm27
	S. No. : NA Dept. : casualty

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified :

Not working Reported.

Action Taken : Checked equipment and Battery Bulbs and tested identified. Battery holder slot fully rusted and also Main board rusted. Fully damaged. Not repairable. Recommended for B.C.R.

Completed Date : 10/11/2023 Time : 2:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2. NA	NA	NA	NA
3.			

Cyrix Engineer

Date

Start Time

End Time

Yeelukulshna G.S

10/11/23

1:40pm

2:00pm

Customer Remark

Completed

Pending

Service Engineer Name : Yeelukulshna G.S

Signature :

Date : 10/11/2023

Contact Number : 8080 197230

Customer Name :

Signature :

Date : 10/11/23

Contact Number : 960564825

Designation : BNO

Hospital Seal :



STOCK REGISTER

Name of Article: B.P. Appointments
 Received from: _____
 or
 Issued to: _____
 Date: _____

Page No. 115

Date	Inv. No. or V. No.	Amount Rs. Ps.	Receipts	Issues	Balance	Remarks
14/9/18	①	Rs 2599/-			7	5
24/3/2021	①	digital Rs 1600/-				
14/3/2020	①	digital				
30/6/2020	②	LED Rs 2500/-				
20/12/2017	①	digital Rs 2400/-				
16/3/2020	②	Regulon Rs 2500/-				

CYRIX COMMERCIAL SOFTWARE PROGRAMS GROUP

TOLL FREE NO: 1800 - 428-7000

**BAR CODE - (8004-890615225)
0722675**



© 1987 Cyrix Corp. All rights reserved. No part of this publication may be reproduced without the prior written permission of Cyrix Corp.




BAUER GmbH, Solinger Str. 218,
89077 Ulm, Germany
Type: BM27
Item No.: 852.80
Measuring range: 30-280 mmHg
Power: 6V --- (4 x 1.5V AA)
IP 21



0483

SN 2020F32 / 14886



beurer



SET

⊞

-

+