


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	Kottayam
2	Name of Hospital	General Hospital Kottayam
3	Name of Equipment with Make, Model and Serial Number	Eg: Stabilizer <i>Flash Autoclave.</i> Make: Chautuo Model: 23BR Sn: BR17092805B
4	Equipment ID & Barcode	0510210
5	Date of purchase / Year of manufacture / Installation Date	30/10/2017 <sup>VOLI</sup> P-NO: 228. <i>as per main stock 28/10/2017</i>
6	Warranty details (Yes/No)	No <i>28-01</i>
7	*AMC/ CAMC Period agreed at the time of purchase	No
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	05/12/2023-ID 84025
9	Action taken	Checked card found equipment is not working
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged.
11	Recommendations for repair (required service details)	Checked with the Supplier for the spare parts, they provide us "non-repairable letter" dtd on 14/12/2023. The equipment is not repairable..
12	Cost of spares (specify parts and cost)	End of life/non repairable letter from the supplier attached.

13	Asset Value	2,76,120/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	EOL / non repairable letter from supplier attached.
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix report attached. The equipment is totally down and is not repairable.
16	Reasons for recommending the equipment as BER	The supplier provided non repairable letter and hence recommending the equipment as BER
17	Name & Signature of CYRIX Authority	 Sanish Swain


\*Not mandatory

#Based on the period of life and value as per the BER guidelines

\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Asset value - Rs 276120  
 Cost of spare - EOL Letter from OEM/supplier  
 life period - attached.  
 6 years. 3 months. (Installation date as per Mstbely 28/10/2017)  
 The machine is 6 year old and spare not available as per guidelines 7 year  
 from OEM/supplier + life period as per guidelines 7 year  
 recommended as BER

Signature of JC BM (NHM)  
  
 18/12/2024



Superintendent / Medical Officer (i/c)



Signature of / c  
 Superintendent  
 General Hospital  
 Kottayam

Date



**BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAMME  
UNDER  
NATIONAL HEALTH MISSION**



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

**CYRIX**  
HEALTHCARE PVT LTD

No. : 172456

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report**

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility : <u>GH</u>	Call Registration Date : <u>05/12/2023</u>
Address : <u>General hospital Kottayam</u>	Caller ID : <u>86025</u>
Ph : <u>9600570655</u>	Date of Visit : <u>10/12/2023</u>
	Asset No. : <u>0510210</u>
	EQPT Name : <u>Steebizer</u>
	Manufacture <u>Chaotuo</u> Model : <u>28BR</u>
	S. No <u>BR/7092805B</u> Dept. <u>OT-Main</u>

**Service Classification :** Breakdown Call  PMS  Calibration  Cust.Training

**Problem Identified :** Steebizer is not working

**Action Taken :** Checked the Steebizer and found not working properly. Tried to repair it and found difficult. contacted the OEM about the availability of spare parts. They provided us non-repairable letter dtd 15/12/2023. The equipment showing severe defect and is not repairable.

Completed  Date : ..... Time : ..... Spare Required


Spare Replaced  Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Sanish Swan</u>	<u>10/12/23</u>	<u>11:00 am</u>	<u>12:00 pm</u>

**Customer Remark** Completed  Pending

<b>Service Engineer Name :</b> <u>Sanish Swan</u> <b>Signature :</b> <b>Date :</b> <u>10/12/2023</u> <b>Contact Number :</b> <u>996646577</u>	<b>Customer Name :</b> <u>Min</u> <b>Signature :</b> <b>Date :</b> <u>10/12/2023</u> <u>MINI JOS E PV</u> <b>Contact Number :</b> <u>Genid Nursing officer</u> <b>Designation :</b> <b>Hospital Seal :</b> <u>9600570655</u>
--	---





# KERALA SURGICAL EQUIPMENT CO

*Everything in Hospital Needs Under One Roof!*

## NON -REPAIRABLE LETTER

14-12-2023

To,

CYRIX HEALTHCARE

**Sub :- Servicing of Flash Autoclave**

**Ref: GH Kottayam**

**Make :- Chaotuo**

**Model :- 23 BR**

**Sn :- BR17092805B**

Sir,

With reference to above, one number of Flash Autoclave having severe defects. Hence we suggest that, the service of this equipment is not reasonable and buy a new one.

Thanking you,

For KERALA SURGICAL EQUIPMENT CO.

*Ahobya*  
MANAGER



STOCK BOOK OF

FLASH AUTOCLAVE

NAME OF ARTICLE

Date	No and date of invoice or bill	From whom received or to whom issued	Receipt	Issue	Balance after each transaction	Initials of receiver	Remarks
23/1/11	1	BF Ad to the Supply by Kerala Hospital Kochin Tutunoor Rs 1,50,00/-	1		1	I also	Main stock Page 17 68 (254) 05 (21) 0117 Main stock p. 228 Rs. 2,76,120.00
Sp. No. 2017		Rd from Store Supply Kerala Surgical Equipments Majin Chaofu Medical Equipments Model - BR 23 WARRANTY PERIOD 3 yrs. from 28/10/17 to 27/10/2020	1		2		Barcode 68057816
Contact No. Whittak - 7407605728 9349910888							Sindy Sr. N.O
2/11/2021		Flash autoclave to Tutunoor transferred to Unservable Register Pg. No 202					NIL



**AUTOCLAVE**

**Name: Table top autoclave-model 238R**

**SN: BR17092805B**

**Max: 2.5 bar 137°C**

**220V/ 55Hz**

**1800W**

**Tianjin Chaotuo Medical Equipment Co., Ltd.**

**Add: Huayuan Industry Park, Tianjin, China**

**Tel: +86-22-83719726**

**Fax: +86-22-83719726**

210