


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

**Recommendations for Beyond Economic Repair (BER)**

**PROFORMA**

Sl. No	Particulars	Details
1	Name of District	Emmenkulam.
2	Name of Hospital	DH Aluva.
3	Name of Equipment with Make, Model and Serial Number	Fetal dopplm. make - life plus model - na SN - NN
4	Equipment ID/ Barcode	0711998.
5	Date of purchase/ Year of manufacture	14/03/18.
6	Warranty details	NA.
7	*AMC/ CAMC Period agreed at the time of purchase	NA
8	Date of breakdown/ Date of registration of complaint	14/10/23.
9	Action taken	Recommended for BER.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged.
11	Recommendations for repair (required, service details)	Board & probe faulty So it is recommended for BER.
12	Cost of spares (specify parts and cost)	nil

13	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	4000/-
14	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX.	Cyrix report.
15	Reasons for recommending the equipment as BER	* main board. * probe. * Display board malfunction.
16	Signature of CYRIX Authority	

\*Not mandatory **#Based on the period of life and value as per the BER guidelines**

**\* Attach Photograph**

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

As per the report of M/S Cyrix main board, display board and probe not working. Installed on 2018. Submitted after 30 days.

*Bevalley*  
02/12/23  
Signature of JC BM (NHM)



*[Handwritten Signature]*  
**SUPERINTENDENT**  
**DISTRICT HOSPITAL**  
Aluva  
Superintendent/ Medical Officer (i/c)

Date *29/11/2023*

**BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAMME  
UNDER  
NATIONAL HEALTH MISSION**



**SERVICE PROVIDER**  
Order No. WO-37/2021-2022/698

**CYRIX**  
HEALTHCARE PVT LTD

**No. :** 150488

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report**

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility : <u>DH Aluva</u>	Call Registration Date : <u>14/10/23</u>
Address : <u>Erna, Kulan</u>	Caller ID : <u>74767</u>
Ph : <u>9947855104</u>	Date of Visit : <u>24/10/23</u>
	Asset No. : <u>0711498</u>
	EQPT Name : <u>Fetal doppler</u>
	Manufacture : <u>Life plus</u> Model : <u>NA</u>
	S. No. : <u>NA</u> Dept. : <u>Injection op.</u>

**Service Classification : Breakdown Call**  **PMS**  **Calibration**  **Cust.Training**

**Problem Identified :** Main board failure

**Action Taken :** Checked and found that probe and main board, display failure not repairable. Recommend for RBE.

**Completed**  **Date :** 24/10/23 **Time :** 10:00 AM **Spare Required**

**Spare Replaced**  **Requested**

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrux Engineer	Date	Start Time	End Time
<u>Alwin</u>	<u>24/10/23</u>	<u>10:00 AM</u>	<u>10:45 PM</u>

**Customer Remark**  **Completed**  **Pending**



**Service Engineer Name :** Alwin  
**Signature :** [Signature]  
**Date :** 24/10/23  
**Contact Number :** 974564723


**Customer Name :** Jessy Mathew  
**Signature :** [Signature]  
**Date :** 24/10/23  
**Contact Number :** SNO  
**Designation :** SNO  
**Hospital Seal :** SNO



# STOCK REGISTER

Name of Article..... FETAL DOPPLER DIGITAL ..... 55

Date	Received from or issued to	Inv. No. or V. No.	Amount		Receipts	Issues	Balance	Remarks	Bar Code
			Rs	Ps					
14/3/18	Received from <u>Mr. X</u>		4800	00	1		1		
	Lifelines HSN code 9018. Batch No. NB. Exp Date 12/25								
	MSR. HMC VOL. V	P. No: 26							
		Kept in crash cart.							

  
 Received  
 14/3/18