

MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

CYRIX

No.:

200668

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in **Service Report** Call Registration Date: 109288 Health Facility Caller ID : Date of Visit: Address CHC Vengoon Asset No.: 0732 588 Canalentons, keonla EQPT Name: Ph: 7039866885 Manufacture Love Model: RCH S. No. NA Dept. LIA B **Cust.Training** Calibration Service Classification : Breakdown Call PMS **Problem Identified:** Date : 214124 Time : 11:00 Am Spare Required Completed Requested Spare Replaced **Part Number** PR Number Qty. Description Motor **End Time** Cyrix Engineer **Date Start Time** 11:00 An 10:00 An **Customer Remark** Completed Service Engineer Name : Qedhu **Customer Name:** Northe TM Signature: Signature: **Contact Number:** Date: **Designation:** 8086147236 Contact Number: **Hospital Seal:**

REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details
1	Name of District	Ernakulam
2	Name of Hospital	CHC VENGOOR
3	Name of Equipment with Make, Model and Serial Number	Equipment: CENTRIFUGE Make: ROTEK Model: RCH-8 Sr.no : NA
4	Equipment ID & Barcode	104288 & 0732588
5	Date of purchase / Year of manufacture /Installation Date	21-02-2012
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	02-04-2024 (TOLL-FREE)
9	Action taken	Checked the machine and found that motor, transformer, centrifuge head and speed regulator are defective and the Machine is fully rusty
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Not recommending for repair.
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	Rs.9651
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that motor, transformer, centrifuge head and speed regulator are defective Also the machine is in fully rusted condition inside the chamber. The equipment outlived 13+years installed on 21-02-2012 and it is an old and outdated model. So recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	JIBIN THOMAS GEORGE

*Not mandatory

#Based on the period of life and value as per the BER quidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Signature of JC BM (NHM)

Superintendent / Medical Officer (i/c)

Signature of seal

Date

മെഡിക്കൻ ഓഫിസർ ഇൻചാർജ് സാമൂഹിക ആരോഗ്യ കേന്ദ്രം വേങ്ങൂർ



7100	21
A22 CENTRIFUGE	
	enhibioe
1) ROTEK M&E Laboratory ce with 12 wells - 01	7
SL: NO: 1672	
Degler Name. M8E+AH2	
2) RCH-6 IDNO. CHCV (from 0 (2+2-22) (Gwell centrific (21.02.2012)	(0.0
2) RCH-6 IDNO, CHCV	-018
(from o (2+2-22) (Gwell centon	ge)
C21.02.2012)	
3) Centrifuge (Electric) Date of From stock reg.	(1.1.2004).
chemi- Centatige (Swell)	
Chemi- Centaling CoxVI cable	'
Motor failure: not servicable Recommended for contempation Recommended for contempation	00 11
by Blomed (Co)	00006/11/22
	1







