


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No.	Particulars	Details
1	Name of District	PALAKKAD
2	Name of Hospital	PHC VANIAMKULAM
3	Name of Equipment with Make, Model and Serial Number	BP APPARATUS make: medicare model: 1018
4	Equipment ID/ Barcode	87007 & 0942289
5	Date of purchase/ Year of manufacture/Installation Date	18/05/2020
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC & CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free. 22/12/2023
9	Action taken	performed all the necessary checkings related to the machine and confirmed that the main board, vertical measurement display segment, bladder and valve has faulty. The mentioned spares need to be replaced. required further checking after the mentioned spare replacement
10	Present status of the equipment (Fully damaged / partially damaged)	FULLY DAMAGED
11	Recommendations for repair (required service details)	NO RECOMMENDATION.
12	Cost of spares (specify parts and cost)	NA


13	Asset Value	2200/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX service reports attached
16	Reasons for recommending the equipment as BER	it was providing wrong NIBP reading always with blur vertical measurement display segment and frequent chinese numerics at main board display. For this equipment spare parts is not available at market therefore quotation not attached. The machine installed on 18/05/2020 and aged 3-8 years. As considering the above mentioned reasons recommend for BER
17	Name & Signature of CYRIX Authority	Rat-firth ✓ 


*Not mandatory #Based on the period of life and value as per the BER guidelines

* **Attach Photograph**


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Main board, display damaged hence recommended for BER.


 16/01/24
 Signature of JC BM (NHM)



Date: _____


 Superintendent
 ഓഫീസർ (i/c)



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 165083

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <i>PHC VANIYAMKULAM</i></p> <p>Address <i>PALAKKAD</i></p> <p>Ph : <i>9656464685</i></p>	<p>Call Registration Date : <i>22/12/2023</i></p> <p>Caller ID : <i>87007</i></p> <p>Date of Visit : <i>26/12/2023</i></p> <p>Asset No. : <i>0942289</i></p> <p>EQPT Name : <i>BP Apparatus</i></p> <p>Manufacture <i>medicare</i> Model : <i>101B</i></p> <p>S. No. <i>Nil</i> Dept. <i>OP</i></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : *wrong reading, blue vertical measurement display segment, Random numerics at main display.*

Action Taken : *performed all the necessary checkings related to the machine and confirmed that main board, vertical measurement display segment, bladder and valve has faulty. The mentioned spares need to be replaced. Required further checkings after the spare replacement.*

Completed Date : Time : *10:30AM* Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.				
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<i>Rajith V</i>	<i>08/01/2024</i>	<i>10AM</i>	<i>10:30AM</i>

Customer Remark Completed Pending

[Handwritten Signature]
സെക്രട്ടറി
കിടപ്പുമുഖ്യമന്ത്രി
വനിതാശാഖ



Service Engineer Name : *Rajith V*
Signature : *[Signature]*
Date : *08/01/2024*
Contact Number : *9539838931*

Customer Name : *[Signature]*
Signature : *[Signature]*
Date : *24*
Contact Number : *9207378048*
Designation : *Nursing Officer*
Hospital Seal :

B1

VOLUME 2



SUB

STOCK BOOK OF EQUIPMENTS AND INSTRUMENTS

- FHC VANIYAMKULAM

NURSING OFFICER

PERIOD FROM -01/01/2008

മെഡിക്കൽ ഓഫീസർ
കുടുംബാരോഗ്യകേന്ദ്രം
വനിയാമകുളം



CODE HI
VOLUME I

SUB STOCK BOOK
EQUIPMENTS REGISTER

I CERTIFIED THAT THIS BOOK CONTAIN 110320
PAGES SERIALLY FROM 03/01/2017.
FOUND ON PHYSICAL VERIFICATION ONLY

DR. DHANYA S. *DS*

സബ് സ്റ്റോക്ക് പുസ്തകം
പരിശോധിച്ചതിന്റെ
അടിസ്ഥാനത്തിൽ



STAFF NURSE
PHC VAALIYAM KULAM

SL
സെലക്ഷൻ കമ്മിഷൻ
കുടുംബശ്രീകൾ
റാണിയാകുളം

VERIFIED
UPTO 31/10/17



P. Anil Kumar
Officer in Charge
Office of Health
✓

Bp apparatus

Date	from whom received or whom receipt issued brought forward from	Issue	Balance	Main stock	Cost	remarks.
	Page no	Volume no		Balance		
15/7/14	Physically verified		5	5		
15/7/14	found on viz	2	3	5		
	Shifted to R ₁ Volume 3			Page No 22		
01/3/18	Received from stor	1		3		
01/08/18	Issued to op	1	-	3		
				8		
29/12/20	Contamination done	4		8-4=4		
18/05/20	Received from store	1	1	1		
6/07/20	Received from store	1	1	1		
31/08/20	Received from store	1	1	1		
				<u>11</u>		
29/12/20	Contamination done	4		<u>11-4=7</u>		


Mercury less
digital bp apparatus

മെഴുതിരിക്കപ്പെട്ട
മെഴുതിരിക്കപ്പെട്ട
മെഴുതിരിക്കപ്പെട്ട






SL
മെഡിക്കൽ ഓഫീസർ
കുടുംബശ്രീ
പാണിയംകുളം



കേരള സർവ്വകലാശാല
കോളേജ് ഓഫ് ടെക്നോളജി
കോളേജ് ഓഫ് ടെക്നോളജി
679 522

മുദ്രിതം
മുദ്രിതം
മുദ്രിതം



[Handwritten signature]
മെമ്പർമാർക്ക് മാത്രം
പ്രവേശനം അനുവദിക്കുന്ന
സ്ഥലമാണ് ഇവിടം