REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details		
1	Name of District	KANNUR		
2	Name of Hospital	GH THALASSERY		
3	Name of Equipment with Make, Model and Serial Number	X-RAY MACHINE Make: ALLENGERS Model: Allengers 525FC/HT SN: 2K101150754-X		
4	Equipment ID/ Barcode	1311338 #93734		
5	Date of purchase/ Year of manufacture/Installation Date	24-12-2010		
6	Warranty details (Yes/No)	No warranty		
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC		
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free- 01-02-2024		
9	Action taken	Checked the machine and found that low clarity output getting, found problem with X-ray tube, HT Tank, HV cable. Enquired OEM for quotation		
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged		
11	Recommendations for repair (required service details)	No recommendations		
12	Cost of spares (specify parts and cost)	1- X-RAY TUBE E-7239-X (2169) with Full mechanical attachment, Manual Collimator attachment and Starter board kit- 218400.00/- 2- TANK SINGLE 325\525 MA COMPLETE [ASSEMBLED] (5554)- 179200.00/- 3- HV CABLE- 56000.00/-		

13	Asset Value	495000/-		
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	91.63%		
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & OEM Quotation attached		
16	Reasons for recommending the equipment as BER	Checked the machine and found that low clarity output getting, found problem with X-ray tube, HT Tank, HV cable. Enquired OEM for quotation. Equipment installed on 24-12-2010 aged up to 13 years and 2 months. Repairing cost is 91.63% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.		
17	Name & Signature of CYRIX Authority	SARANG K M		

*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

The Mallie & identified that low quality of polaries

X-ray tube, HT talk, HV cuble failure. The machine

aged upe 13 years above its QH also failed in

The machine

mac

Dinga baran Int Radiogrephi

Date: 4 120

Signature of Superintendency and Car Officer (i/c)



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

2-2-24

Contact Number: 9995521436

Date:

No.: 184895

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY AERB Approved Service Agency Service Report 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in Call Registration Date: 1-2-24 Health Facility (a.H. Thalasserry Caller ID: 93734 Date of Visit: 2-2-24 Address Thalasseny Asset No. : 1311338 Kannur EQPT Name : X- Yay Machine Ph: 9495669140 Manufacture Allengens Model: 525FC/HT S. No. 2KIDIISOTS4-XDept. Radiology Service Classification : Breakdown Call PMS Calibration **Cust.Training** Problem Identified: Low quality image output Action Taken: checked the machine and found that low danity output getting, Found problem with x-may tube, HT tank, MY Cable Enquired OFM for quotation Completed Date : 2-2-24 Time : 12:50Pm Spare Required Spare Replaced Requested Description Qty. **Part Number** PR Number 1. 2. 3. Cyrix Engineer Date **Start Time End Time** Rasilray 2-2-24 12:30Pm 12:50Pm **Customer Remark** Completed Pending Menden! Service Engineer Name : Ra Silva Customer Name: Signature: Signature: Pasibel 2.2.24 Jumber: 9495669140

Contact Number :

Hospital Seal:

Designation: Ladiograph 1







Head Officé: S.C.O. 212-213-214, Sector 34-A Chandigarh-U.T. 160 022 (INDIA) Tel.: +91-172-3012280-84 Fax:+91-172-2621912, 2621913 E-mail: sales@allengers.net Web: www.allengers.com

Date: 15/02/2024

To, **Cyrix Healthcare (P) Ltd** 30/641B, Vandipetta Rd, near SBI Bank,, Poonithura, Maradu, Ernakulam, Kerala-682038

Sub: Estimate for Tube head-HT Tank and HV Cable for GH Thalassery

Dear Sir,

As per the above mentioned subject please find the below estimate.

Kindly go through the same and we are expecting your work order at the earliest.

SI No.	Item description	QTY	Price	Taxes	Amount in Rs
1	X-RAY TUBE E-7239-X (2169) with Full mechanical attachment, Manual Collimator attachment and Starter board kit.	1	195000	12%	218400.00
2	TANK SINGLE 325\525 MA COMPLETE [ASSEMBLED] (5554)	1	160000	12%	179200.00
3	HV CABLE	2	50000	12%	56000.00
	453600.00				

*Above information is not an invoice and only an estimate of services described above. If prices and tax change or additional parts, and labor are required, we will inform you prior to proceeding with the work. Kindly confirm your billing address (as mentioned above) and intimate us if any changes required. This is not included our service charges.

Kindly give an approval for the service in written (Work order) to following address/ Email id, so that we can perform the Job accordingly.

Payment: 100% in advance.

Our GSTIN number: 03AABCA2332H1ZE

For Allengers Medical Systems Ltd

Authorized Signatory

Allengers Medical Systems Ltd, 5B, 5th Floor, Hedge house

Edapally-Palarivattom Road-682025

9946669084/0484-4035626/ker.service@allengers.net

ISO 9001. 2008 ISO 13485. 2003 AFRE APPROVED BIS APPROVED

G H Thalassery Quotation - Spares for Allengers X Ray Unit 525

From: Aneesh P B mklse@cyrix.in

To: sarangcyrix@gmail.com sarangcyrix@gmail.com

Cc: Blesson Jose zm2.klbemp@cyrix.in,

Project Manager KLBEMP

pm.bempkl@cyrix.in

Sent: Thursday, 15 February at 4:13 pm

Dear Sarang,

PFA trail mail for spare parts to GH Thalassery.

Kind Regards,
Aneesh P B
Deputy Manager - Service

Ph: 9744827770

Cyrix Healthcare Pvt Ltd | 30/641 B | Pettah

Jn | Poonithura | Cochin -38 | Kerala | India

Ph: 9744555073 | M 9072522093 | W www.cyrixheal

thcare.com

KERALA || KARNATAKA || UTHAR PRADESH || TAMIL

NADU || KUWAIT || KSA ||UAE

From: RENJITH < ker.service@allengers.net > Sent: Thursday, February 15, 2024 4:12:09 PM

To: Aneesh P B < mklse@cyrix.in>

Subject: RE: Request for Quotation - Spares for

Allengers X Ray Unit 525

Dear Aneesh,

Please find the attached estimate.

Thanks and regards

RENJITH RAMESH C | Executive, Office Operations | Cochin Branch

Allengers Medical Systems Ltd

5-B, 5th Floor, Hedge House (Pearl Opulence), Edapally-Palarivattom Road, Ernakulam – 682 025

Tel (484) 4035626 | mobile <u>+91 7087029374</u>| Toll free 1800 266

8800

www.allengers.com | ker.service@allengers.net

Confidentiality Note: This e-mail and any attachments are confidential and may be protected by legal privilege. If you are not the intended recipient, be aware that any disclosure, copying, distribution or use of this e-mail or any attachment is prohibited. If you have received this e-mail in error, Please notify us immediately by returning it to the sender and delete this copy from your system. Thank you for your cooperation.

P.Please consider the environment before printing this e-mail!

From: Aneesh P B [mailto:mklse@cyrix.in]
Sent: Thursday, February 15, 2024 7:39 AM

To: RENJITH

Subject: Request for Quotation - Spares for Allengers X

Ray Unit 525

Dear Renjith,

I hope this email finds you well.

I am writing to request a quotation for the following spare parts required for our Allengers X Ray unit 525 installed at G H Thalassery. We kindly request your earliest attention to this matter.

- **Equipment:** Allengers 525
- **Serial Number: ** 2K101150754
- **Location:** G H Thalassery
- **Required Spares:**
- 1. H T Transformer
- 2. Canon X Ray Tube
- 3. HV Cable 1 pair

Please provide us with a detailed quotation, including the unit prices, taxes, and shipping costs, at your earliest convenience.

We appreciate your prompt response and look forward to receiving your quotation.

Best regards,

Aneesh P B
Deputy Manager - Service
Cyrix Healthcare Pvt Ltd
30/641 B, Pettah Jn, Poonithura, Cochin -38,
Kerala, India

Phone: 9744827770

Website: www.cyrixhealthcare.com


KERALA || KARNATAKA || UTHAR PRADESH || TAMIL NADU || KUWAIT || KSA || UAE











SENERAL HOSPITA,

dinja karan Radiographili



SINO:	Date	Hem Received	
Rona	4 RADOOS 41-83.	Hem Received	Page 11 whi
I ·	24-12-2010	ALLENGERS - 500m A X-RAY MACHINE	B. 512904
		AND 175 ACCESSORIES	
		issuinfe	De Jens
-		122 no 122	2.12
		bµatw ₃	toro Keeps
	GNERAL HOE	1 2 24	Dinya Care Radiograph
		A 312	Mar o grafin
	870 10	Superintendent SENERAL HOSPITAL SHALASSERY • 670 101	
•		West-Angles - God 14	
	•		
			1-