


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	THQH PAYYANUR
3	Name of Equipment with Make, Model and Serial Number	REFRIGERATOR Make: VIDEOCON Model: ECOCOOL SN: N/A
4	Equipment ID/ Barcode	1321108 #91766
5	Date of purchase/ Year of manufacture/Installation Date	14-01-2010
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 19-01-2024
9	Action taken	Checked the Refrigerator and found that equipment not cooling , found problem with compressor, filter, condenser. Enquired for quotation
n	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	Compressor-6300/- Filter- 600/- Gas charging -2400/- Condenser change- 1800/-

13	Asset Value	6500/-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	170%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & quotation attached
16	Reasons for recommending the equipment as BER	Checked the Refrigerator and found that equipment not cooling , found problem with compressor, filter, condenser coil . Equipment installed on 14-01-2010 aged up to 14 years and 1 month. Repairing cost is 170% both criteria for RBER met. As per tender clause 5.3.14.1 we recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	SARANG K M 


*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identified that compressor, filter, condenser coil are damaged. Aged up to 14 years above. As per quotation the service cost economically not feasible as per quotation, so recommended for BER as per BER protocol.

 Signature of JC BM (NHM)
15/2/2024

Beena Kneriam
Bees
Nursing Officer
T-H Payyanur

Date: 9/3/24



CONSULTANT BIOMEDICAL
NATIONAL HEALTH MISSION
KANNUR - 670002

Signature of
Superintendent/Medical Officer


SUPERINTENDENT
TALUK HOSPITAL
PAYANUR, KANNUR DT.



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 174323

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>THOH Payyanur</u>.....</p> <p>Address <u>Kannur</u>.....</p> <p>Ph : <u>9847949526</u>.....</p>	<p>Call Registration Date : <u>19-01-2024</u>.....</p> <p>Caller ID : <u>91766</u>.....</p> <p>Date of Visit : <u>20-01-2024</u>.....</p> <p>Asset No. : <u>1321108</u>.....</p> <p>EQPT Name : <u>Refrigerator</u>.....</p> <p>Manufacture <u>Videocan</u> Model : <u>Ecocool</u>.....</p> <p>S. No. <u>NA</u> Dept. <u>FM Ward</u>.....</p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Found that equipment is not cooling

Action Taken : Checked refrigerator and found that equipment not cooling, found problem with compressor, filter, condenser. Enquired for quotation.

Completed Date : 20-01-2024 Time : 11:00AM Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.				
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Nitheesh P</u>	<u>20-01-2024</u>	<u>10:00AM</u>	<u>11:00AM</u>

Customer Remark Completed Pending



Handwritten signature
SUPERINTENDENT
TALUK HOSPITAL
PAYANUR, KANNUR DT.

<p>Service Engineer Name : <u>Nitheesh P</u></p> <p>Signature : <i>[Signature]</i></p> <p>Date : <u>20-01-2024</u></p> <p>Contact Number : <u>9301871531</u></p>	<p>Customer Name : <u>Beena</u></p> <p>Signature : <i>[Signature]</i></p> <p>Date : <u>20/1/24</u></p> <p>Contact Number : <u>9847949526</u></p> <p>Designation : <u>NID</u></p> <p>Hospital Seal :</p>
--	---



Fwd: PFC

1 message

Sarang KM <arangcyrix@gmail.com>
To: avinash t <avinashtcyrix@gmail.com>

Mon, 11 Mar, 2024 at 9:09 pm

FYI

----- Forwarded message -----

From: **ECOTONIC AUTOMATION SOLUTIONS** <ecotonicsolutions@gmail.com>

Date: Tue, Feb 27, 2024 at 4:26 PM

Subject: PFC


To: Sarang KM <arangcyrix@gmail.com>

--
Thanks & Regards

Sarang.k.m
Divisional Incharge|North Zone
Bemp-Kerala
Mobile : **+91 7593847150**
Email : arangcyrix@gmail.com

CYRIX HEALTHCARE (P) LTD
30/641B | Petta | Punithura | Kochi | Kerala- 682038
www.cyrixhealthcare.com

P Save Environment, Please do not print this e-mail unless it's essential



കമ്മ്യൂണിറ്റി ഹെൽത്ത്
 പ്ലാനിംഗ്
 ന്യൂനതകൾ
 പരിഹരിക്കാനുള്ള
 ഉദ്യമങ്ങൾ
 നടപ്പിലാക്കുന്നു



Handwritten signature

SUPERINTENDENT
 TALUK HOSPITAL
 PAYYANUR, KANNUR DISTRICT

CYRIXTM HEALTH CARE PVT LTD **BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME (BEMP)**

TOLL FREE NO: 1800 - 425-7669

BAR CODE - (8004-890615225)

1321108