


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KANNUR
2	Name of Hospital	DH KANNUR
3	Name of Equipment with Make, Model and Serial Number	ULTRASOUND MACHINE Make: GE Model: LOGIQ P3 SN: 62247WS4
4	Equipment ID/ Barcode	1311085 #96058
5	Date of purchase/ Year of manufacture/Installation Date	24-03-2015
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free 01-12-2023
9	Action taken	Checked the machine and found that Machine is not switching ON, found problem with mainboard, enquired OEM for quotation
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	N/A

13	Asset Value	484441/-
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	N/A
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service report & OEM End of life letter attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that Machine is not switching ON, found problem with mainboard, enquired OEM for quotation. Equipment installed on 24-03-2015 aged up to 8 years 11 Months, oem informed that this machine is obsolete model, end of life letter issued. As per tender clause 5.3.14.2 we recommending the equipment for condemnation.
1	Name & Signature of CYRIX Authority	AVINASH T 


*Not mandatory

#Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

checked & identified that machine main board issue and aged up to 8 years above. OEM reported as a obsolete model. so recommended for BER as per BER protocol.


Signature of JC BM (NHM)
15/03/2024


CONSULTANT BIOMEDICAL
NATIONAL HEALTH MISSION
KANNUR - 670002

Nisha. V.V Nishu

Nursing officer. Govt

Date: 16.03.2024




Signature of
Superintendent/Medical Officer (i/c)
SUPERINTENDENT
DISTRICT HOSPITAL
KANNUR



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 189131

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility <u>DH Kannur</u></p> <p>Address <u>Kannur</u></p> <p style="padding-left: 100px;"><u>Kerala</u></p> <p>Ph : <u>9947447318</u></p>	<p>Call Registration Date : <u>01/12/23</u></p> <p>Caller ID : # <u>96058</u></p> <p>Date of Visit : # <u>02/12/23</u></p> <p>Asset No. : # <u>1311085</u></p> <p>EQPT Name : # <u>ultrasound machine</u></p> <p>Manufacture <u>G.E</u> Model : <u>LOGIQ P3</u></p> <p>S. No. <u>62247WS4</u> Dept. <u>Laboratory</u></p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : # machine is not switching on

Action Taken : # Checked the machine and found that machine is not switching on. found problem with main board. enquired OEM for quotation.

Completed Date : 02/12/23 Time : 11:30am Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Shebin vs - S.BME</u>	<u>02/12/23</u>	<u>10:50am</u>	<u>11:30am</u>

Customer Remark Completed Pending

Service Engineer Name : Shebin vs
Signature :
Date : 02/12/24
Contact Number : 7593847149

Customer Name : Nisha.v.v.
Signature :
Date : 02/12/23
Contact Number : 9947447318
Designation : SUPERINTENDENT
Hospital Seal :



WIPRO GE HEALTHCARE
CIN: U33111KA1990PTC016063
No. 4 Kadugodi Industrial Area,
Bangalore 560067, Karnataka
India, T: 91 80 4180 1000
F 91 80 4180 1290
website: www.gehealthcare.in

Letter No: 2021/US/LOGIQ P3/M8/381

To,

DIST HOSPITAL KANNUR
SUPERINTENDENTRICT HOSPITAL
Kannur
KANNUR, KERALA -670001

Subject: Notice of LOGIQ P3 (Initial Version) - Planned Product Discontinuance (M8)/ ASSET# GIB_S_IN_083037860050010/ PRODUCT ULOP3A - LOGIQ P3

Dear Customer:

As a member of the GE family through your purchase of LOGIQ P3 (Initial Version), we want to thank you for your trust and confidence in our products. We are taking this opportunity to update you on our LOGIQ P3 (Initial Version) product lifecycle and to inform you of the intention of GE Healthcare - Primary Care Ultrasound to fully discontinue service and part support for this product as of September 2021.

Analyzing fast technology shift in recent years, GE Healthcare have determined sustained supply of high-quality parts to support your system cannot be guaranteed. We want to offer you the best service possible but given the parts position we will only be able to offer a service contract on the basis of best endeavors.

If you have a system currently under service contract with GE Healthcare, we will be contacting you shortly to discuss available service options. As you prepare to replace your equipment, we will work with you to assess your options and define a solution to best balance your clinical and budgetary needs. We recommend you contact your local GE Healthcare sales or service representative or Call Product Sales toll free # **1800-102-2977** or Call Service toll free # **18004257255/18004258025**

Thank you for your continued support and confidence in the Vivid brand products. We value and appreciate the continued opportunity to support you in your medical equipment and service needs.

For WIPRO GE HEALTHCARE PVT. LTD.,
Sincerely,

Naresh Pradhan
Manager - Service Operations
WIPRO GE HEALTHCARE PVT. LTD.

Fwd: EOL letter for GE Logiq P3 - D H Kannur 1311085

1 message

Sarang KM <sarangcyrix@gmail.com>
To: avinash t <avinashcyrix@gmail.com>

Sun, Mar 10, 2024 at 11:25 PM

FYI

----- Forwarded message -----

From: **MD, Sooryavarma (Consultant)** <Sooryavarma.MD@gehealthcare.com>
Date: Tue, Feb 27, 2024 at 10:40 AM
Subject: RE: EOL letter for GE Logiq P3 - D H Kannur
To: Aneesh P B <mklse@cyrix.in>
Cc: Blesson Jose <zm2.klbemp@cyrix.in>, sarangcyrix@gmail.com <sarangcyrix@gmail.com>

Hi Aneesh,

Pls find the attached EOL letter for your reference!

Regards,

Sooryavarma MD

Service Sales Manager

Wipro GE Healthcare Pvt. Ltd.

Cochin, Kerala.

PH: +91-9497152800



From: Aneesh P B <mklse@cyrix.in>
Sent: Friday, February 23, 2024 3:08 PM
To: MD, Sooryavarma (Consultant) <Sooryavarma.MD@gehealthcare.com>
Cc: Blesson Jose <zm2.klbemp@cyrix.in>; sarangcyrix@gmail.com
Subject: EOL letter for GE Logiq P3 - D H Kannur

WARNING: This email originated from outside of GE HealthCare. Please validate the sender's email address before clicking on links or attachments as they may not be safe.

Dear Soorya,

Please provide the EOL letter for the GE logiq P3 installed in D H Kannur as soon as possible.

System ID: 083037860050010

Thank you for your prompt attention to this matter.

Best regards,

Aneesh P B

Deputy Manager - Service

Ph: 9744827770

Cyrix Healthcare Pvt Ltd | 30/641 B | Pettah Jn | Poonithura | Cochin -38 | Kerala | India

Ph: 9744555073 | M 9072522093 | W www.cyrixhealthcare.com

KERALA || KARNATAKA || UTHAR PRADESH || TAMIL NADU || KUWAIT || KSA || UAE

--

Thanks & Regards

Sarang.k.m

Divisional Incharge|North Zone

Bemp-Kerala

Mobile : **+91 7593847150**

Email : sarangcyrix@gmail.com


CYRIX HEALTHCARE (P) LTD

30/641B | Petta | Punithura | Kochi | Kerala- 682038

www.cyrixhealthcare.com



Save Environment, Please do not print this e-mail unless it's essential

 **GIB_S_IN_083037860050010.pdf**
162K



9a
 (01/02/24)
 SUPERINTENDENT
 DISTRICT HOSPITAL
 KANNUR

Leenath - K
 Nursing Officer Gr I
 Leenath