AIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAM (BEMP)

Recommendations for Beyond Economic Repair (BER)

PROFORMA

SI. No	Particulars	Details				
1	Name of District	KOZHIKODE				
2	Name of Hospital	THQH KUTTIADI				
3	Name of Equipment with Make, Model and Serial Number	Equipment : Suction Apparatus Make : N/A Model : N/A SN : N/A				
4	Equipment ID & Barcode	105127 & 1120941				
5	Date of purchase / Year of manufacture /Installation Date	08-05-2019 (Actual installation date is 09-01-2017, stock book attached for reference)				
6	Warranty details (Yes/No)	No warranty				
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC				
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	06/04/2024 (Toll free)				
9	Action taken	Checked and found that rusted and weakened body structure, motor dysfunction and damaged suction bottle, need to replace this spares				
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged				
11	Recommendations for repair (required service details)	Not recommending for repair				
12	Cost of spares (specify parts and cost)	N/A				

	13	Asset Value	10800 /-
	14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	N/A
,	15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached
	16		The Suction Apparatus has deteriorated significantly, with rusted and weakened body structure, posing a hazard to patients and users. The extensive rusting and physical debilitation compromise the apparatus's integrity, while the motor dysfunction and damaged suction bottle jars exacerbate its unsuitability for medical use. The amalgamated toll exacted by these imperfections highlights an irrevocable estrangement from utility, posing potential harm to patients and operational efficiency. In software installation date is 08.05.2019 As per the stock book Machine is installed on 09.01.2017 aged up to 7 years it's a donated equipment. Therefore, we recommend immediate condemnation and to mitigate risks and uphold patient safety.
	17		ARUN KK

^{*}Not mandatory #Based on the period of life and value as per the BER guidelines

Remarks and Recommendations of Junior Consultant (Biomedical) NHM: Suchio Checkel & Yapaihah Hemachine and found that machine rousted of body streeture damaged. Motors & suctions bottle, jess one damaged. Machine installed on 9/01/2017. So recommended for Consultars Bin Mare of Trois BMr (NHM)

National Health Mission Kczhikode

Seal

Date

^{*} Attach Photograph



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER Tender No. WO-37/2021-2022/698

CYRIX

No.:

184682

HEA	LTHCA	REPVT	LID	18468	,-
ISO 13485 : 2012 & ISO 9001-20	008 CERTIFIE	ED COMPANY A	ERB Approved Se	rvice Agency	1
Service Report 30/64 1 B, Petta Ju Ph : 98472 99500 Websi	ite : www.c	onithura, Koch cyrix.com E	i - 682 038, Kera ·mail : bemp.kl@d	ila cyrix.in	
Health Facility		Call Registra	ntion Date :	6141	
Address KUTTIADY		Date of Visit	: 81	4124	
KOZHIKODE	STREET, STREET		112		NAME OF STREET OF STREET STREET, STREET STREET
			: Succ		
Ph: 9746260450			v e		
			<i>№</i> D		
Service Classification : Breakdown			Calibration		Training
mahlam II wa i					-
roblem Identified:Machin	ne r	10t ge	Hing (2N	
			T,		
action Taken : Checked	2 1	G	1		
TOTOLI TARELLE LA CALLACTE	902.0		1 11		
		Co.unc	the.	issue	1. then
onformed Sucction	0r	2.0.107	rusted	and	burned.
earing Stuck and	also	noton Suc	rusted	and	burned.
earing Stuck and Partis are rusted	also	noton Suc	rusted	proxous	burned, body
earing Stuck and Partis are rusted	also	noton Suc	rusted	proxous	burned, body
conformed Sucction searing Stuck and Part is are rusted need to replace these	o m also bol Spax	ttle for	rusted ction ou od tub Gryther c	Prand prandus ing des heckng	burned, body ective so of Machine
earing Stuck and Part is are rusted need to replace these completed \(\text{Date} : 8.14.1.24 \).	o m also bol Spax	ttle for	rusted ction ou od tub Gryther c	Prand prandus ing des heckng	burned, body
conformed Sucction pearing Stuck and Part S are rusted need to replace these completed Date: 8.14.1.24 T spare Replaced Requested	o m also bol Spax	ttle for	rusted ction ou nd tub Further o	Prand Prandus ing de s heckng Spare	burned. body cative so OF Machine Required
Description	o m also bol Spax	ttle for	rusted ction ou od tub Gryther c	Prand Prandus ing de s heckng Spare	burned, body ective so of Machine
Conformed Sucction Dearing Stuck and Part S are Tusted Description Conformed Sucction Stuck and Part Sucction Stuck and Part Sucction Stuck and Stuck and Fusted Sucction Stuck and Fusted Sucction Part Sucction Stuck and Fusted Sucction	o m also bol Spax	ttle for	rusted ction ou nd tub Further o	Prand Prandus ing de s heckng Spare	burned. body cative so OF Machine Required
part S are rusted ped to replace these completed Date: 8.4.1.24 T pare Replaced Requested Description	o m also bol Spax	ttle for	rusted ction ou nd tub Further o	Prand Prandus ing de s heckng Spare	burned. body cative so OF Machine Required
Conformed Sucction Searing Stuck and Partis are rusted need to replace these completed Date: 8.14.1.24 To Spare Replaced Requested Description	o m also bol Spax	ttle for	rusted ction ou nd tub Further o	Prand Prandus ing de s heckng Spare	burned. body cative so OF Machine Required
Description	O	ttle of Axoopm	Part Num	PPATOHUS PPATOHUS PPATOHUS Spare Spare Start Time	burned. body cotive so of Machine Required PR Number
Contarmed Sucction Searing Stuck and Partis are rusted need to replace these completed Date: 8.4.1.24 To Spare Replaced Requested Description	O	ttle for	Part Num	PPATOHUS PPATOHUS PPATOHUS Spare Spare Start Time	burned. body cotive so OF Machine Required [
Cyrix Engineer	O	Coton Such Such Such Runkk	Part Num	PPATOHUS PPATOHUS PPATOHUS Spare Spare Start Time	burned. body ective so of Machne Required PR Number End Time 4.00Pm.
earing Stuck and Part S are rusted need to replace these completed Date: 8/4/24. T spare Replaced Requested Description	O	ttle of Axoopm	Tusted Chian Ou Chian Ou Pub Further C Part Num Date	PPATOHUS PPATOHUS PPATOHUS Spare Spare Start Time	burned. body ective so of Machne Required PR Number End Time 4.00Pm.
Cyrix Engineer	O	Coton Such Such Such Runkk	Part Num Date 8 14 12 9	PPAROLUS PPAROLUS Shecisng Spare Start Time	burned. body ective so of Machne Required PR Number End Time 4.00Pm.
Cyrix Engineer	O	Coton Such Such Such Runkk	Part Num Date 8 14 12 9	PPAROLUS PPAROLUS Shecisng Spare Start Time	burned. body ective so of Machne Required PR Number End Time 4.00Pm.
Cyrix Engineer Sucction Sucction Sucction Sucction Sucction Sucction Sucction Part IS are rusted Description Cyrix Engineer	O	Qty. Completed	Part Num Date 8 14 12 9	Start Time	burned. body ective so of Machne Required PR Number End Time 4.00Pm.
Cyrix Engineer Sucction Sucction Sucction Sucction Sucction Sucction Sucction Part S are rusted Description Cyrix Engineer	O	Qty. Custome	Part Num Date 8 14 12 9 Pr Name: 800	Start Time	burned. body ective so of Machne Required PR Number End Time 4.00Pm.
Cyrix Engineer Customer Remark Customer Remark Customer Remark Customer Remark	A KK	Qty. Custome Signatur	Part Num Date 8 14 12 9 Pr Name: Bare: Bare: Bare	Start Time	burned. body ective so of Machne Required PR Number End Time 4.00Pm.
Conformed Sucction Searing Stuck and Part S are rusted need to replace these completed Date: 8.4.1.24 To spare Replaced Requested Description Cyrix Engineer Customer Remark Service Engineer Name: ARUN Signature: 2.1.2.4	A KK	Qty. Custome Signatur Date:	Part Num Part N	Start Time Start Time	burned body control of Machine Required Time
Contarmed Sucction Searing Stuck and Part S are rusted need to replace these completed Date: 8.14.1.24 To spare Replaced Requested Description Cyrix Engineer Customer Remark Service Engineer Name: ARUN Signature: ARUN	A KK	Qty. Custome Signatur Date: Contact	Part Num Part N	Start Time Start Time Pending Manual Properties Start Time Soop manual Properties Pending Manual	End Time
Cyrix Engineer Customer Remark Customer Remark Customer Remark Customer Remark Customer Remark	A KK	Qty. Custome Signatur Date: Contact	Part Num Part N	Start Time Start Time Pending Manual Properties Start Time Soop manual Properties Pending Manual	burned body control of Machine Required Time

Date	O. P.	CK ACCOUNT FOR			CHARGO	encela	15
	No.	Name and Address		l .	1		
2210/98	Par	eived from the gree P	Age	Псоме	Receipt	Issue	Balance
	23/	3/12 (Scot for To	SP. NI		1_	1	diff.
12/2/10		100 60	Said) 6 mi	orih	5XLV	orvil
Stalid	REC	FLUED FROM PAINS AND (Postable 2	Pa.	A/ADM/E	10/1		Z(1)
oleliu	-	Postable & Ceaup Regul	uction	apparek	2)(8	162h	30/11
-1-114.	-16	oms fer out to 0	TC	HABLE. 1		-1-/	1.
	Ro				1621	D _	Mil.
		cesived booms poins					
9/1/17	-	Received follow stoke.					Į
31,		Doorstad by Face Book 2508	2/				
31/10/18	· -	Conclamination clome GO					
	-	PET OFCHET NO. CO/1605/18					
1/3/19		dt.25/10	11.2 7		:		1 Malson
11 .11.		1 a. O.M. 60 O.L	un).				2,
al I.							
विसिर्ग		Rel from Store	<u> </u>				2 - 1
6/02/202	4 To	out to 8 to ck registes.	20.61	Dage 61	1791	Mal.	n M
14-1-02	/	000 10 019 90 pages 01 05.5	LULV.	ragion		V.UL.	W SIV
			1				AA
		क्रिक्शिक्षां साव	തുപത്ര	030			m
		E CL	O AL	*		DER	NTENDEN HOSPIT HOSPIT TIADY:6735
		San Walled Co.	de con	nel-61se		ALU	TIADY:673
						KO.	
		•					
		Y	1				

