

**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

**Recommendations for Beyond Economic Repair (BER)**

**PROFORMA**

<b>Sl. No</b>	<b>Particulars</b>	<b>Details</b>
1	Name of District	PALAKKAD
2	Name of Hospital	THQH OTTAPALAM
3	Name of Equipment with Make, Model and Serial Number	DRILL SYSTEM Make : STRIKER Model: SYSTEM 6 SN: 7208000000
4	Equipment ID/ Barcode	0921312 #108202
5	Date of purchase/ Year of manufacture/Installation Date	25-06-2018
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	25-04-2024 toll free
9	Action taken	Checked the machine Found heating. Problem with battery and drill hand piece. Requested OEM support
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	RS. 732338/-
14	* Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Service report attached EOL letter attached
16	Reasons for recommending the equipment as BER	Checked the machine found heating problem with battery and drill hand piece . Equipment installed on 25-06-2018 aged upto 5 years 9 months. OEM informed that this model is obsolete.service not available. End of life letter issued. As per tender clause 5.3.14.2 we recommending the equipment for condemnation
17	Name & Signature of CYRIX Authority	AKHILESH P

\*Not mandatory

#Based on the period of life and value as per the BER guidelines

\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Equipment installed on 25-6-2018. RBER  
Criteria not met.



*Ashok*  
16/05/24  
Signature of JC BM (NHM)

Date: 31/5/2024



*Amith Kumar*  
Signature of  
Superintendent/  
Medical Officer (i/c)  
Taluk Head Quarters Hospital  
Ottapalam





**BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAMME  
UNDER  
NATIONAL HEALTH MISSION**



SERVICE PROVIDER  
Tender No. WO-37/2021-2022/698

**CYRIX**  
HEALTHCARE PVT LTD

No. : 217319

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

**Service Report** 30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility : THQH	Call Registration Date : 25-04-2024
Address : Ottapalam palakkad	Caller ID : 108202
Ph : 09778528122	Date of Visit : 26-04-2024
	Asset No. : 0921312
	EQPT Name : DRILL SYSTEM
	Manufacture STRIKER Model : SYSTEM 6
	S. No. 7208000000 Dept. OT

Service Classification : Breakdown Call  PMS  Calibration  Cust.Training

Problem Identified : Heating Problem.

Action Taken : Checked the machine Found Heating Problem with Battery and drill hand piece. Requested OEM support

Completed  Date : 26-4-2024 Time : 11:00am Spare Required

Spare Replaced  Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
MIDHUN RAJ K	26-4-2024	10:00am	11:00am

Customer Remark  Completed  Pending

Service Engineer Name : MIDHUN RAJ	Customer Name : Needhishe A.
Signature : <i>[Signature]</i>	Signature : <i>[Signature]</i>
Date : 26-4-24	Date : 26/4/24
Contact Number : 9072522081	Contact Number : Nursing officer
	Hospital Seal : 75588629 Superintendent



Taluk Head Quarters Hos  
Ottapalam



To:	Stryker System 6 Customers & Sales Representatives
From:	Stryker India Marketing
Subject:	End of Service Support Notification
Date:	September 29th, 2021

Dear Valued Customer,

Stryker is committed to providing high quality service for the life of our products. Certain products within the Stryker Powertools portfolio are approaching their end of life status and as a result, we will no longer repair those specific products. Products reach end of life status because they have exceeded their useful life or due to a supplier restraint, which can include: component obsolescence, manufacturing obsolescence, and/or technology obsolescence.

Please be aware that the System 6 series has been made obsolete and will no longer be made serviceable with effect from December 31, 2021. Beyond this date, service will only be available on best of efforts basis.

Part numbers which will no longer be serviced or sold:

- 6203-000-000 (System 6 Single Trigger Rotary)
- 6205-000-000 (System 6 Dual Trigger Rotary)
- 6206-000-000 (System 6 Reciprocating Saw)
- 6207-000-000 (System 6 Sternum Saw) 6208-000-000 (System 6 Sagittal Saw)
- 6209-000-000 (System 6 Precision Saw)
- 6215-000-000 (System 6 Large Battery)
- 6212-000-000 (System 6 Small Battery)
- 6126-000-000 (System 6 Large Aseptic Kit)  
Includes: 6126-110-000 (Battery), 6126-120-000 (Housing), 6126-130-000 (Shield)
- 6127-000-000 (System 6 Small Aseptic Kit)  
Includes: 4222-110-000 (Battery), 6127-120-000 (Housing), 4222-130-000 (Shield)
- 6110-120-000 (System 6 Charger)
- 6203-133-000 (1/4" Keyless Chuck)
- 6203-134-000 (1/8" Keyless chuck)

Stryker values your continued partnership in delivering high quality patient care and encourages you to reach out to your local Stryker Account Sales Representative for replacement options.

Thank you,  
Aneasha Philip  
Sr. BU Director  
Stryker India Pvt Ltd



---

**ORTHO DRILL 0921312 # 108202 @ THQH OTTAPALAM**

5 messages

**Akhilesh P** <akhileshcyrix@gmail.com>

Fri, May 3, 2024 at 3:56 PM

To: sangeeth.vr@stryker.com

Cc: Sarang KM &lt;sarangcyrix@gmail.com&gt;, Blesson Jose &lt;Zm2.klbemp@cyrix.in&gt;

Dear sir

As per telephonic conversation , Stryker Drill system is send to below mentioned address. Please acknowledge when it's received.

Adress :

Innovative concepts  
35/1476A, Kripa,Kochaneth lane  
South Janatha road,Palarivattom  
Cochin-682 025  
Kerala  
Ph: 9495964201

Thanks &amp; Regards

AKHILESH P  
DISTRICT INCHARGE - PALAKKAD  
Bemp-Kerala  
Mobile : +91 7593847154  
Email : [akhileshcyrix@gmail.com](mailto:akhileshcyrix@gmail.com)

CYRIX HEALTHCARE (P) LTD  
30/641B, Petta, Punithura  
Ernakulam- 682038  
[www.cyrixhealthcare.com](http://www.cyrixhealthcare.com)

---

**VR, Sangeeth (Contractor)** <sangeeth.vr@stryker.com>

Fri, May 3, 2024 at 4:13 PM

To: Akhilesh P &lt;akhileshcyrix@gmail.com&gt;

Cc: Sarang KM &lt;sarangcyrix@gmail.com&gt;, Blesson Jose &lt;Zm2.klbemp@cyrix.in&gt;

Dear Akhilesh,

Greetings from Stryker Service.

We had received the unit at Kochi. We will dispatch the unit to Regional service centre Chennai at the earliest. We will provide the service estimate once the inspection is complete.

**Thanks & Regards,****Sangeeth V R****Sr. Service Engineer,****Kerala****M: 9048215494.****Mail ID : [sangeeth.vr@stryker.com](mailto:sangeeth.vr@stryker.com)****Toll free number: 18001038030****Service India mail ID: [service.india@stryker.com](mailto:service.india@stryker.com)**Visit us for a Service request: <https://bit.ly/3Eh1Xjd>

Use through Mobile scanner



---

**From:** Akhilesh P <akhileshcyrix@gmail.com>  
**Sent:** Friday, May 3, 2024 3:56:41 PM  
**To:** VR, Sangeeth (Contractor) <sangeeth.vr@stryker.com>  
**Cc:** Sarang KM <sarangcyrix@gmail.com>; Blesson Jose <Zm2.klbemp@cyrix.in>  
**Subject:** ORTHO DRILL 0921312 # 108202 @ THQH OTTAPALAM

You don't often get email from [akhileshcyrix@gmail.com](mailto:akhileshcyrix@gmail.com). [Learn why this is important](#)

**EXTERNAL EMAIL**

[Quoted text hidden]

**CAUTION:** External email. Do not click links or open attachments unless you recognize the sender and know the content is safe.  
Please forward all suspicious emails to [informationsecurity@stryker.com](mailto:informationsecurity@stryker.com).

Follow this link to read our [Privacy Statement](#)

---

**VR, Sangeeth (Contractor)** <sangeeth.vr@stryker.com>  
To: Akhilesh P <akhileshcyrix@gmail.com>  
Cc: Sarang KM <sarangcyrix@gmail.com>, Blesson Jose <Zm2.klbemp@cyrix.in>

Fri, May 10, 2024 at 6:29 PM

Dear Akhilesh,  
Greetings from Stryker Service.

System 6 Rotary is an obsolete model and we have only limited services available due to spare unavailability. End of service letter attached for your reference.

**Thanks & Regards,**

**Sangeeth V R**

**Sr. Service Engineer,**

**Kerala**

**M: 9048215494.**

**Mail ID :** [sangeeth.vr@stryker.com](mailto:sangeeth.vr@stryker.com)

**Toll free number: 18001038030**

**Service India mail ID:** [service.india@stryker.com](mailto:service.india@stryker.com)

Visit us for a Service request: <https://bit.ly/3Eh1Xjd>

Use through Mobile scanner



---

**From:** VR, Sangeeth (Contractor) <sangeeth.vr@stryker.com>  
**Sent:** Friday, May 3, 2024 4:13:52 PM  
**To:** Akhilesh P <akhileshcyrix@gmail.com>  
**Cc:** Sarang KM <sarangcyrix@gmail.com>; Blesson Jose <Zm2.klbemp@cyrix.in>  
**Subject:** Re: ORTHO DRILL 0921312 # 108202 @ THQH OTTAPALAM

[Quoted text hidden]

**2 attachments**



Image.jpeg  
18K


 **Customer Communication - System 6 V3.pdf**  
94K

# BATTERY OPERATED POWERDRILL FOR ARTHROSCOPY.


81

RSBY	BF from P.No. III / Q3	R	IN	Scale	M. Chgs. Chk.
30/1/18	Rd from store	1		2	RS 54420/-
	1. Battery operated Powerdrill SN/7236. SD/5099.	2		2	
	2. Charger S.No. 1734706983				RS 243750
	3 - Drill & Reamer hand piece S.No. 1622312063	1		1	RS 381250
	4. Sagittal saw hand piece S.No. 1815 208193	1		1	3,25,000
	5. Reamer attachment S.No. 18138	1		1	29250/-
	6. Quick connect attachment S.No. 18169	1		1	24750/-
	7. K wire collect-attachment S.No. 1634411393	1		1	15938/-
	8 1/2 Inch Jacobs drill attachment C Key S.No. 18170	1		1	27562/-
	Date of installation 24/8/2018				Total
	NEOPTIC Surgeries, Kochi				12,45,350
	Phone No. 0484 2344201				
	and to OT				



  
 1/6/2018  
 Superintendent  
 Head Quarters Hospital  
 Ottapalam





A.P.S.  
3/15/24.  
Superintendent  
Faluk Head Quarters Hospitz.  
Ottapalam





*Ananth*  
3/15/24  
Superintendent  
Taluk Head Quarters Hospital  
Ottapalam