


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	KOZHIKODE
2	Name of Hospital	THQH KUTTIADY
3	Name of Equipment with Make, Model and Serial Number	Equipment : NEBULIZER Make : BEURER Model : IH21 SN : 2018D15/013988
4	Equipment ID & Barcode	102478 & 1120643
5	Date of purchase / Year of manufacture /Installation Date	08- 05- 2019
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	21/03/2024(Toll free)
9	Action taken	Checked and found compressor motor with piston defective need to replace these spares for further checking working condition of the equipment.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Not recommending for repair
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	1353
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached
16	Reasons for recommending the equipment as BER	Checked and found compressor motor with piston defective need to replace these spares for further checking and working condition of the equipment. Equipment installed on 08/05/2019 aged up to 4years 11 months. Quotation not submitted since spares are not available in the market So we recommend the equipment for condemnation
17	Name & Signature of CYRIX Authority	ARUN KK 

\*Not mandatory

#Based on the period of life and value as per the BER guidelines


\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Checked and found that compressors with piston are damaged. Machine installed on 8/5/2019. So recommended for condemnation. Spares not available in the market.

Signature of BMZ/NHM  
National Health Mission  
Kozhikode

17/4/2024  
Date



Signature of  
Superintendent / Medical Officer

**SUPERINTENDENT  
TALUK HOSPITAL  
KUTTIADY-675208**





# STOCK BOOK OF \_\_\_\_\_

81

Name of article NEBULISER


Date	Invoice No.	From whom received or to whom issued	Receipt	Issued	Balance	Batch No Exp. Date Mfg. Date	Price per Unit/MFG	Remarks
		Brought Forward						from stock register vol: 11 page no: 145
15/6/20		Rel date - 7/7/14	1		9			
		12/2/18	-2		11			
		8/5/19	2		11			
		10/6/19	-2	9	11			
7/1/21		condemnation done under order no: C2/1443-A/2020 dated 7/1/2021		2	9			
5/10/22		Tr. in from New	2		11			
		[ <del>EP</del> stock book						
		[ LD stock book						
		Med page no: 183						
14/12/22		Rel from the above	3		14			
		[ from HDC - 7						
		page no: 184 ]						

*[Signature]*  
17/4/2024  
SUPERINTENDENT  
TALUK HOSPITAL  
KIATTIADY-673508







**CYRIX**  
**TOLL FREE NO. 1800 - 433-7668**  
 SAN CODE (1800-433-7668) 1120643  


**Beurer GmbH, Söllinger Str. 218,**  
**D-89077 Ulm, GERMANY**  
 Model: IH 21 Type: IH 21/1  
 Item No.: 601.12  
 230V~ / 50Hz / 1.0A / 230VA  
 30 min. ON / 30 min. OFF  
**EAC**  
**CE** 0483     
  **SH** 2018D15/013988

*Handwritten signature*  
 17/4/2024

**SUPERINTENDENT**  
**TALUK HOSPITAL**  
 KUITTYAN - 673508

