


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT  
MAINTENANCE PROGRAM (BEMP)**

**Recommendations for Beyond Economic Repair (BER)**

**PROFORMA**

<b>Sl. No</b>	<b>Particulars</b>	<b>Details</b>
1	Name of District	THRISSUR
2	Name of Hospital	GH THRISSUR
3	Name of Equipment with Make, Model and Serial Number	Nebulizer Make : Philips Model: Respirationics SN: 1022176151
4	Equipment ID/ Barcode	0810921 #109039
5	Date of purchase/ Year of manufacture/Installation Date	13-11-2020
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CAMC
8	Date of breakdown (Date of registration of complaint through email/ Toll free)	Toll free- 02-05-2024
9	Action taken	Checked the machine and found that Machine is not switching on, Found mainboard, motor and piston are defective. Need to replace these spares for further checking.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendations
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	1353 /-
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	NA
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Service report attached
16	Reasons for recommending the equipment as BER	Checked the machine and found that Machine is not switching on. Found mainboard, motor and piston are defective. Equipment installed on 13-11-20 aged up to 3 years 5 month. Quotation not submitted since spares are not available from the market. So we recommend the equipment for condemnation.
17	Name & Signature of CYRIX Authority	BIJO T JOY 

\*Not mandatory      #Based on the period of life and value as per the BER guidelines

\* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Nebuliser @ 1482 and spare cost is not cost effective


**Jr. Consultant (Biomedical)**  
**NHM, Thrissur**



Signature of JC BM (NHM)

Date:



  
Signature of  
Superintendent (Medical Officer/c)  
**SUPERINTENDENT (Dy. DHS)**  
**GENERAL HOSPITAL**  
THRISSUR - PIN: 680 001

# STOCK REGISTER

Name

Date	Received from or issued to	Inv. No. of Issue	Rate		Receipts	Issues	Balance	Remarks
			Ruppes	Ps				
	B- FROM EQUIPMENT BOOK Vol II PAGE 72				1-7-06 25/11/11 12/19/14 (sum) 12/9/14		3	
	(Condemned as per order no B5 2018/0111-702 Dated 4/9/2018 Rel from state about 2980- Page 20 Fuel water fuel 01 key no -70083:231					2	1	2
12/20	Rel from store				1	1027	3	9th
1/20	Entered in the Condemnation Policy Register					1	2	2nd
13/11/20	RFS DSC (482)				1		3	
12/1/21	Rd from the state (novation)				1		4	





# BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



**SERVICE PROVIDER**  
Tender No. WO-37/2021-2022/698

## CYRIX

HEALTHCARE PVT LTD

No. : 215171

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

### Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala  
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Health Facility <u>G.H. THRISSUR</u>	Call Registration Date : <u>2/05/2024</u>
Address <u>THRISSUR</u>	Caller ID : <u>109039</u>
<u>KERALA</u>	Date of Visit : <u>3/05/2024</u>
Ph : <u>9495055712</u>	Asset No. : <u>0810921</u>
	EQPT Name : <u>Nebuliser</u>
	Manufacture <u>philips</u> Model : <u>Respironics</u>
	S. No. <u>1022176151</u> Dept. <u>OP</u>

Service Classification : Breakdown Call  PMS  Calibration  Cust.Training

Problem Identified : Nebuliser is not working.

Action Taken : checked the machine and found that machine is not switching on found mainboard, motor and piston are defective. Need to replace these spares for further checking.

Completed  Date : 3/05/2024 Time : 11:30 am Spare Required

Spare Replaced  Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>ABSIL TONY</u>	<u>3/05/24</u>	<u>10:30am</u>	<u>11:30am</u>

Customer Remark



Completed

Pending

Service Engineer Name : ABSIL TONY

Signature :

Date : 3/05/2024

Contact Number : 9795328470

Customer Name : Tony

Signature :

Date : 03/5/24

Contact Number : 9495055712

Designation : SN

Hospital Seal :

Tony SUPERINTENDENT (Dy.DHS)

GENERAL HOSPITAL

THRISSUR - PIN: 682 038

