



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 192931

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

484

<p>Health Facility <u>General Hospital</u></p> <p>Address <u>Thiruvananthapuram</u></p> <p>Ph : <u>7012 896198</u></p>	<p>Call Registration Date : <u>01-04-2024</u></p> <p>Caller ID : <u>104082</u></p> <p>Date of Visit : <u>02-04-2024</u></p> <p>Asset No. : <u>0115816</u></p> <p>EQPT Name : <u>BP Apparatus</u></p> <p>Manufacture <u>Lifecare</u> Model : <u>bsx515</u></p> <p>S. No. <u>MA</u> Dept. <u>FSW</u></p>
------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Cutt not Inflating

Action Taken : Checked the machine and found air pump motor and control board damaged. Need to replace these spare to further check working condition of machine


Completed Date : 02-04-24 Time : 4:30pm Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.				
2.	NA	-	-	-
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>ADITHYA.J.J</u>	<u>02-04-24</u>	<u>3:30pm</u>	<u>4:00pm</u>

Customer Remark Completed Pending



<p>Service Engineer Name : <u>ADITHYA.J.J</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>02-04-2024</u></p> <p>Contact Number : <u>9745054344</u></p>	<p>Customer Name : <u>General Hospital Thiruvananthapuram</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>2/4/24</u></p> <p>Contact Number : <u>7012 896198</u></p> <p>Designation : <u>Superintendent</u></p> <p>Hospital Seal : <u>[Seal]</u></p>
-------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

489

PROFORMA

Sl. No	Particulars	Details
1	Name of District	THIRUVANANTHAPURAM
2	Name of Hospital	GH THIRUVANANTHAPURAM
3	Name of Equipment with Make, Model and Serial Number	Equipment : BP APPARATUS Make: LIFECARE Model :BSX 515 SN : NA
4	Equipment ID & Barcode	104082 & 0115816
5	Date of purchase / Year of manufacture /Installation Date	31.03.2021
6	Warranty details (Yes/No)	No warranty
7	*AMC/ CAMC Period agreed at the time of purchase	No AMC/CMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	01.04.2024 (Toll free)
9	Action taken	Checked the machine and found the motor and control board defective.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	Not recommending for repair.
12	Cost of spares (specify parts and cost)	NA

13	Asset Value	Rs. 1201.76
14	#Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	Na
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix service report attached
16	Reasons for recommending the equipment as BER	Checked and found that motor and control board are defective. Machine installed on 31.03.2021 and aged up to 3 years. Quotation not attached as spare not available in the market. Hence recommending the equipment for condemnation.
17	Name & Signature of CYRIX Authority	ADITHYA J S 


*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:


Control board defective. can be RBER.

MANEESHA MOHAN M.R.
Junior Consultant (Biomedical)
National Health Mission
Thiruvananthapuram


22-4-2024.
Signature of JC BM (NHM)


Date






Signature of 
Superintendent Medical Officer (i/c) Hospital

74 Digital BP Apparatus.

Date	Particulars	R/d	Issued	Balance	Remarks
22/11/19	R/d from store (True check)	1		1	
22/2/21	R/d from store [Eiko] (Exp Date 28/12/2030)	1	✓	2	By/HN
31/3/21	(L.P) Received from store Tris from local purchase Register page no: 26 (RS 1201-46)	1		3	Loss/INT
<u>Life span</u> Exp date <u>30/6/2030</u>	model Bx 575 Lot no S15CIBH19				
<u>Batch no</u>	BH 19 - model Bx Box code: 0115893 1) 0115816 3) 0110082 ii) 0110692 (extra)				
20/10/2021	Physically found BPL 120/80 B9			4	Loss/INT



Superintendent
General Hospital
Thiruvananthapuram



Superintendent
 General Hospital
 Thiruvananthapuram