



BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 194184

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

Service Report

<p>Health Facility : <u>THQH</u></p> <p>Address : <u>Thussavoor</u> <u>Alappuzha</u></p> <p>Ph : <u>8289877287</u></p>	<p>Call Registration Date : <u>21/4/2024</u></p> <p>Caller ID : <u>107409</u></p> <p>Date of Visit : <u>23/4/2024</u></p> <p>Asset No. : <u>0721300</u></p> <p>EQPT Name : <u>Suction Apparatus</u></p> <p>Manufacture <u>MEDEC</u> Model : <u>Standard</u></p> <p>S. No. <u>NA</u> Dept. <u>Casualty</u></p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Suction Apparatus is not getting on

Action Taken : checked the machine and found that suction motor is defective. Enquired the spare with the Vendor

Completed Date : 23/4/24 Time : 12:00PM Spare Required

Spare Replaced Requested

No.	Description	Qty.	Part Number	PR Number
1.				
2.				
3.				

Cyrix Engineer	Date	Start Time	End Time
<u>Nasut</u>	<u>23/4/24</u>	<u>10:00am</u>	<u>12:00pm</u>

Customer Remark : Not working

Completed Pending

<p>Service Engineer Name : <u>Nasut</u></p> <p>Signature : <u>Nasut</u></p> <p>Date : <u>23/4/24</u></p> <p>Contact Number : <u>9526744524</u></p>	<p>Customer Name : <u>B. Sankar V R</u></p> <p>Signature : <u>[Signature]</u></p> <p>Date : <u>23/4/24</u></p> <p>Contact Number : <u>9446452484</u></p> <p>Designation : <u>S.N.O</u></p> <p>Hospital Seal :</p>
--	---





BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 194191

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility : <u>THQH</u></p> <p>Address : <u>Thuravoor</u> <u>Alappuzha</u></p> <p>Ph : <u>8289877257</u></p>	<p>Call Registration Date : <u>21/4/2024</u></p> <p>Caller ID : <u>107409</u></p> <p>Date of Visit : <u>23/4/2024</u></p> <p>Asset No. : <u>0721300</u></p> <p>EQPT Name : <u>Suction Apparatus</u></p> <p>Manufacture : <u>MEDEC</u> Model : <u>Standard</u></p> <p>S. No. : <u>NA</u> Dept. : <u>Casualty</u></p>
---	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : Suction Apparatus is not getting on

Action Taken : checked the machine and found that suction motor is defective. Enquired the spare with the vendor

Completed Date : 6/5/24 Time : 12:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
<u>Nasuf</u>	<u>6/5/24</u>	<u>9:30am</u>	<u>12:00pm</u>

Customer Remark Completed Pending

Not working

Service Engineer Name : Nasuf
Signature : Nasuf
Date : 6/5/24
Contact Number : 9526744524

Customer Name : Shanab
Signature : Shanab
Date : 6/5/2024
Contact Number : Medical Officer in Charge
Designation : Taluk Hospital, Thuravoor
Hospital Seal : Alappuzha, Pin: 688532




**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA

Sl. No	Particulars	Details
1	Name of District	ALAPPUZHA
2	Name of Hospital	THQH THURAVOOR
3	Name of Equipment with Make, Model and Serial Number	SUCTION APPARATUS MAKE:- MEDEC MODEL :- STANDARD SN :- NA
4	Equipment ID & Barcode	107409 & 0421300
5	Date of purchase / Year of manufacture /Installation Date	08/03/2018
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	21/04/2024
9	Action taken	Checked the machine and found that Suction motor is defective. Enquired the spare with the vendor.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully Damaged
11	Recommendations for repair (required service details)	Not Recommending For Repair
12	Cost of spares (specify parts and cost)	Suction Motor – 4200/-


13	Asset Value	RS :- 5800/-
14	*Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	RS:- 72%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	Cyrix Service Report And Vendor Quotation Attached.
16	Reasons for recommending the equipment as BER	Checked and Found that Suction Motor is Defective. Equipment was installed on 08/03/2018 and aged up to 6 Years. Spare cost of the equipment is 72%, both criteria met, so we are recommending the equipment for condemnation as per the tender clause 5.3.14.1.
17	Name & Signature of CYRIX Authority	NASEEF K 

*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph


Remarks and Recommendations of Junior Consultant (Biomedical) NHM:

Recommended for BER


 JYOTHISH THOMAS
 Consultant
 Signature of JC BM (NHM)
 NHM ALAPPUZHA

Date




 6/5/2024
 Signature of
 Superintendent/ Medical Officer (i/c)
 Taluk Hospital, Thiruvavoor
 Alappuzha - P



Stawath

Medical Officer in Charge
Taluk Hospital, Thuravoor
Alappuzha- Pin: 688532



9744473043, 9744473243

cloud99biotech@gmail.com

1 KM/700-1333
Room No: 22,
CSI Golden Jubilee Complex
Baker Hill
Shastri Road
Kottayam

CLOUD99 BIOTECH

GSTIN: 32AMWPT5633Q1Z0
State: 32 - Kerala

MSME No: UDYAM-KL-07-0030714

Estimate

Estimate For:

ABHILASH A

CYRIX HEALTHCARE PRIVATE LIMITED
1 ST FLOOR: 30/641B
KOCHI DHANUSHKODI ROAD, POONETHURA
ERNAKULAM 682038

Contact No.: 9157068590

GSTIN Number: 32AAFC2489H22M

State: 32-Kerala

Estimate No.: C99B-QTN-9

Date: 05/05/2024

Place of Supply: 32-Kerala

#	Item name	HSN/ SAC	Quantity	Price/ UNIT	GST	Amount
1	SUCTION MOTOR (MOTOR FOR HOSPITAL SUCTION)	9018	1	₹ 3,559.32	₹ 640.68 (18%)	₹ 4,200.00
Total			1		₹ 640.68	₹ 4,200.00



Pay To:

Bank Name : UNION BANK OF INDIA, KOTTAYAM

Bank Account No. : 361201010035646

Bank IFSC code : UBIN0556121

Account holder's name : CLOUD99 BIOTECH

Sub Total	₹ 3,559.32
SGST@9%	₹ 320.94
CGST@9%	₹ 320.94
Total	₹ 4,200.00

Description

THQH Thuravoor
Alappuzha
Ticket No :- 107409
Barcode 0421300

Suction Apparatus
Model :- Medec

Estimate Amount In Words

Four Thousand Two Hundred Rupees only

Terms And Conditions

Thanks for doing business with us!

For: CLOUD99 BIOTECH



Authorized Signatory



Shrawan

Medical Officer in Charge
Taluk Hospital, Thuravoor
Alappuzha- Pin: 688532