


**REPAIR OF BIOMEDICAL EQUIPMENTS UNDER BIOMEDICAL EQUIPMENT
MAINTENANCE PROGRAM (BEMP)**

Recommendations for Beyond Economic Repair (BER)

PROFORMA


Sl. No	Particulars	Details
1	Name of District	KASARGOD
2	Name of Hospital	PHC NARKILAKKAD
3	Name of Equipment with Make, Model and Serial Number	Name:- BP apparatus Make:- BIO PLUS Model:-N/A SN:- N/A
4	Equipment ID & Barcode	100909 / 1440108
5	Date of purchase / Year of manufacture /Installation Date	27-05-2015
6	Warranty details (Yes/No)	NO WARRANTY
7	*AMC/ CAMC Period agreed at the time of purchase	NO AMC/CAMC
8	Date of breakdown(Date of registration of complaint through email/ Toll free)	13-03-2024 (Toll free)
9	Action taken	Checked the machine and found that glass tube broken, mercury spilled. Enquired for quotation.
10	Present status of the equipment (Fully damaged / partially damaged)	Fully damaged
11	Recommendations for repair (required service details)	No recommendation.
12	Cost of spares (specify parts and cost)	Mercury 5ml- 1652 Glass tube – 112 Total: ₹ 1764



13	Asset Value	1323
14	# Percentage value of the cost of spares with respect to Cost of Purchase/ Asset Value	133%
15	Abstract of Service Report provided by the OEM/ Authorized Service Provider/ CYRIX (Attached or Not)	CYRIX SERVICE REPORT AND QUOTATION ATTACHED.
16	Reasons for recommending the equipment as BER	Checked the machine and found that Mercury spilled and glass tube broken. Machine installed on 27/5/2015 and aged up to 8 years and 9 months. The spare cost of the equipment surpasses its original asset value of rupees 1323, meeting both criteria for condemnation. Therefore, it is recommended to condemn the equipment as per tender clause 5.3.14.1.
17	Name & Signature of CYRIX Authority	ABHINAV O 


*Not mandatory #Based on the period of life and value as per the BER guidelines

* Attach Photograph

Remarks and Recommendations of Junior Consultant (Biomedical) NHM:
 Checked the machine and found that mercury leakage & mercury column broken. BP Apparatus installed on 27/5/2015. Quotation for mercury column & mercury attached. Recommending the equipment for BER.


 Signature of JC BM (NHM) Jr. CONSULTANT
 Biomedical Engineering
 Arogyakeralam (NHM)
 Kasaragod at Kanhangad


 Date 03/04/24
 Seal
 Signature of
 Superintendent / Medical Officer (i/c)






BIOMEDICAL EQUIPMENT MAINTENANCE PROGRAMME UNDER NATIONAL HEALTH MISSION



SERVICE PROVIDER
Tender No. WO-37/2021-2022/698

CYRIX

HEALTHCARE PVT LTD

No. : 185983

ISO 13485 : 2012 & ISO 9001-2008 CERTIFIED COMPANY | AERB Approved Service Agency

Service Report

30/64 1 B, Petta Junction, Poonithura, Kochi - 682 038, Kerala
Ph : 98472 99500 Website : www.cyrix.com | E-mail : bemp.kl@cyrix.in

<p>Health Facility FHC Narkilakkad</p> <p>Address Narkilakkad Kasaragod</p> <p>Ph : 9496493572</p>	<p>Call Registration Date : 13/03/2024</p> <p>Caller ID : 100909</p> <p>Date of Visit : 14/03/24</p> <p>Asset No. : 1440108</p> <p>EQPT Name : BP apparatus</p> <p>Manufacture Bioplus Model : NA</p> <p>S. No. NA Dept. OP</p>
--	---

Service Classification : Breakdown Call PMS Calibration Cust.Training

Problem Identified : mercury leakage

Action Taken : checked the machine and found that glass tube broken, mercury spilled. Need to replace these spare for further checking of equipment.

Completed Date : 14/03/24 Time : 12:00pm Spare Required

Spare Replaced Requested

Description	Qty.	Part Number	PR Number
1.			
2.			
3.			

Cyrix Engineer	Date	Start Time	End Time
Vishnu P	14/03/24	11:00AM	12:00PM

Customer Remark Completed Pending

<p>Service Engineer Name : Vishnu P</p> <p>Signature : </p> <p>Date : 14/03/24</p> <p>Contact Number : 9072011476</p>	<p>Customer Name : Vidy V</p> <p>Signature : </p> <p>Date : 14/03/24</p> <p>Contact Number : 9496493572</p> <p>Designation : Nursing officer on E</p> <p>Hospital Seal :</p>
---	--

Quotation

1 message

Medade healthcare <sales.medade@gmail.com>
To: Sarang KM <sarangcyrix@gmail.com>

Wed, Jun 12, 2024 at 10:31 PM


Dear Mr. Sarang,



Please find the attached quotation for repairing the BP apparatus.

Anticipating for your favorable response.

Thanks and regards,

MEDADE HEALTHCARE
KM 32/1475 A4 Ground, Saaff Arcade,
New Bus Stand Link Road Koyilandy,
Koyilandy - 673305,
Kozhikode, Kerala
Tel: +9181 2910 2919
+9170 1211 2424

 **MHQTN23240126 Cyrix BP Apparatus.pdf**
642K



Chaitan

સર્વ સ્વાસ્થ્ય
સાગ્ય, મહેતુભાવ

